



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info	
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897	Cust No/Name	KCV17595/Mr Mandapati Venkata Satya Kira
TEL:67143369	Reg No/Reg Date	SLP6932U*# / 15/06/2017
Contact No	Date In/Mileage	19/01/2022/ 64434
	Chassis No	JMYXTGF3WHZ002287
	Engine No	4B12TC3024
	Make/Model	MIT/OUTLANDER 2.4 CVT AWD (F58)
	Colour/Trim	DO1 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No				
F0000051	Credit	28/01/2022/ 09:24	OD	303 / Renemer	25532				
Description of Goods / Services						Qty	Unit Price	Disc%	Amount
S	MIPNT88088	DIAGNOSTIC/SCANNING				200			250.00
S	MIPNT88088	TO CHECK ALL LIGHTING/WIRING SYSTEM ON LHR ACCIDENT AFFECTED AREAS				80			100.00
S	MIPNT88088	TO REPLACE TAILGATE GLASS AND MOULDINGS				240			300.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW TAILGATE GLASS				80			100.00
S	MIPNT88088	TO INSTALL RIKECOOL SOLAR FILM ON NEW TAILGATE GLASS & LH QTR GLASS				100			370.00
S	MIPNT88088	TO TRANSFER TAILGATE COMPONENTS & MECHANISM PARTS				320			640.00
S	MIPNT88088	TO REMOVE & RE-INSTALL ALL CARPETS/TRIMMING/ROOF LINING TO FACILITATE REPAIR ON LHR ACCIDENT AFFECTED AREAS				640			640.00
S	MIPNT88088	TO APPLY SEALANT KIT ON NEW & REPAIR BODY PANELS				160			300.00
S	MIPNT88088	TO REMOVE & RE-INSTALL FUEL TANK TO GIVE WAY ACCESS REPAIR ON LHR ACCIDENT AFFECTED AREAS				320			640.00
S	MIPNT88088	TO REPLACE LOGO, TAILLAMPS, TAILGATE, GARNISH, MLDGS, CLIPS, BRACKETS, REAR BUMPER, LH QTR GLASS, WIRING HARNESS, ETC -TO CUT & WELD LH QTR PANEL, LH UPR & LWR EXTENSION PANEL, RR END PANEL STRAIGHTEN, REFORM, ALIGN ON LHR ACCIDENT AFFECTED AREAS				640	44.5	28%	5120.00
S	MIPNT98088	SPRAY PAINTING ON LHR ACCIDENT AFFECTED AREAS (TAILGATE, REAR BUMPER, LH QTR PNL, UPR & LWR EXTENSION PNL, RR END PANEL)				2200			3200.00
S	MIPNT88088	REVERSE SENSOR (ITEMS & INSTALLATION INCLUDED)							280.00
M	SUNDRY	C & C LOGO							50.00
M	JJ5805A758	GLASS, TAILGATE WINDO				1.00	551.00	0.00	551.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 TEL:67143369 Contact No	Cust No/Name KCV17595/Mr Mandapati Venkata Satya Kira Reg No/Reg Date SLP6932U*# / 15/06/2017 Date In/Mileage 19/01/2022/ 64434 Chassis No JMYXTGF3WHZ002287 Engine No 4B12TC3024 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F58) Colour/Trim D01 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
F0000051	Credit	28/01/2022/ 09:24	0D	303 / Renemer	25532		
Description of Goods / Services							
				Qty	Unit Price	Disc%	Amount
M JJ5805A316		UPR DAM, TAILGATE	nee	1.00	13.00	0.00	13.00
M JJ5805A315		SIDE DAM, TAILGATE	nee	2.00	27.00	0.00	54.00
M JJ5805A317		LWR DAM, TAIL GATE	nee	1.00	24.00	0.00	24.00
M JJMB814447		FASTENER, WINDSHIELD	nee	4.00	6.00	0.00	24.00
M JJMR462285		STOPPER, WINDSHIELD G	nee	2.00	3.00	0.00	6.00
M JJ5801B673		PANEL ASSY, TAILGATE	nee/Buc	1.00	989.00	0.00	989.00
M JJ7415A015		MARK, THREE-DIA	nee	1.00	61.00	0.00	61.00
M JJ5817A265BA		GARNISH, TAILGATE	nee	1.00	496.00	0.00	496.00
M JJ7415A401		MARK, OUTLANDER	nee	1.00	95.00	0.00	95.00
M JJ8330B173		LH OTR RR LAMP ASSY,	nee	1.00	603.00	0.00	603.00
M JJ8331A179		LH INR LAMP ASSY, TAILGATE	nee	1.00	506.00	0.00	506.00
M JJ5802A779		LH GAS SPRING, TAILGATE	nee	1.00	194.00	0.00	194.00
M JJ5802A780		RH GAS SPRING, TAILGATE	nee	1.00	194.00	0.00	194.00
M JJ5808A119		LATCH, TAILGATE	nee	1.00	222.00	0.00	222.00
M JJ5815A067		W/STRIP, TAILGATE OPE	nee	1.00	213.00	0.00	213.00
M JJ6121A495		LH GLASS, QTR WINDOW	nee	1.00	339.00	0.00	339.00
M JJ5301G843		LH PANEL, QTR, OTR	nee	1.00	1298.00	0.00	1298.00
M JJ5301F623		LH UPR OTR, EXTENSION	nee	1.00	276.00	0.00	276.00
M JJ5301H593		LH LWR OTR, EXTENSION	nee	1.00	78.00	0.00	78.00
M JJ7407A303		LH MLDG, RR WHEEL ARC	nee	1.00	199.00	0.00	199.00
M JJ7835A060		DUCT, RR VENTILATOR	nee	1.00	39.00	0.00	39.00
M JJ6410F374		FACE, RR BUMPER	nee	1.00	811.00	0.00	811.00
M JJMR200300		CLIP, BUMPER	nee	10.00	4.00	0.00	40.00
M JJ6410D336		LH SIDE BRACKET, RR B	nee	1.00	19.00	0.00	19.00
M JJ6410D337		RH SIDE BRACKET, RR B	nee	1.00	19.00	0.00	19.00
M JJ6415A061		EXTENSION, RR BUMPER	nee	1.00	232.00	0.00	232.00
M JJ8336A153		LH REFLECTOR, TAIL LA	nee	1.00	100.00	0.00	100.00
M JJ7407A317		LH MOULDING, RR BUMPE	nee	1.00	106.00	0.00	106.00
M JJ5370C005		LH RR SHIELD, WHEEL S	nee	1.00	128.00	0.00	128.00
M JJ5370B015		LH RR SHIELD, WHEEL S	nee	1.00	19.00	0.00	19.00
M JJMB253964		CLIP, SPLASH SHIELD	nee	6.00	4.00	0.00	24.00
M JJMR328954		CLIP, SPLASH SHIELD	nee	2.00	4.00	0.00	8.00
M JJ5257A973		LH INR, RR END PANEL	nee	1.00	146.00	0.00	146.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE-FULCO MOTOR DEALER PTE LTD
EUNOS LINK SERVICE CENTRE

330 Ubi Road 3 Singapore 408650 Tel: 67461000 Fax: 64875857



ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897 TEL:67143369 Contact No	Cust No/Name KCV17595/Mr Mandapati Venkata Satya Kira Reg No/Reg Date SLP6932U*# / 15/06/2017 Date In/Mileage 19/01/2022/ 64434 Chassis No JMYXTGF3WHZ002287 Engine No 4B12TC3024 Make/Model MIT/OUTLANDER 2.4 CVT AWD (F58) Colour/Trim DO1 / BK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
F0000051	Credit	28/01/2022/ 09:24	OD	303 / Renemer	25532	
Description of Goods / Services						
			Qty	Unit Price	Disc%	Amount
M	JJ5257A967	PANEL,RR END	1.00	326.00	0.00	326.00
M	JJ6410B895	LH REINFORCEMENT,RR	1.00	79.00	0.00	79.00
M	JJ8518B070	HARNES,RR BUMPER	1.00	82.00	0.00	82.00
M	JJ8510J305	HARNES,RR END	1.00	90.00	0.00	90.00
M	JJ8637A176	BUZZER,KEYLESS OPERA	1.00	91.00	0.00	91.00
M	JJ8637B115	ANTENNA,KEYLESS OPER	1.00	96.00	0.00	96.00
Z	NOTES					
ACCIDENT ON 19/01/2022 ALONG PAYA LEBAR TOWARDS KPE BEF BUS STOP						
OWNER CLAIMING OWN POLICY						
EXCESS AND AUTHORIZATION WILL BE ADVISE BY THE INSURANCE COMPANY						
<h1>Estimate</h1>						
<p><i>not Authorized</i> <i>take</i> <i>me'ing</i> <i>28/1/22</i> <i>7/1/22</i> <i>Excess?</i> <i>10 days.</i> <i>Tel: 62883561</i></p>						
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>						7820

Confirm & accepted by	Parts	8,890.00
	Labour	0.00
	Standard Menu	0.00
	Specialist Job	11,940.00
	Others(Lub,etc)	0.00
	Sundry	50.00
	Total(w/o GST)	20,880.00
Authorized signatory and company stamp		

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.