

Vehicle Number : GBF9630S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>List Items</u>				
1 pc	Front corner panel	Cracked / deformed	\$ 375.00	\$ 375.00 ✓
1 pc	Front headlamp assy	deformed	\$ 650.00	\$ 650.00 ✓
1 pc	Front signal lamp	Cracked / deformed	\$ 275.00	\$ 275.00 208
1 pc	Front bumper assy	Warped / deformed	\$ 650.00	\$ 650.00 ✓
1 pc	Front bumper side garnish	Warped / deformed	\$ 220.00	\$ 220.00 170
1 pc	Front Grille xnn	distorted	\$ 340.00	\$ 340.00 x
4 pcs	Front Grille Clips xnn	necessary	\$ 40.00	\$ 40.00 x
	2053			
	25%			
	<u>1539.75</u>			
	List Parts Sub-Total		\$ 2,550.00	\$ 2,550.00
	Less 10% discount		\$ 255.00	\$ 255.00
	Discounted sub-total		\$ 2,295.00	\$ 2,295.00

Vehicle Number : GBF9630S

SPARE PARTS

QTY	PARTS DESCRIPTION	CONDITION	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
<u>Special Nett Items</u>				
1 pc	Number plate xnn	necessary	\$ 65.00	\$ 65.00 x
1 pc	Side mirror with round mirror assy	broken	\$ 450.00	\$ 450.00 300
	Special Nett Sub-Total		\$ 515.00	\$ 515.00
	Spare Parts Total		\$ 2,810.00	\$ 2,810.00
				<u>300</u>

LABOUR COST

S/No	JOB DESCRIPTIONS	Workshop Estimation (S\$)	Our Revised Estimation (S\$)
------	------------------	---------------------------	------------------------------

	Spare Parts	Total c/f	\$	2,810.00	\$	2,810.00
1	To renew damaged parts, straighten and repair front chassis member, front fender, front door and aligned all parts.	\$	1,600.00	\$	400	1,400.00
2	To check wiring functions & conduct water leakage test.	\$	180.00	\$	30	150.00
3	To putty, apply primer & spray-paint the affected areas.	\$	1,400.00	\$	300	1,200.00
4	To apply rust-proofing on repaired/replaced panels.	\$	180.00	\$	40	150.00

Total \$ 6,170.00 \$ 5,710.00

The repairer has agreed to undertake the repair under a Lump Sum Basis. We have further adjusted the amount to a Lump Sum Repair of :

\$ 4,550.00

770

1539.75

300.00


770.00

2609.75

20%

2087.80

L/S-\$2,100/4 DAYS


Fong Kok Heng
Qualified Appraiser

