

TNECNIV SERVICES

Blk 495-E Tampines Street 43, #04-368 Singapore 524495 Tel: 97859520

Reg.No. : 53436440C Insurance Loss Adjuster Licensed Appraiser

(Member Of Singapore Automobile Appraisers Association)

AUTOMOBILE INSPECTION REPORT

m/s	Goodyear Services	Date :	14/12/2021
	210 Turf Club Road Lot C11 Turf City Auto Emporium	Our Ref :	TP/2021/00612
	Singapore 287995.	Claim No :	-
		Policy No :	-

Date of Accident :	29/11/2021	Date of Inspection :	6/12/2021
Survey Held At :	Precise Auto Service	As Requested By :	Miss Arin
	1 Kaki Bukit Ave 6, #02-34 AutoBay	On :	6/12/2021
	Singapore 417883.		

PARTICULARS OF VEHICLE

Reg No :	SMN3174J	Make/Model :	Toyota Sienta	Year :	31/7/2019
Engine No :	2NRX475512	Chassis No :	MHFZ28H3000064381	Colour :	M. Grey
Mileage :	209871 Km	Engine Cap :	1496 cc	Seat Belt :	Yes
Aircon :	Yes	Radio/Cassette :	Yes	Rims :	Alloy

VEHICLE CONDITION (Static Test Only)

Brakes :	Serviceable	Handbrakes :	Serviceable	Steering :	Serviceable
General Body Works :	Good				

TYRE CONDITIONS

Front O/S :	8	Rear O/S :	8	Make :	Rapid
Front N/S :	8	Rear N/S :	8	Size :	185\60R15

(Remaining Estimated Life Of Tyre in num)

GENERAL DESCRIPTION OF DAMAGES

The vehicle sustained an impact on its rear o/s portion resulting in the rear end panel inner and outer dented/push-in; exhaust muffler bent/push-in; tailgate, chassis, o/s taillamp panel, o/s rear fender bent/dented; rear bumper, rear bumper o/s garnish bent and cut; o/s taillamp, o/s reflector, o/s fender air vent cracked. (see attached schedule for other damages)

ADJUSTMENT AND RECOMMENDATION COST OF REPAIR

Repairer's Estimate :	\$11,199.29	
Revised Amount :	\$9,235.34	
Less Excess :	N.A	
Nett Total :	\$7,350.00	(Lump Sum)
Estimated Period Required For Repair :	<u>Six</u>	Days

Survey was conducted in accordance to your instructions. We have / have not authorised repairs.
29 photos were taken at the time of inspection and attached.

Remarks : **The Survey was conducted strictly without prejudice.**

TNECNIV SERVICES

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No : SMN3174J

QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST (\$)	OUR REVISED (\$)
	TO SUPPLY			
1 pc	rear bumper	bent/cut	1,086.25	1,086.25
1 pc	rear bumper o/s reflector	cracked	571.25	172.75
1 pc	rear bumper centre pad	dented/cut	289.90	289.90
1 pc	rear bumper o/s pad	bent/cut	274.45	274.45
10 pcs	rear bumper clip	necessary	129.00	129.00
1 pc	rear bumper o/s side retainer	bent	172.45	172.45
1 pc	rear bumper o/s side attachment	bent	181.90	181.90
2 pcs	rear bumper clip	repeat item	25.80	-
1 pc	tailgate	bent/dented	1,086.25	1,086.25
1 pc	tailgate logo	necessary	171.10	171.10
1 pc	tailgate "G" emblem	necessary	61.00	16.00
1 pc	tailgate "Sienta" emblem	necessary	61.00	61.00
1 pc	tailgate weatherstrip	cut	381.90	381.90
2 pcs	rear w/screen glass moulding	necessary	343.60	343.60
14 pcs	rear w/screen glass clip	necessary	180.60	180.60
1 pc	rear w/screen glass inner seal	necessary	50.00	50.00
1 pc	o/s rear fender	bent/dented	757.10	757.10
1 pc	o/s rear quarter glass inner seal	necessary	50.00	50.00
1 pc	o/s rear fender air vent	cracked	182.25	182.25
8 pcs	o/s rear quarter glass clip	necessary	103.20	103.20
1 pc	o/s taillamp	cracked	350.25	350.25
1 pc	o/s taillamp sealant	necessary	50.00	50.00
2 pcs	o/s taillamp clip	necessary	25.80	25.80
1 pc	o/s taillamp panel	bent	581.90	581.90
2 pcs	rear exhaust muffler	bent	981.40	981.40
2 pcs	rear exhaust muffler hook	serviceable	127.80	-
1 pc	rear end panel outer	dented/push-in	581.40	581.40
1 pc	rear end panel inner	dented (repair)	781.50	-
			9,639.05	8,260.45
	Less 25%		2,409.76	2,065.11
			7,229.29	6,195.34
	TO SUPPLY (Special item)			
2 pcs	rear and o/s quarter glass sealant	necessary	120.00	120.00
	Total Spare Parts		7,349.29	6,315.34
	LABOUR CHARGE			
	Towing		80.00	80.00


TNECNIV SERVICES

ADJUSTMENT ON REPAIR COST AND REPLACEMENT OF PARTS

Veh.No : **SMN3174J**

QTY	DESCRIPTION OF PARTS AND LABOUR	CONDITION	REPAIRER EST (\$)	OUR REVISED (\$)
	To dismantle and refix boot compartment trimming and other fitting to facilitate repairs.		180.00	100.00
	To dismantle and transfer tailgate serviceable parts to new gate.		250.00	100.00
	To check wiring and clear fault code.		180.00	150.00
	To tuff coat after on affected areas.		180.00	150.00
	To remove and refix o/s rear quarter glass and transfer rear w/screen glass.		380.00	240.00
	To apply primer, putty and paint rear bumper, o/s rear fender, o/s taillamp panel, rear end panel inner and outer, tailgate and other affected areas.		1,200.00	1000.00
	To dismantle damaged parts, jack out, straighten and knock out dents on rear end panel inner, chassis member. cut and weld rear end panel outer, o/s taillamp panel, o/s rear fender and renew recommended parts.		1,400.00	1100.00
	Total Labour Charge		3,850.00	2920.00
	GRAND TOTAL		11,199.29	9,235.34
Note :	<p>The repairer had agreed to undertake the repairs on Lump Sum basis of \$7,350.00 nett to reinstate this vehicle to its pre-accident condition.</p> <p>(repairer discretion to repair parts, to replace with Second hand parts, or to replace with OEM or Genuine parts)</p> <p>.....</p>			
		End of Reports

TNECNIV SERVICES



Vincent Ng Seow Gim

20594.22

PRECISE AUTO SERVICE

NO 1 KAKI BUKIT AVE 6 #02-33/34/36 AUTOBAY SINGAPORE 417883

TEL : 6745 7367 FAX : 6841 3390

CO. REG. NO. : 35766600C GST REG. NO. : 35766600C

=====

Accident Date : 29-11-2021

OUR REF : SMN 3174J/T/21

Goodyear Services

210 Turf Club Road

C8 The Grandstand

Singapore 287995

TAX INVOICE

Invoice No. : TP2112-011

DATE : 31-12-21

FINAL BILL ON VEH. NO. : SMN 3174J

VEHICLE MODEL : TOYOTA SIENTA

LUMP SUM REPAIR

INCLUDING SUPPLY OF PARTS & LABOUR

PANEL BEATING & SPRAY PAINTING

7,350.00

SUB-TOTAL : 7,350.00

ADD GST 7% : 514.50

TOTAL AMOUNT SGD : 7,864.50

This is a computer generated document and requires no signature.

GOODYEAR SERVICES

210 TURF CLUB ROAD LOT C11,
TURF CITY AUTO EMPORIUM, SINGAPORE 287995
TEL: 6466 9792 FAX: 6466 5776
(ROC No. 53319102E)

VEHICLE HIRING AGREEMENT

THIS AGREEMENT is made on 06/08/2019 between Goodyear Services ("the Owner") and
MUHAMAD SHAARI BIN KAMAL ("the Hirer")
of S1801927B (NRIC/Passport No.) BLK 429 JURONG WEST AVENUE 1
#04-326 (S) 640429 (Address) 84411233 (Contact No.)
with a valid license no. S1801927B of class 3 and of the other part.

WHEREBY IT IS AGREED that the Owner lets to the Hirer the motor vehicle ("the vehicle") for the period ("the Period of Hire") at the rate of hire rental ("the Rental") as specified in the schedule ("the Schedule") upon the terms and conditions stated hereunder.

THE SCHEDULE 1 TO THIS AGREEMENT

DESCRIPTION OF VEHICLE:

Registration Vehicle No.: SMN3174J Make/Model: TOYOTA SIENNA STANDARD
Chassis No.: MHFZ28H3000064381 Engine No.: 2NRX475512

PERIOD OF HIRE:

Commencing date (Delivery of Vehicle) : 06/08/2019 time 1:00 P.M.

Vehicle was returned on : _____ time _____

✓ Every 3 weeks / months with renewal terms.

✓ Period of hire expires on: 06/11/2019



WEEKLY / MONTHLY RENTAL: _____ DEPOSIT: _____

TERMS OF PAYMENTS : Weekly / Monthly

INTEREST ON OVERDUE PAYMENTS : 10% per week

ACCIDENT CLAIM EXCESS : (In Singapore) Section 1: \$2,000.00 and Section 2: \$1,500.00 + 7% GST
: (In Malaysia) Double amount of Section 1 and Section 2 + 7% GST

WINDSCREEN CLAIM EXCESS : \$100 + 7% GST

AUTHORISED DRIVER : _____

OWNER'S BANK DETAILS : DBS CURRENT AC.
0059045724

OWNER	HIRER
(Please Initial)	