

(08/11/13) wef

ASS. REC. BY: Ryan

REF:

CS/4A122000996/R1#3

369K

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SHB 5743B

at Workshop m/s

STRIPS

of

60, WOODLARKS LN PK E4

Insured:

GAI

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Date / Time

Action / Instruction

Veh No:

SHB 5743B

Yr Regn:

2011 / OCT

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

TOYOTA PRIUS HYBRID 1.8CVT c.c 1798

Colour

MAROON

A/C: Insured / Std / NI / NA

Sp. Reading

443762

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JTDKB3FU103573048

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

SAILUN

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

27/01/22

D.O.I.

28/01/22

Survey held at

STRIPS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee:

Date/Time, File Return to?

Transportation:

2)

Add Fee:

☐

: Site Insp (\$

); S + RS, SI

☐

: Interview (\$

); Photos

☐

: Tech. Invs (\$

); Others

Report Format :

Case Details

Case Reference Number : TAX/01/22/2064
Type of Repair : Accident Repair
Vehicle Registration Number : SHB5743B

Company Type : Strides Taxi Pte Ltd
Estimation ID : EST-17352-ID
Assigned By : Taxi Claims Manager Team

Insurance Company Name : Great American Insurance Company
Accident Date and Time : 27/01/2022 03:30 AM
Vehicle Age(In Months) : -

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			COVER, RR BUMPER ASSY	1	423.90	423.90	25.00	317.92	Replace	1	317.92	Replace	de /
Standard	Main			REAR BUMPER REINFORCEMENT	1	318.80	318.80	25.00	239.10	Replace	1	239.10	Replace	sf /
Standard	Main			PAD, RR BUMPER, RH & LH, 1	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	ne /
Standard	Main			PAD, RR BUMPER, RH & LH, 2	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	ne /
Standard	Main			PAD, RR BUMPER, RH & LH, 3	2	3.80	7.60	25.00	5.70	Replace	2	5.70	Replace	ne /
Standard	Main			PAD, RR BUMPER, CTR	3	2.20	6.60	25.00	4.95	Replace	3	4.95	Replace	ne /
Standard	Main			SEAL, RR BUMPER ARM, RH & LH	2	11.00	22.00	25.00	16.50	Replace	2	16.50	Replace	ne /
Standard	Main			STOPPER, RR BUMPER, RH & LH	2	4.30	8.60	25.00	6.45	Replace	0	0	Not Give	kan
Standard	Main			RETAINER, RR BUMPER, RH	1	112.70	112.70	25.00	84.53	Replace	0	0	Not Give	kan
Standard	Main			RETAINER, RR BUMPER, LH	1	111.50	111.50	25.00	83.63	Replace	0	0	Check	?
Standard	Main			SEAL, RR BUMPER, RH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	kan
Standard	Main			SEAL, RR BUMPER, LH	1	85.20	85.20	25.00	63.90	Replace	0	0	Not Give	kan
Standard	Main			CLIPS PIECE, FRT & RR BUMPER	10	1.50	15.00	25.00	11.25	Replace	10	11.25	Replace	ne /
Standard	Main			GUARD, RR BUMPER, LOWER	1	558.30	558.30	25.00	418.72	Replace	1	418.72	Replace	de /

Total Spare Part Cost 15,239.64

Surveyor Total 6,357.78

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 11,984.89

Final Sur Total 5,086.22

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			FILLER, RR BUMPER , RH	1	119.90	119.90	25.00	89.93	Replace	0	0	Not Give	Xan
Standard	Main			FILLER, RR BUMPER , LH	1	119.90	119.90	25.00	89.93	Replace	0	0	Check	?
Standard	Main			COVER, GUARD RR BUMPER LOWER	1	14.80	14.80	25.00	11.10	Replace	0	0	Check	?
Standard	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	1	180.00	Replace	nw✓
Standard	Main			ANTENNA, ELECTRICAL KEY	1	60.30	60.30	10.00	54.27	Replace	0	0	Check	?
Standard	Main			REAR BUMPER GROMMET SCREW	2	2.20	4.40	25.00	3.30	Replace	0	0	Not Give	Xan
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , RH	1	438.10	438.10	10.00	394.29	Replace	0	0	Check	?
Standard	Main			LENS & BODY, REAR COMBINATION LAMP , LH	1	438.10	438.10	10.00	394.29	Replace	1	394.29	Replace	ca✓
Standard	Main			LENS & BODY ASSY , RR BUMPER , RH	1	486.80	486.80	10.00	438.12	Replace	0	0	Check	?
Standard	Main			LENS & BODY ASSY , RR BUMPER , LH	1	486.80	486.80	10.00	438.12	Replace	1	438.12	Replace	ca✓
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	54.00	54.00	25.00	40.50	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	54.00	54.00	25.00	40.50	Replace	0	0	Check	?
Standard	Main			COVER, REAR FLOOR UNDER , RH	1	169.50	169.50	25.00	127.13	Replace	0	0	Not Give	Xan
Standard	Main			COVER, REAR FLOOR UNDER , LH	1	234.30	234.30	25.00	175.73	Replace	0	0	Check	?
Standard	Main			COVER, REAR FLOOR UNDER CENTER	1	222.60	222.60	25.00	166.95	Replace	0	0	Check	?
Standard	Main			PANEL SUB-ASSY, FENDER REAR RH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	Xan
Standard	Main			PANEL SUB-ASSY, FENDER REAR LH	1	824.80	824.80	25.00	618.60	Replace	0	0	Not Give	Xan
Standard	Main			LINER, REAR FENDER , LH	1	135.80	135.80	25.00	101.85	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE PANEL SUB-ASSY, BACK DOOR	1	929.60	929.60	25.00	697.20	Replace	1	697.20	Replace	bf✓
Standard	Main			TAIL GATE WEATHERSTRIP, BACK DOOR	1	360.70	360.70	25.00	270.53	Replace	1	270.53	Replace	nc✓

Total Spare Part Cost 15,239.64

Surveyor Total 6,357.78

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	1	27.90	27.90	25.00	20.92	Replace	1	20.92	Replace	nee /
Standard	Main			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	1	668.40	668.40	25.00	668.40	Replace	1	668.40	Replace	ca /
Standard	Main			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	1	39.22	39.22	25.00	39.22	Replace	1	39.22	Replace	nee /
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	39.22	39.22	25.00	39.22	Replace	1	39.22	Replace	nee /
Standard	Main			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	1	39.22	39.22	25.00	39.22	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, RH	1	394.29	394.29	10.00	394.29	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY, REAR COMBINATION LAMP, LH	1	394.29	394.29	10.00	394.29	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY ASSY, RR BUMPER, RH	1	438.12	438.12	10.00	438.12	Replace	0	0	Not Give	X11
Standard	Main			LENS & BODY ASSY, RR BUMPER, LH	1	438.12	438.12	10.00	438.12	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR COMBINATION LAMP, RH	1	40.50	40.50	25.00	40.50	Replace	0	0	Not Give	X11
Standard	Main			COVER, REAR COMBINATION LAMP, LH	1	40.50	40.50	25.00	40.50	Replace	0	0	Not Give	X11
Standard	Main			TAIL GATE GLASS SUB-ASSY, BACK DOOR	1	1,177.28	1,177.28	25.00	1,177.28	Replace	0	0	Not Give	X11
Standard	Main			TAIL GATE LOWER GLASS SUB-ASSY, BACK DOOR	1	544.43	544.43	25.00	544.43	Replace	1	544.43	Replace	ca /
Standard	Main			SEALANT W/SCREEN	3	111.00	111.00	0.00	111.00	Replace	3	111.00	Replace	nee /
Standard	Main			TAILGATE TRIM, UPPER	1	37.88	37.88	25.00	37.88	Replace	0	0	Not Give	X11
Standard	Main			TAILGATE TRIM, RH	1	69.07	69.07	25.00	69.07	Replace	0	0	Not Give	X11
Standard	Main			TAILGATE TRIM, LH	1	69.07	69.07	25.00	69.07	Replace	0	0	Not Give	X11

Total Spare Part Cost 15,239.64

Surveyor Total 6,357.78

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 11,984.89

Final Sur Total 5,086.22

Yr Regn: 2020/2021

SLX 27E 312 X13

Veh No: 1

SMRT Recommendation										Surveyor Approval				Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			TAILGATE TRIM , LOWER	1	218.50	218.50	25.00	163.88	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE BOARD ASSY	1	251.50	251.50	25.00	188.63	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE BOARD , COVER	1	24.10	24.10	25.00	18.08	Replace	0	0	Not Give	Xan
Standard	Main	VM		CLIP(FOR FRONT BODY PILLAR GARNISH)	10	2.20	22.00	25.00	16.50	Replace	0	0	Not Give	Xan
Standard	Main			TAILGATE BOARD , HANDLE PULL	1	19.50	19.50	25.00	14.63	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE BACK DOOR HINGE ASSY, RH & LH	2	59.10	118.20	25.00	88.65	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE STAY ASSY , BACK DOOR , RH	1	235.00	176.25	25.00	176.25	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE BOLT, BACK DOOR STAY , RH & LH	2	11.80	23.60	30.00	16.52	Replace	0	0	Not Give	Xan
Standard	Main	BODY LH		TAIL GATE STAY BRACKET, BACK DOOR , RH & LH	2	11.80	23.60	25.00	17.70	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE STAY ASSY , BACK DOOR , LH	1	235.00	235.00	25.00	176.25	Replace	0	0	Not Give	Xan
Standard	Main			TAIL GATE LOCK ASSY, BACK DOOR	1	452.10	452.10	10.00	406.89	Replace	1	406.89	Replace	scr /
Standard	Main			TAIL GATE LOCK COVER , BACK DOOR	1	25.30	25.30	25.00	18.98	Replace	1	18.98	Replace	scr /
Standard	Main			TAIL GATE STRIKER ASSY, BACK DOOR	1	24.90	24.90	25.00	18.67	Replace	0	0	Not Give	Xan
Standard	Main			EMBLEM SUB-ASSY REAR	1	46.30	46.30	25.00	34.72	Replace	1	34.72	Replace	scr /
Standard	Main			SPOILER SUB-ASSY, REAR	1	1,322.10	1,322.10	25.00	991.57	Replace	1	991.57	Replace	scr /
Standard	Main			LAMP SET, STOP CENTER	1	186.50	186.50	10.00	167.85	Replace	1	167.85	Replace	scr /
Standard	Main			PROTECTOR, REAR SPOILER	2	14.00	28.00	25.00	21.00	Replace	2	21.00	Replace	scr /
Standard	Main			WIRE, TAIL GATE BACK DOOR	1	246.80	246.80	10.00	222.12	Replace	0	0	Not Give	Xan
Standard	Main			WIRE, TAIL GATE BACK DOOR , NO.2	1	246.80	246.80	10.00	222.12	Replace	0	0	Not Give	Xan
Standard	Main			STICKER STRIDES TAXI WITH (GO GREEN LOGO)	1	7.80	7.80	0.00	7.80	Replace	1	7.80	Replace	scr /
Standard	Main			STICKER DECAL 6555 8888	1	21.60	21.60	0.00	21.60	Replace	1	21.60	Replace	scr /

Total Spare Part Cost 15,239.64

Surveyor Total 6,357.78

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 11,984.89

Final Sur Total 5,086.22

SMRT Recommendation											Surveyor Approval			
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.80	629.80	25.00	472.35	Replace	1	0	Repair	R
Standard	Main			SPARE TYRE PANEL, PAN, REAR FLOOR	1	564.80	564.80	25.00	423.60	Replace	0	0	Not Give	Xan
Standard	Main			SEALANT SIKAFLEX	1	37.00	37.00	0.00	37.00	Replace	0	0	Not Give	Xan
Standard	Main			END PANEL, COVER, DECK TRIM SERVICE HOLE	1	47.00	47.00	25.00	35.25	Replace	0	0	Check	?
Standard	Main			END PANEL, COVER, DECK TRIM, REAR	1	122.80	122.80	25.00	92.10	Replace	0	0	Check	?
Standard	Main			EXTENSION, REAR FLOOR SIDE PANEL, LH	1	76.20	76.20	25.00	57.15	Replace	0	0	Not Give	Xan
Standard	Main	Body		BRACKET, REAR BUMPER COVER	1	17.10	17.10	25.00	12.83	Replace	0	0	Not Give	Xan
Standard	Main			PANEL ASSY, DECK TRIM SIDE, LH	1	344.70	344.70	25.00	258.53	Replace	1	258.5	Replace	de
Total Spare Part Cost									15,239.64	Surveyor Total		6,357.78		
Lump Sum Discount (%)									20.00	Lump Sum Dis (%)		20		
Final Spare Part Cost									11,984.89	Final Sur Total		5,086.22		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	1,690.00	700	
Total:			1,690.00	700.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY REAR FENDER LH	378.00	0	Xan
3	Main	TO RESPRAY REAR FENDER RH	378.00	0	Xan
4	Main	TO RESPRAY TAIL GATE	378.00	200	
5	Main	TO RESPRAY TAILGATE OUTSIDE GARNISH	180.00	100	
6	Main	TO RESPRAY REAR SPARE TYRE PANEL	180.00	0	Xan
Total:			2,592.00	600.00	

Yr Regn:

SLX 21E

Veh No:

Date:

2022, 14:55

https://vacswweb.smrt.com.sg/Estimation.aspx

No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
7	Main	TO RESPRAY TAIL LAMP PANEL LH	180.00	0 Xan	
8	Main	TO RESPRAY REAR PANEL	180.00	100	
9	Main	TO RESPRAY TAIL LAMP PANEL RH	180.00	0 Xan	
10	Main	TO RESPRAY REAR SPOILER	180.00	0 Xan	
Total:			2,592.00	600.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0 Xan	
2	Main	TO REPLACE SUNDRY PARTS	100.00	0 Xan	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	20	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	40	
5	Main	TO CHECK WIRING AND SYSTEM FUNCTION	120.00	0 Xan	
6	Main	TO REMOVE / REFIT WINDSCREEN	120.00	80	
7	Main	TO ALIGN CHASSIS	350.00	0 Xan	
8	Main	TO TRANSFER REAR TAILGATE MECHANISM	120.00	60	
9	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	350.00	0 Xan	
10	Main	TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	125.00	
Total:			1,665.00	325.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	11,984.89	5,086.22
Total Labour Cost	1,690.00	700.00
Total Spray Painting	2,592.00	600.00
Other	1,665.00	325.00
Overall Total	17,931.89	6,711.22

Date:

Veh No:

2022, 14:55

Estimator Assesment(\$)

Surveyor Assesment(\$)

Lump Sum Repair Option



Lump Sum Total

17,950.00

6,700.00

Surveyor Approved Amount

6,700.00

No of Repair Days*

8

7

Remarks

LUMP SUM REPAIR / RESURVEY AFTER PAINT PHOTO /

Surveyor Name

Rasul

Signature




Save

Clear

Survey Date

28/01/2022

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Veh No:

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 27/01/2022 15:46 (SGT)
Date of Accident 27/01/2022 11:30 (SGT)
Exact Location of Accident Senoko Ave, Singapore
Additional Location Information SENOKO AVE TOWARDS ADMIRALTY ROAD WEST
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SHB5743B

INSURED/POLICYHOLDER

Is company? Yes
Name Of Registered Owner Strides Taxi Pte Ltd
Company Reg No 1XXXXX369K
Email Address AUTO-SVCS-TARC@SMRT.COM.SG
Mobile Phone No (Phone) +65-68662671
Alternative Phone No (Office) +65-68662672

VEHICLE PARTICULARS

Manufacturer Toyota
Model Prius
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party
Vehicle Category Taxi
Transmission Auto
CC 1800

INSURANCE COMPANY

Name of Insurance Company MS First Capital Insurance Ltd
Type of Coverage ThirdParty
Fleet Policy Yes
Policy Number D-21097466MFSH
Cover Note Number -

DRIVER

Name of Driver KUAN SIEW LEONG
NRIC No SXXXX729I

Birth
ation
Of Driving Pass
ing experience
der
ile Number
Phone Number
mail Address
address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

04/05/1968
Outdoor
16/07/1992
29 YEARS AND 6 MONTHS
Male
(Phone) +65-68662672
-
AUTO-SVCS-TARC@SMRT.COM.SG
11
-
-
No
RELIEF
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other vehicle or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
No
-
Yes
3
No

PASSENGER 1

Name
Gender

UNKNOWN
Female

PASSENGER 2

Name
Gender

UNKNOWN
Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

ON 27/01/22 AT ABOUT 1130HRS. I WAS TRAVELLING ALONG SENOKO AVE WITH 2 PASSENGERS ON BOARD. I WAS APPROACHING THE TRAFFIC JUNCTION AND THE TRAFFIC LIGHT TURNED RED, AS SUCH I STOPPED. SUDDENLY A VEHICLE (GBB2942J) HIT ONTO REAR PORTION OF MY VEHICLE. DUE TO THE IMPACT, MY VEHICLE MOVE FORWARD TOWARDS ADMIRALTY RD WEST.

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Reasons for not uploading a video of the accident
Was there any audio recorded?

Yes
Yes
FILE TOO BIG
No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBB2942J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	UNKNOWN
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Photos

/5

Add res. 

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

27/1/22

27/1/22



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	369K
Vehicle No.:	SHB5743B
Vehicle to be Exported:	No
Intended Deregistration Date:	02 Feb 2022
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS HYBRID 1.8 CVT
Primary Colour:	Maroon
Manufacturing Year:	2017
Engine No.:	2ZRS09B732
Chassis No.:	JTDKB3FU103573048
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$29,007.00
Original Registration Date:	12 Oct 2017
First Registration Date:	12 Oct 2017
Transfer Count:	0
Actual ARF Paid:	\$5,000.00

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	11 Oct 2025
PARF Rebate Amount:	\$3,750.00

COE Expiry Date:	11 Oct 2025
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$34,052.00
COE Rebate Amount:	\$15,710.00
Total Rebate Amount:	\$19,460.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 02 Feb 2022

OK