

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22000999/KTY3N2**Date:** 22/02/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00139902100
<b>Claimant Vehicle No :</b>	SKE2244T	<b>Insured Vehicle No :</b>	XE2409G
Date of Loss:	25/01/2022	Nature of Claim:	TP
		Claim No:	SNM22D200666/C02

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SKE2244T</b>	Engine No:	B4204T74103637
Make & Model:	VOLVO S80, 2.0 T5 (A)	Chassis No:	YV1AS475BC1154378
Reg. Date:	16/02/2012 (Man. Year: 2011)	Odometer:	198515 km
Colour:	Metallic Grey		
Engine Capacity:	1999 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	225/50ZR17	Rear Tyre Size:	225/50ZR17
Front Left Side:	Falken 5 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 5 mm	Rear Right Side:	Falken 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	12,037.90	3,960.90	8,077.00	67.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,000.00	1,060.00	2,940.00	73.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>16,037.90</b>	<b>5,020.90</b>	<b>11,017.00</b>	<b>68.69</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,000.00</b>		
<b>(\$\$)</b>	16,037.90	4,000.00	12,037.90	75.06
<b>+ GST 7.00/7.00% (\$\$)</b>	1,122.65	280.00	842.65	75.06
<b>Nett Amount (\$\$)</b>	<b>17,160.55</b>	<b>4,280.00</b>	<b>12,880.55</b>	<b>75.06</b>

**INSPECTION**

Date of Assignment:	28/01/2022	
Date Inspected:	28/01/2022	Inspected At: Motor Edgevantage Pte Ltd (HQ) 160 Sin Ming Drive, Sin Ming AutoCity #03-01/02 Singapore 575722
Estimated Period of Repair:	4.0 days	

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 21 Feb 2022)
<b>Parts:</b>	143	VOLVO S80 2.0 T5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKE2244T)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*VOLVO REAR BOOT LID ASSEMBLY S80	Repair	2,150.00 F	*- FL
2	1		*VOLVO REAR BOOT LID CHROME MOULDING S80	Serviceable	423.00 F	*- FL
3	1		*VOLVO REAR BOOT LID EMBLEM (S80)	Necessary	85.00 F	*85.00 FL
4	1		*VOLVO REAR BOOT LID EMBLEM (VOLVO)	Necessary	124.00 F	*88.00 FL
5	1		*VOLVO REAR BOOT LID EMBLEM (T5)	Necessary	86.00 F	*86.00 FL
6	1		*VOLVO REAR BOOT LID HINGES LH	Repair	221.00 F	*- FL
7	1		*VOLVO REAR BOOT LID HINGES RH	Repair	221.00 F	*- FL
8	2		*VOLVO REAR BOOT LID ABSORBER	Serviceable	156.00 F	*- FL
9	1		*VOLVO REAR BUMPER ASSEMBLY S80	Bent	2,128.30 F	*1,620.00 FL
10	1		*VOLVO REAR BUMPER SIDE BRACKET RH	Repair	85.00 F	*- FL
11	1		*VOLVO REAR BUMPER SIDE BRACKET LH	Repair	85.00 F	*- FL
12	1		*VOLVO REAR BUMPER REINFORCEMENT S80	Buckled	1,582.00 F	*1,119.00 FL
13	1		*VOLVO REAR BUMPER LOWER SPOILER S80	Mtg Cracked	1,120.00 F	*1,120.00 FL
14	1		*VOLVO REAR SECTION PANEL S80	Repair	1,693.00 F	*- FL
15	1		*VOLVO REAR BOOT LID LOCK S80	Dented	283.00 F	*283.00 FL
16	1		*VOLVO REAR BOOT LID CATCH S80	Repair	230.00 F	*- FL
17	4		*VOLVO REAR PARKING SENSOR S80	Serviceable	515.60 F	*- FL
18	1		*VOLVO REAR PARKING SENSOR HARNESS S80	Serviceable	850.00 F	*- FL

F=Franchise part. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>12,037.90</b>	<b>4,401.00</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	440.10
<b>Total Parts (\$\$)</b>	<b>12,037.90</b>	<b>3,960.90</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REMOVE,RE-INSTALL,REPLACE OF REAR BOOT LID TRUNK,REAR BUMPER,REAR BUMPER REINFORCEMENT,LOWER SPOILER	New	1,600.00	400.00
2	TO PUTTY,REPAIR SPRAY PAINTING REAR BOOT LID TRUCK,REAR BUMPER,REAR INNER SECTION PANEL & SPARE TYRE COMPARTMENT	New	1,600.00	660.00
3	TO CONDUCT WELDING ON REAR SECTION PANEL & REALIGN REAR SPARE TYRE COMPARTMENT	New	600.00	0.00
4	TO CHECK WIRING & RESET FAULT CODE	New	200.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>4,000.00</b>	<b>1,060.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >