

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC6/AIG22001000/AEA3Q2**Date:** 21/09/2022REFERENCE

|                              |                                      |                             |              |
|------------------------------|--------------------------------------|-----------------------------|--------------|
| Handling Insurer:            | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:                  | 1800138066   |
| <b>Claimant Vehicle No :</b> | SLF2351A                             | <b>Insured Vehicle No :</b> | SMF8326Y     |
| Date of Loss:                | 25/01/2022                           | Nature of Claim:            | TP           |
|                              |                                      | Claim No:                   | 7598242248SG |

DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                                 |             |            |
|-----------------------------|-------------------------------------------------|-------------|------------|
| Reg No:                     | <b>SLF2351A</b>                                 |             |            |
| Make & Model:               | HONDA VEZEL, 1.5 S CVT ABS D/AIRBAG 2WD 5DR (A) | Engine No:  | LEB5905096 |
| Reg. Date:                  | 18/08/2016 (Man. Year: 2016)                    | Chassis No: | RU31205085 |
| Colour:                     | White                                           | Odometer:   | 166013 km  |
| Engine Capacity:            | 1496 cc                                         |             |            |
| Market Value/New Car Price: | N/A                                             |             |            |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b>               |             |            |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

CONDITION OF TYRES

|                   |               |                  |               |
|-------------------|---------------|------------------|---------------|
| Front Tyre Size:  | 225/45R19     | Rear Tyre Size:  | 225/45R19     |
| Front Left Side:  | Yokohama 6 mm | Rear Left Side:  | Yokohama 6 mm |
| Front Right Side: | Yokohama 6 mm | Rear Right Side: | Yokohama 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                           | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|-------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                           | 14,800.96         | 7,525.44          | 7,275.52          | 49.16         |
| Miscellaneous Items                             | 0.00              | 0.00              | 0.00              |               |
| Labour                                          | 6,250.00          | 1,710.00          | 4,540.00          | 72.64         |
| Paintwork Labour                                | 0.00              | 0.00              | 0.00              |               |
| Towing                                          | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (S\$)</b>             | <b>21,050.96</b>  | <b>9,235.44</b>   | <b>11,815.52</b>  | <b>56.13</b>  |
| <b>Approved Total (Overridden) (S\$)</b>        |                   | <b>7,400.00</b>   |                   |               |
| <b>Nett Amount (S\$)</b>                        | <b>21,050.96</b>  | <b>7,400.00</b>   | <b>13,650.96</b>  | <b>64.85</b>  |
| <b>+ Loss of Use (8.0 x S\$60.00/day) (S\$)</b> |                   | 480.00            |                   |               |
| <b>Nett Liability (S\$)</b>                     |                   | <b>7,880.00</b>   |                   |               |

INSPECTION

|                             |            |                                                                                                                       |
|-----------------------------|------------|-----------------------------------------------------------------------------------------------------------------------|
| Date of Assignment:         | 26/01/2022 |                                                                                                                       |
| Date Inspected:             | 26/01/2022 | Inspected At: HD Perfect Autowork Pte Ltd (HQ)<br>8 Kaki Bukit Ave 4, #08-09 Premier @ Kaki Bukit<br>Singapore 415875 |
| Estimated Period of Repair: | 6.0 days   |                                                                                                                       |

**Adjuster:** ADRIAN LING**Manager:** Asher Sng Rong Yi*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                               | Condition     | Repairer's  | Amount       |
|-----|-----|----------|-------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *HEADLAMP RH                              | Cracked       | 1,850.00 FL | *1,850.00 FL |
| 2   | 1   |          | *HEADLAMP LOWER BRACKET RH                | Not Necessary | 52.00 FL    | *- FL        |
| 3   | 1   |          | *FRONT BUMPER                             | Not Necessary | 878.50 FL   | *- FL        |
| 4   | 1   |          | *FRONT FENDER RH                          | Serviceable   | 748.80 FL   | *- FL        |
| 5   | 1   |          | *FRONT FENDER INNER GARNISH RH            | Not Necessary | 85.00 FL    | *- FL        |
| 6   | 1   |          | *FRONT FENDER ARCD GARNISH RH             | Cut           | 195.00 FL   | *195.00 FL   |
| 7   | 1   |          | *FRONT FENDER INNER COWLING RH            | Not Necessary | 170.50 FL   | *- FL        |
| 8   | 1   |          | *SIDE SKIRT RH                            | Deformed      | 790.00 FL   | *790.00 FL   |
| 9   | 1   |          | *SIDE MIRROR RH                           | Not Necessary | 841.60 FL   | *- FL        |
| 10  | 1   |          | *FRONT DOOR RH                            | Dented        | 950.00 FL   | *950.00 FL   |
| 11  | 1   |          | *FRONT DOOR OUTER MOULDING RH             | Not Necessary | 87.00 FL    | *- FL        |
| 12  | 2   |          | *FRONT DOOR HINGE RH                      | Not Necessary | 110.00 FL   | *- FL        |
| 13  | 1   |          | *FRONT DOOR CHECKER RH                    | Not Necessary | 74.00 FL    | *- FL        |
| 14  | 1   |          | *FRONT DOOR WEATHER STRIP RH              | Cut           | 127.00 FL   | *127.00 FL   |
| 15  | 1   |          | *FRONT DOOR GLASS CHANNEL RH              | Not Necessary | 106.00 FL   | *- FL        |
| 16  | 1   |          | *FRONT DOOR INNER LOCK RH                 | Not Necessary | 262.00 FL   | *- FL        |
| 17  | 1   |          | *FRONT DOOR LOCK CATCH RH                 | Not Necessary | 27.00 FL    | *- FL        |
| 18  | 1   |          | *FRONT DOOR OUTER KEY LOCK RH             | Not Necessary | 185.00 FL   | *- FL        |
| 19  | 1   |          | *FRONT DOOR INNER TRIM BOARD RH           | Cracked       | 650.00 FL   | *498.00 FL   |
| 20  | 1   |          | *FRONT DOOR REGULATOR RH                  | Not Necessary | 215.00 FL   | *- FL        |
| 21  | 1   |          | *FRONT DOOR POWER WINDOW MOTOR RH         | Not Necessary | 400.00 FL   | *- FL        |
| 22  | 1   |          | *FRONT DOOR SPEAKER RH                    | Not Necessary | 165.00 FL   | *- FL        |
| 23  | 1   |          | *FRONT DOOR FRAME WEATHERS TRIP RH        | Not Necessary | 135.00 FL   | *- FL        |
| 24  | 1   |          | *FRONT DOOR BLACK STICKER RH              | Necessary     | 95.00 FL    | *95.00 FL    |
| 25  | 1   |          | *FRONT ABS SENSOR                         | Not Necessary | 295.00 FL   | *- FL        |
| 26  | 1   |          | *FRONT CROSSMEMBER                        | Not Necessary | 1,365.00 FL | *- FL        |
| 27  | 1   |          | *FRONT STEERING RACK & PINION             | Bent          | 1,750.00 FL | *1,750.00 FL |
| 28  | 1   |          | *FRONT SHOCK ABSORBER RH                  | Bent          | 586.50 FL   | *586.50 FL   |
| 29  | 1   |          | *FRONT LOWER ARM RH                       | Bent          | 474.70 FL   | *474.70 FL   |
| 30  | 1   |          | *FRONT KNUCKLE ARM RH                     | Damaged       | 461.70 FL   | *461.70 FL   |
| 31  | 1   |          | *FRONT KNUCKLE ARM INNER BEARING RH       | Damaged       | 262.00 FL   | *262.00 FL   |
| 32  | 1   |          | *FRONT WHEEL HUP RH                       | Damaged       | 379.40 FL   | *379.40 FL   |
| 33  | 1   |          | *FRONT LINKAGE RH                         | Not Necessary | 65.00 FL    | *- FL        |
| 34  | 1   |          | *SET FRONT BUMPER CLIP                    | Not Necessary | 60.00 FS    | *- FS        |
| 35  | 1   |          | *SET FRONT BUMPER LOWER GARNISH CLIP      | Not Necessary | 60.00 FS    | *- FS        |
| 36  | 1   |          | *SET FRONT WIPER PANEL GARNISH CLIP       | Not Necessary | 30.00 FS    | *- FS        |
| 37  | 1   |          | *SET FRONT SUPPORT PANEL TOP GARNISH CLIP | Not Necessary | 30.00 FS    | *- FS        |
| 38  | 1   |          | *SET FRONT FENDER INNER GARNISH CLIP RH   | Not Necessary | 50.00 FS    | *- FS        |
| 39  | 1   |          | *SET FRONT FENDER ARCED GARNISH CLIP LH   | Necessary     | 50.00 FS    | *20.00 FS    |
| 40  | 1   |          | *SET FRONT FENDER INNER COWLING CLIP RH   | Not Necessary | 50.00 FS    | *- FS        |
| 41  | 1   |          | *SIDE SKIRT CLIP RH                       | Necessary     | 80.00 FS    | *30.00 FS    |
| 42  | 1   |          | *FRONT DOOR SEALANT RH                    | Not Necessary | 150.00 FS   | *- FS        |
| 43  | 1   |          | *SET FRONT DOOR TRIM BOARD CLIP           | Necessary     | 80.00 FS    | *30.00 FS    |
| 44  | 1   |          | *FRONT DOOR PROTECTOR SEAL (SPECIAL TYPE) | Cut           | 150.00 FS   | *60.00 FS    |
| 45  | 1   |          | *SET WHEEL CAP                            | Not Necessary | 150.00 FS   | *- FS        |
| 46  | 1   |          | *FRONT WHEEL TYRE RH                      | Not Necessary | 450.00 FS   | *- FS        |
| 47  | 1   |          | *FRONT WHEEL RIM RH                       | Cut           | 1,500.00 FS | *650.00 FS   |
| 48  | 1   |          | *BRAKE OIL                                | Not Necessary | 40.00 FS    | *- FS        |

F=Franchise part. S=SpcNett. L=ListItemDisc.

|                                                            |                  |                 |
|------------------------------------------------------------|------------------|-----------------|
| <b>Sub Total (\$\$)</b>                                    | <b>17,768.70</b> | <b>9,209.30</b> |
| <b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b> | 2,967.74         | 1,683.86        |
| <b>Total Parts (\$\$)</b>                                  | <b>14,800.96</b> | <b>7,525.44</b> |

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                                  | Lab.Type | Repairer's      | Amount          |
|---------------------------------|----------------------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b>Labour Items</b>             |                                                                                              |          |                 |                 |
| 1                               | PANEL BEATING,REMOVING AND REPLACING PARTS                                                   | New      | 1,800.00        | 700.00          |
| 2                               | SPRAY PAINTING TO AFFECTED AREA                                                              | New      | 1,800.00        | 600.00          |
| 3                               | TUFF COAT                                                                                    | New      | 250.00          | 40.00           |
| 4                               | WIRING CHECK                                                                                 | New      | 120.00          | 30.00           |
| 5                               | REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR                    | New      | 350.00          | 0.00            |
| 6                               | REMOVE & REFIX AUDIO SPEAKER                                                                 | New      | 120.00          | 0.00            |
| 7                               | TRANSFER FRONT DOOR MECHANISM                                                                | New      | 80.00           | 80.00           |
| 8                               | CONDUCT WATER LEAKAGE TEST                                                                   | New      | 80.00           | 0.00            |
| 9                               | REMOVE AND REFIX FRONT UNDERCARRIAGE                                                         | New      | 650.00          | 180.00          |
| 10                              | REMOVE AND REFIX POWER STEERING RACK AND PINION                                              | New      | 350.00          | 0.00            |
| 11                              | FOUR WHEEL ALIGNMENT                                                                         | New      | 120.00          | 80.00           |
| 12                              | RESET ABS LIGHT                                                                              | New      | 350.00          | 0.00            |
| 13                              | TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS,RESET MEMORIES TO SPECIFICATION ETC | New      | 180.00          | 0.00            |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                              |          | <b>6,250.00</b> | <b>1,710.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >