

HD Perfect Autowork Pte Ltd

Company Reg No: 202136904Z

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail: hdperfectautowork@gmail.com



HD PERFECT
AUTOWORK PTE LTD

DATE : 25.01.2022

TO : **AIG MOTOR CLAIMS DEPTS**
VEHICLE NO : **SLF2351K**
MODEL : **HONDA VEZEL**
DATE OF ACCIDENT : 25.01.2022
TIME OF ACCIDENT : 14:45HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	HEADLAMP RH <i>cracked</i>	1	\$ 1850	\$ 1850
2	HEADLAMP LOWER BRACKET RH <i>new</i>	1	\$ 52.00	\$ 52.00
3	FRONT BUMPER <i>new</i>	1	\$ 878.50	\$ 878.50
4	FRONT FENDER RH <i>dent</i> SVC	1	\$ 748.80	\$ 748.80
5	FRONT FENDER INNER GARNISH RH <i>new</i>	1	\$ 85.00	\$ 85.00
6	FRONT FENDER ARCD GARNISH RH <i>new</i>	1	\$ 195.00	\$ 195.00
7	FRONT FENDER INNER COWLING RH <i>new</i>	1	\$ 170.50	\$ 170.50
8	SIDE SKIRT RH <i>dent</i>	1	\$ 790.00	\$ 790.00
9	SIDE MIRROR RH <i>dent</i> NEW	1	\$ 841.60	\$ 841.60
10	FRONT DOOR RH <i>dent</i>	1	\$ 950.00	\$ 950.00
11	FRONT DOOR OUTER MOULDING RH <i>new</i>	1	\$ 87.00	\$ 87.00
12	FRONT DOOR HINGE RH <i>new</i>	2	\$ 55.00	\$ 110.00
13	FRONT DOOR CHECKER RH <i>new</i>	1	\$ 74.00	\$ 74.00
14	FRONT DOOR WEATHER STRIP RH <i>new</i>	1	\$ 127.00	\$ 127.00
15	FRONT DOOR GLASS CHANNEL RH <i>new</i>	1	\$ 106.00	\$ 106.00
16	FRONT DOOR INNER LOCK RH <i>new</i>	1	\$ 262.00	\$ 262.00
17	FRONT DOOR LOCK CATCH RH <i>new</i>	1	\$ 27.00	\$ 27.00
18	FRONT DOOR OUTER KEY LOCK RH <i>new</i>	1	\$ 185.00	\$ 185.00
19	FRONT DOOR INNER TRIM BOARD RH <i>cracked</i>	1	\$ 650.00	\$ 650.00
20	FRONT DOOR REGULATOR RH <i>new</i>	1	\$ 215.00	\$ 215.00
21	FRONT DOOR POWER WINDOW MOTOR RH <i>new</i>	1	\$ 400.00	\$ 400.00
22	FRONT DOOR SPEAKER RH <i>new</i>	1	\$ 165.00	\$ 165.00
23	FRONT DOOR FRAME WEATHER STRIP RH <i>new</i>	1	\$ 135.00	\$ 135.00
24	FRONT DOOR BLACK STICKER RH <i>new</i>	1	\$ 95.00	\$ 95.00
25	FRONT ABS SENSOR <i>new</i>	1	\$ 295.00	\$ 295.00

TO : **AIG MOTOR CLAIMS DEPTS**
 VEHICLE NO : **SLF2351K**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 25.01.2022
 TIME OF ACCIDENT : 14:45HRS

26	FRONT CROSSMEMBER <i>Neu</i>	1	\$ 1,365.00	\$ 1,365.00	x.
27	FRONT STEERING RACK & PINION <i>Best</i>	1	\$ 1,750.00	\$ 1,750.00	✓
28	FRONT SHOCK ABSORBER RH <i>Best</i>	1	\$ 586.50	\$ 586.50	✓
29	FRONT LOWER ARM RH <i>Best</i>	1	\$ 474.70	\$ 474.70	✓
30	FRONT KNUCKLE ARM RH <i>2nd</i>	1	\$ 461.70	\$ 461.70	✓
31	FRONT KNUCKLE ARM INNER BEARING RH <i>2nd</i>	1	\$ 262.00	\$ 262.00	✓
32	FRONT WHEEL HUP RH <i>Dmgd.</i>	1	\$ 379.40	\$ 379.40	✓
33	FRONT LINKAGE RH <i>Neu</i>	1	\$ 65.00	\$ 65.00	x.

8419.30

56735.44

TOTAL PRICE \$ 14,141.00
 LESS 20% \$ 2,828.20
SUB TOTAL PRICE \$ 11,312.80

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT	
1	FRONT BUMPER CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	x.
2	FRONT BUMPER LOWER GARNISH CLIP (SET) <i>Neu</i>	1	\$ 60.00	\$ 60.00	x.
3	FRONT WIPER PANEL GARNISH CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	x.
4	FRONT SUPPORT PANEL TOP GARNISH CLIP (SET) <i>Neu</i>	1	\$ 30.00	\$ 30.00	+
5	FRONT FENDER INNER GARNISH CLIP RH (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
6	FRONT FENDER ARCED GARNISH CLIP LH (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	20
7	FRONT FENDER INNER COWLING CLIP RH (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00	+
8	SIDE SKIRT CLIP RH <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
9	FRONT DOOR SEALANT RH <i>Neu</i>	1	\$ 150.00	\$ 150.00	+
10	FRONT DOOR TRIM BOARD CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00	30
11	FRONT DOOR PROTECTOR SEAL (SPECAIL TYPE) <i>cut</i>	1	\$ 150.00	\$ 150.00	60
12	WHEEL CAP (SET) <i>Neu</i>	1	\$ 150.00	\$ 150.00	x
13	FRONT WHEEL TYRE RH <i>Neu</i>	1	\$ 450.00	\$ 450.00	+
14	FRONT WHEEL RIM RH <i>cut</i>	1	\$ 1,500.00	\$ 1,500.00	650
15	BRAKE OIL <i>Neu</i>	1	\$ 40.00	\$ 40.00	x.

790

TOTAL \$ 2,930.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,800.00	<i>700</i>
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,800.00	<i>600</i>
3	TUFF COAT	\$ 250.00	<i>40</i>

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SLF2351K**
 MODEL : **HONDA VEZEL**
 DATE OF ACCIDENT : 25.01.2022
 TIME OF ACCIDENT : 14:45HRS

4	WIRING CHECK	\$ 120.00	30
5	REMOVE & REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	x
6	REMOVE & REFIX AUDIO SPEAKER	\$ 120.00	x
7	TRANSFER FRONT DOOR MECHANISM	\$ 80.00	✓
8	CONDUCT WATER LEAKAGE TEST	\$ 80.00	x
9	REMOVE AND REFIX FRONT UNDERCARRIAGE	\$ 650.00	780
10	REMOVE AND REFIX POWER STEERING RACK AND PINION	\$ 350.00	x
11	FOUR WHEEL ALIGNMENT	\$ 120.00	80
12	RESET ABS LIGHT	\$ 350.00	x
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

TOTAL
 TOTAL PARTS COST : \$ 14,242.80
 TOTAL LABOUR COST : \$ 6,250.00
 TOTAL REPAIR COST : \$ 20,492.80

6250

1710

Admin
 2/5 26/01/22

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.

PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
 IRENE
 HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Vehicle must be resurveyed and Insurance Company

total: 9235.44
 2/5 704K

06 Days