



## YSK AUTO WORKSHOP

No. 1 Kaki Bukit Avenue 6 @Autobay, #01-71 Singapore 417883  
UEN 53311047E

### LKK Auto Consultants Pte Ltd

Blk 51, Paya Ubi Industrial Park,  
Ubi Avenue 1, #02-25 | S(408933)

**Tax Invoice** : 202202\_0034  
**Date** : 26/02/2022  
**Vehicle** : SKU8690P  
**Make Model** : MAZDA 3  
**Accident Date** : 26/01/2022 08:16 (SGT)  
**Accident Location**: 329 CCK AVE 3 MICASA GUARD HOUSE, SINGAPORE


#### Particular

|                                                      |            |
|------------------------------------------------------|------------|
| COST OF REPAIR & LABOUR                              | \$5,100.00 |
| LOSS OF USE 03 Days X @\$120.00 per day              | \$ 360.00  |
| Pre-Repair Inspection for 2 days x @\$120.00 per day | \$ 240.00  |
| GIA / LTA SEARCH FEE                                 | \$ 7.45    |

**Singapore Dollars: Five Thousand Seven Hundred Seven and Cents Forty-Five Only**

**Total S\$: 5,707.45**

=====



YSK Auto Workshop