

ASS. REC. BY:

REF: C721Kenneth

CS/CTI22001005/Kty3

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. DMPCSNW00171382102Claims No. SNM22D200579/C01/TANKL

Sum Insured: _____

Excess: _____

(Client's Record)

1K

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 833k

IDAC Accident Report: _____

Consistent?: Yes or No

GIA / PR Seen: _____

Consistent?: Yes or No

Est. Repairs: 11 days

Res.: Yes or No

Lum Sum: 20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMD 8083RYr Regn: 09.14Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Volkswagen Golf cc1395Colour: Red

A/C: Insured / Std / NI / NA

Sp. Reading: 80709

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVW 777 AUZFW 015241Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD A/Rlm orTyre Size: F: 225/40R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 8 mmR/Bal. 8 mmL/Bal. 8 mmL/Bal. 8 mmD.O.A. 17/1/22D.O.I. 28/1/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

O/S FR & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

submit unecnomical total loss

Pre-Accident Value :S\$ 33,000.00

COE / PARF Rebate :S\$ 19,388.00

Margin for Repair :S\$ 13,612.00

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

Add Fee: ☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) S + RS. SI

) Extras

) Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

S&H Motor Pte Ltd
160 Sin Ming Drive #07-02
Sin Ming Autocity
Singapore 575722

Insurer Reference:
Repairer Reference: 045869
Date calculated: 27/01/2022 4:46 PM

Full Report
Registration: SMD8063R
Printed: 27/01/2022 4:46 PM

Summary Information

Claim		Work Provider:	China Taiping Insurance
Location:	Singapore (SG)		(Singapore) Pte Ltd
Printed by:	SH Motor	Currency:	SGD
Claim Reference:		Date of Incident:	17/01/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle
Manufacturer: VW
Model: GOLF (5G)
Sub Model: BASE MODEL
Model Sheet Number: 06 B1 23
Registration: SMD8063R
VIN number: WVVZZZAUZFW015241
Odometer:

*Not with the
61 Day @
Penny After Pain
Ex @ 1000h*

Model Specs			
FROM 06.2014	OCCUPANT PROTECT SYS	BLUE MOTION TECHNO	CHROME PACKAGE
CLIMATRONIC	D/MIRROR W/AMBIENT	LIGHT-/RAIN SENSOR	FRT/RR ELECT WINDOWS
AUTO DIPPING MIRROR	8 SPEAKER	RADIO "COMP COLOUR"	FOG LAMPS
LIGHT SWITCHING AUTO	CLOTH TRIM	HEIGHT ADJ PASS SEAT	STRG WHEEL LEATHER
MULTI FUNC INDICATOR	LUMBAR SUPPORT	STOP-START SYSTEM	FRONT CENTRE ARMREST
REAR CENTRE ARMREST	SMOKER EQUIPMENT	ALTERNATOR 140A	HD COOLING
1.4 LTR 90KW	7-SPEED DSG	SELECT DRIVE	TYRES 205/55 R16..V
WHEELS 6.5J X 16 ALU	SPACE SAVER SP-WHEEL	RR DUAL EXHAUST PIPE	5-DOOR
CRUISE CONTROL	TWO COAT METALLIC	PREPARE OFF VEHICLE	

Labour

Code	Description	Time Base 10 WU/h		Price = 42.00 SGD/h	
		WU	Price SGD	WU	Price SGD
45 01 01 ZAX	CHECK ABS SYSTEM WITH TESTER	2.0	8.40		
97 85 09 50	DETACH + REFIT BATTERY EARTH STRAP	1.0	4.20		
66 05 19 00	R + R RADIATOR GRILLE	2.0	8.40		
63 29 19 50	R + R FRONT BUMPER COVER (RADIATOR GRILLE REMOVED)	4.0	16.80		
63 29 55 51	RENEW FRONT BUMPER COVER (REMOVED)	12.0	50.40		
	INCLUDES: CONVERT ATTACHED PARTS				
94 15 19 50)	R + R RIGHT HEADLAMP (RADIATOR GRILLE REMOVED) (FRONT BUMPER COVER DETACHED OR REMOVED)	1.0	4.20		

Code	Description	WU	Price SGD
50 55 19 50	DOES NOT INCLUDE: ADJUST HEADLAMPS R + R RIGHT FRONT WING (BUMPER COVER REMOVED) INCLUDES: R + R WHEEL AND WHEELHOUSE SHELL	7.0	29.40
50 55 51 50	R/F WING SEAL (COMPOSITE WORK)	3.0	12.60
NO NUMBER	R + R R/F WING STRUT	2.0	8.40
55 22 19 00	REMOVE/REFIT BONNET PANEL INCLUDES: ADJUST BONNET CLEARANCES	6.0	25.20
55 22 55 50	RENEW BONNET (BONNET REMOVED) INCLUDES: R + R ALL PARTS	4.0	16.80
92 25 20 00	R + R WIPER ARMS	4.0	16.80
66 44 20 50	R + R COWL TRIMS (WIPER ARMS REMOVED)	3.0	12.60
55 25 55 50	REPLACE RH FRONT BONNET HINGE (WITH BONNET REMOVED)	1.0	4.20
55 25 15 50	ADJUST R/F BONNET HINGE	1.0	4.20
70 59 19 00	R + R LEFT FRONT DOOR TRIM	4.0	16.80
57 51 19 00	R + R RIGHT FRONT DOOR	3.0	12.60
57 51 55 50	RENEW RIGHT FRONT DOOR (DOOR REMOVED) INCLUDES: R + R ALL PARTS	24.0	100.80
66 89 55 50	RENEW R/OUTSIDE MIRROR (REMOVED) INCLUDES: R + R MIRROR HOUSING AND MIRROR GLASS	3.0	12.60
66 78 55 50	RENEW R/MIRROR GLASS (REMOVED)	1.0	4.20
57 53 19 63	RENEW R/F LOWER DOOR HINGE (DOOR REMOVED)	3.0	12.60
57 53 19 53)	RENEW R/F UPPER DOOR HINGE (DOOR AND INSTRUMENT PANEL REMOVED)	1.0	4.20
NO NUMBER	RENEW R/UPP INN HINGE PILLAR (COMP WORK)	11.0	46.20
51 38 55 50	RENEW R/HINGE PILLAR REINFORCEMENT (COMPOSITE WORK)	27.0	113.40
51 49 55 50	RENEW R/SILL REINFORCEMENT (COMP WORK)	23.0	96.60
72 01 19 00)	R + R L/F SEAT (BATTERY DETACHED)	4.0	16.80
69 24 19 50	R + R LEFT FRONT SEAT BELT LOCK (SEAT REMOVED)	1.0	4.20
72 01 19 00)	R + R R/F SEAT (BATTERY DETACHED)	4.0	16.80
69 24 19 50	R + R RIGHT FRONT SEAT BELT LOCK (SEAT REMOVED)	1.0	4.20
70 57 19 00	R + R LEFT UPPER A-PILLAR TRIM	2.0	8.40
70 57 19 00	R + R RIGHT UPPER A-PILLAR TRIM	2.0	8.40
68 05 19 50	R + R L/INN SILL PANEL COVER	1.0	4.20
64 29 55 00)	R + R R/F SIDE WINDOW (A-PILLAR TRIM REMOVED)	7.0	29.40
68 05 19 50	R + R R/INN SILL PANEL COVER	1.0	4.20
70 28 19 50	R + R LEFT REAR WHEEL HOUSE TRIM	1.0	4.20
70 28 19 50	R + R RIGHT REAR WHEEL HOUSE TRIM	1.0	4.20
69 11 20 50)	R + R BOTH FRONT SEAT BELTS	3.0	12.60
69 51 19 50	R + R L/F AIRBAG SENSOR	1.0	4.20
69 51 19 50	R + R R/F AIRBAG SENSOR	1.0	4.20
69 67 55 50	RENEW KNEE BAG (REMOVED)	1.0	4.20

Code	Description	WU	Price SGD
59 59 55 50	RENEW PASSENGER AIRBAG UNIT (REMOVED)	1.0	4.20
69 58 55 50	RENEW DRIVER AIRBAG UNIT (REMOVED)	1.0	4.20
70 11 19 00	R + R STEERING COLUMN TRIM	2.0	8.40
70 22 19 00	R + R INSTRUMENT PANEL COVER	2.0	8.40
70 18 19 00)	R + R INSTRUMENT PANEL (LOWER INSTRUMENT PANEL SHELF, GLOVE BOX AND UPPER A-PILLAR TRIMS REMOVED) INCLUDES: REMOVE STEERING WHEEL, STEERING COLUMN SWITCH, INSTRUMENT CLUSTER AND KNEE BAG	15.0	63.00
70 18 55 50	RENEW SWITCH PANEL (REMOVED) INCLUDES: CONVERT SWITCH PANEL	5.0	21.00
70 41 19 00)	R + R FLOOR CARPET CPL (FRONT SEATS, SILL MOULDINGS AND REAR SEAT CUSHION/REAR SEATS REMOVED) INCLUDES: R + R CONSOLE, DETACH + REFIT BONNET LOCK CABLE	8.0	33.60
69 53 19 00)	R + R AIRBAG TRIGGER UNIT	5.0	21.00
69 53 55 50	RENEW AIRBAG TRIGGER UNIT (REMOVED)	1.0	4.20
48 35 19 00)	R + R STEERING GEAR (WHEELS, OSCILLATION DAMPER AND NOISE CONTROL PAN REMOVED) INCLUDES: DETACH + REFIT ASSEMBLY CARRIER DOES NOT INCLUDE: ALIGN FRONT AND REAR, READ OUT FAULT MEMORY	6.0	25.20
48 35 55 50	RENEW STEERING GEAR (REMOVED)	5.0	21.00
47 26 19 50	R + R RIGHT FRONT BRAKE HOSE	1.0	4.20
47 39 19 50)	DETACH + REFIT L/FR BRAKE CALIPER	1.0	4.20
47 39 19 50)	R + R R/F BRAKE CALIPER	1.0	4.20
47 39 55 50	RENEW R/F BRAKE CALIPER (REMOVED)	1.0	4.20
46 36 19 50)	R + R L/F BRAKE PADS	3.0	12.60
46 14 19 50)	R + R RIGHT FRONT BRAKE CALIPER CARRIER	4.0	16.80
46 50 56 50	RENEW FRONT BRAKE DISCS (REMOVED)	1.0	4.20
40 85 19 50)	R + R R/F SPRING STRUT (WHEEL AND COWL TRIM REMOVED)	4.0	16.80
40 90 19 50	R + R RIGHT FRONT SHOCK ABSORBER (SPRING STRUT REMOVED) INCLUDES: R + R SPRING STRUT MOUNT AND COIL SPRING	4.0	16.80
45 46 55 00)	RENEW R/F SPEED SENSOR WIRING SET	6.0	25.20
40 50 19 50	R + R R/F WHEEL BEARING HOUSING (WHEELS REMOVED) INCLUDES: R + R SPEED SENSOR AND BRAKE DISC,	7.0	29.40
40 50 55 50	DETACH + REFIT DRIVE SHAFT RENEW R/F WHEEL BEARING HOUSING (WHEEL BEARING HOUSING REMOVED) INCLUDES: R + R WHEEL BEARING AND WHEEL HUB	4.0	16.80
40 41 19 02)	R + R R/F DRIVE SHAFT	4.0	16.80
40 07 19 00)	R + R ASSEMBLY CARRIER (WHEELS AND SOUND PROTECTION PAN	14.0	58.80

	Description	WU	Price SGD
	REMOVED)		
	INCLUDES: DETACH + REFIT LOWER AXLE RADIUS ARMS		
	DOES NOT INCLUDE: ALIGN FRONT AND REAR		
40 07 55 50	RENEW AGGREGATE CARRIER (REMOVED)	6.0	25.20
47 01 07 50	BLEED BRAKE SYSTEM	3.0	12.60
44 12 55 50	RENEW R/F WHEEL (WHEEL REMOVED)	2.0	8.40
44 05 93 55	BALANCE R/F WHEEL (WHEEL REMOVED)	1.0	4.20
44 95 03 00	ALIGN FRONT AND REAR VEHICLE	10.0	42.00
	INCLUDES: CHECK TOE AND CAMBER, R + R BRACKET AND ALIGNMENT SENSOR		
	DOES NOT INCLUDE: ADJUSTMENT		
94 15 06 00	ADJUST HEADLAMPS	3.0	12.60
	INCLUDES: ADJUST FRONT FOG LAMPS		
4258	RIGHT FLOOR PANEL REPAIR	25 48.0*	168.00
Labour Cost			
	Panel / Mechanical Labour	Hrs	WU
	Alignment	34.50	345.0
	Measuring Work	1.00	10.0
	Total of Labour		1,491.00

Paint

Paint Work	SYSTEM AZT	Time Basis 10 WU/h
Code	Description - TWO COAT METALLIC	WU Price SGD
	BONNET NEW PART PAINTING	22.0
	R/F WING NEW PART PAINTING	9.0
	RIGHT FRONT DOOR NEW PART PAINTING	16.0
	R/F UPPER DOOR HINGE SURFACE PAINT	4.0
	R/F LOWER DOOR HINGE SURFACE PAINT	4.0
	FRONT BUMPER COVER NEW PART PAINT K1G	19.0
	RIGHT FLOOR PANEL SURFACE PAINT	6.0

Paint Material Per Part

Code	Description	Price SGD
0471	BONNET NEW PART PAINTING	71.21
0742	R/F WING NEW PART PAINTING	15.48
1482	RIGHT FRONT DOOR NEW PART PAINTING	43.34
1488	R/F UPPER DOOR HINGE SURFACE PAINT	0.25
1496	R/F LOWER DOOR HINGE SURFACE PAINT	0.25
0283	FRONT BUMPER COVER NEW PART PAINT K1G	60.67
4258	RIGHT FLOOR PANEL SURFACE PAINT	11.21

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor	42.00 SGD/h		
Time Paint		80.0	
Preparation Main Work Metal	2.50	25.0	105.00
Preparation Comp. Work Plastic	0.80	8.0	33.60
Total	10 WU/h	113.0	474.60

Material Cost - Paint

New Part Painting

New Part Painting - Plastic K1G

Surface-/Blend Paint

Material-constant Metal Preparation

Material-constant Plastic

Total

Price SGD

130.03

60.67

11.71

28.60

12.70

243.71

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01 Price SGD
0283	FRONT BUMPER COVER	5G0 807 217 BN GRU	Original	CM 650.00 ✓
0292	R/F AIR GUIDE GRILLE	5G0 853 212 E 9B9	Original	PL 20.00 X
0471	BONNET	5G0 823 031 J	Original	R 850.00 X
0476	RIGHT BONNET HINGE	5G0 823 302 B	Original	R 55.00 X
0562	RIGHT HEADLAMP ASSY	5G2 941 006 E	Original	CM 300.00 ✓
0638	R/F FOG LAMP	5G0 941 662 J	Original	R 120.00 X
0742	R/F WING	5G0 821 106 A	Original	R 265.00 ✓
0762	R/WING STRUT	5G0 821 136 B	Original	011 28.00 ✓
0792	R/FR NUT	N 908 173 02		0.00
0842	R/F W-HOUSE RR COVER	5G0 805 970 N	Original	CM 100.00 ✓
0844	R/F W-HOUSE FRT CVR	5G0 805 912 L	Original	CM 65.00 ✓
0990	R/LOCK CARRIER STRUT	5G0 805 932	Original	R 35.00 X
1420	R/F SIDE WINDOW	5G0 845 412 E NVB	Original	D.Y 100.00 ✓
1424	R/F S-WINDOW GLUE	D 169 300 M1		0.00
1425	FRT S-WINDOW PRIMER	D 009 200 02		0.00
1482	RIGHT FRONT DOOR	5G4 831 056 AS	Original	R 950.00 ✓
1488	R/F UPPER DOOR HINGE	8K0 831 402 D	Original	70.00 7
1496	R/F LOWER DOOR HINGE	8K0 831 402 D	Original	70.00 7
1506	R/F DOOR CHECK	5G0 837 249 D	Original	R 55.00 X
1736	R/DOOR MIRROR COVER	5G0 857 538 E GRU	Original	M1 75.00 ✓
1738	R/DOOR MIRROR	5G2 857 508 BG 9B9	Original	250.00 7
1744	R/DOOR MIRROR GLASS	5G0 857 522 A	Original	R 95.00 X
2140	R/OUTER SILL PANEL	5G4 809 378	Original	R 500.00 ✓
2266	R/INNER A-PILLAR	5G2 802 124	Original	I 185.00 7
2270	R/LWR A-PILLAR REINF	5G0 809 204 B	Original	400.00 7
4325	PASSENGER AIRBAG	8V0 880 204 M	Original	Perth 2,000.00 ✓
4331	INSTRUMENT PANEL	5G2 857 003 M HR6	Original	Tn 2,750.00 ✓
4351	KNEE AIRBAG	5G2 880 842 D	Original	Perth 700.00 ✓
4611	L/F AIRBAG SENSOR	5Q0 959 354 A	Original	R 150.00 ✓
4612	R/F AIRBAG SENSOR	5Q0 959 354 A	Original	R 150.00 ✓
4653	L/F SEAT BELT LOCK	5G4 857 755 C YLZ	Original	Tn 150.00 ✓
4654	R/F SEAT BELT LOCK	5G4 857 756 B QVZ	Original	Tn 150.00 ✓
4661	L/F SEAT BELT	5G4 857 705 N RAA	Original	Tn 700.00 ✓
4662	R/F SEAT BELT	5G4 857 706 N RAA	Original	Tn 700.00 ✓

Code	Description	Part Number	Part Source	Price SGD
7011	ASSEMBLY CARRIER	5WA 199 315 F	Original	500.00 ?
7036	R/DRIVE SHAFT CPL	5Q0 407 272 FG	Original	1,000.00 ✓
7048	R/F TRACK CONT ARM	5WA 407 152	Original	185.00 ✓
7062	R/F GUIDE JOINT	5Q0 407 366 A	Original	65.00 ✓
7082	R/WHEEL BEARING HSG	5Q0 407 256 R	Original	385.00 ✓
7088	R/FR SHOCK ABSORBER	5Q0 413 023 FH	Original	185.00 ✓
7092	R/F SPRING LEG BRG	5Q0 412 331 E	Original	65.00 ✓
7096	R/F S-ABSORB BRACKET	5Q0 412 249 E	Original	25.00 ✓
7132	R/F WHEEL HUB/BRG	8V0 498 625	Original	300.00 ✓
7134	R/F COVER PANEL	5Q0 615 312 G	Original	40.00 ✓
7142	R/F BRAKE DISC	5Q0 615 301 H	Original	110.00 ✓
7156	R/CALIPER HOUSING	8V0 615 124	Original	325.00 ✓
7166	R/F BRAKE HOSE	5Q0 611 701 C	Original	150.00 ✓
7180	FRONT BRAKE PAD SET	8V0 698 151	Original	125.00 ✓
7202	R/F WHEEL	5G0 601 025 8Z8	Original	600.00 ✓
7246	R/F SPEED SENSOR	WHT 003 860	Original	75.00 ✓
7250	R/F SENSOR CABLE	5G0 927 903 AA	Original	175.00 ✓
7261	FRONT STABILISER	5Q0 411 303 Q	Original	240.00 ✓
7278	R/ANTI-SQUAT ROD	5Q0 411 315 A	Original	60.00 ✓
7300	POWER STEERING	5Q2 423 055 L	Original	3,250.00 ✓
7310	R/TIE ROD	1K0 423 810 A	Original	65.00 ✓
7312	R/TIE ROD BALL JOINT	1K0 423 812 J	Original	75.00 ✓
7435	ELECTRONIC UNIT	5Q0 953 549 E	Original	550.00 ✓
7441	AIRBAG CONTROL UNIT	5Q0 959 655 AA	Original	950.00 ✓
7445	DRIVER AIRBAG	5G0 880 201 S	Original	1,400.00 ✓
8771	ENGINE PROTECTION	81U	Original	140.00 ?
f: OEM Parts				Savings 0.00
n: Non-OEM Parts				Subtotal 23,728.00
u: Used parts				Fixed Sundry Parts Price 100.00
Total				23,828.00

Extras

Code	Description	Price SGD
1000	RH QTR GLASS SEALANT RH QTR GLASS	40.00*
1001	RH QTR GLASS IN SEAL RH QTR GLASS	27.00* 200
1002	RH FRONT TYRE RH FRONT TYRE	190.00*
1003	BRAKE OIL BRAKE	20.00*
1004	Electrical work Electrical work	25.00*
1005	Wheel alignment Wheel alignment	60.00*
1006	AIRBAG PROGRAMMING AIRBAG	380.00*
Total Extras		742.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Final Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	23,728.00	
	100.00	
Total Parts		23,828.00
Labour Time Base 10 WU/h		
Total 345.0 WU X 42.00 SGD/h	1,449.00	
Alignment		
Measuring Work	42.00	
Total of Labour		1,491.00
Total Of Extras		742.00
Paint Work Time Base 10 WU/h		
Labour Cost 113.0 WU X 42.00 SGD/h	474.60	
Material Cost	243.71	
Total Paint Including Material		718.31
Repair Cost Excludes GST		26,779.31
GST (+7.0%)		1,874.55
Repair Cost Included GST		28,653.86

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:

Singapore NRIC

Owner ID:

033H

Vehicle Details

Vehicle No.:

SMD8063R

Vehicle to be Exported:

Yes

Intended Deregistration Date:

24 Jan 2022

Vehicle Make:

VOLKSWAGEN

Vehicle Model:

GOLF A7 1.4 TSI AT 5G13GZ W/O HID

Primary Colour:

Red

Manufacturing Year:

2014

Engine No.:

CXS213274

Chassis No.:

WVWZZZAUZFW015241

Maximum Power Output:

90.0 kW (120 bhp)

Open Market Value:

\$20,784.00

Original Registration Date:

08 Sep 2014

First Registration Date:

08 Sep 2014

Transfer Count:

1

Actual ARF Paid:

\$6,098.00

Intended PARF Rebate Details

PARF Eligibility:

Yes

PARF Eligibility Expiry Date:

07 Sep 2024

PARF Rebate Amount:

\$3,658.00

Intended COE Rebate Details

COE Expiry Date:

07 Sep 2024

COE Category:

A - Car up to 1600cc & 97kW (130bhp)

COE Period(Years):

10

QP Paid:

\$60,002.00

COE Rebate Amount:

\$15,730.00

Total Rebate Amount:

\$19,388.00

The information contained herein is correct as at 24 Jan 2022

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 24/01/2022 14:13 (SGT)
Date of Accident 17/01/2022 02:45 (SGT)
Exact Location of Accident PIE, Singapore
Additional Location Information ENTER BKE/SLE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMD8063R

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner NG WEI SIANG (HUANG WEIXIANG)
NRIC No S8722033H
Email Address dannyingws@gmail.com
Mobile Phone No (Phone) +65-91815944
Alternative Phone No +65-91815944

VEHICLE PARTICULARS

Manufacturer Volkswagen
Model Golf
Variant -
Exact purpose for which vehicle was being used at time of accident Private use
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car
Transmission Auto
CC 1395

INSURANCE COMPANY

Name of Insurance Company China Taiping Insurance (Singapore) Pte. Ltd.
Type of Coverage Comprehensive
Fleet Policy No
Policy Number DMPCSNW00171382102
Cover Note Number -

DRIVER

Name of Driver NG WEI ZHONG, ROYSTON
NRIC No S9019424J