



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CS3/CTI21011539/Evy3n2-1 Date: 28/03/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)				
Insured Veh.	PC 4310Z	Veh. Inspected	FBJ 8578X	
Policy No.	DMB1SNW00011792100	Coverage (\$)	0.00	
Claim No.	SNM21D206268/C02	Excess (\$)	0.00	
Assign From	CECILIA LEE PENG GEOK	Assign Date	28/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW R1200GS	c.c	1170	
Engine No.	HIDDEN	Year of Reg.	2014	
Chassis No.	WB10A0200EZ208096	Colour	WHITE	
Odometer	93270 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	120/70ZR19	CONTINENTAL	4 mm	
L/H Front Tyre			mm	
R/H Rear Tyre	170/60 ZR17	CONTINENTAL	4 mm	
L/H Rear Tyre			mm	
4. Description of Damages				
THE VEHICLE HAD COMPLETED ITS REPAIR WORKS. REPAIR CONDITION SEE DETAILS.				
5. General Information				
Accident Date	30/10/2021	Inspection Date	14/03/2022	
Survey held at	BLK 1008 BUKIT MERAH LANE 3, #01-14			
Repairer	SPEEDWAY MOTOR PL			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			8 Working Days	