

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001018/GQY3M4**Date:** 29/03/2023REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMCVSNA00154542100

**Claimant Vehicle
No :** SLP1327A**Insured Vehicle
No :** YP5020D

Date of Loss: 25/01/2022

Nature of Claim: TP

Claim
No: SNM22D200710/C02/LEEPGDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLP1327A**Make & Model: PEUGEOT 308, 1.2 5DR ALLURE PURETECH
A/T 2WD S/R (A)

Engine No: 10XTA40402805

Reg. Date: 26/05/2017 (Man. Year: 2016)

Chassis No: VF3LPHNYWGS197226

Colour: Black

Odometer: 28292 km

Engine Capacity: 1199 cc

Market Value/New Car
Price: N/ASum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17

Rear Tyre Size: 225/45 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,833.02	3,232.13	11,600.89	78.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,880.00	1,470.00	1,410.00	48.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	17,713.02	4,702.13	13,010.89	73.45
Approved Total (Overridden) (S\$)		3,750.00		
(S\$)	17,713.02	3,750.00	13,963.02	78.83
+ GST 8.00/8.00% (S\$)	1,417.04	300.00	1,117.04	78.83
Nett Amount (S\$)	19,130.06	4,050.00	15,080.06	78.83

INSPECTION

Date of Assignment: 28/01/2022

Date Inspected: 07/02/2022

Inspected At:

Hs Automotives Pte Ltd (HQ)
Blk 2 Kaki Bukit Ave 2, #02-25
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: XING GUO QIANG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 29 Mar 2023)	
Parts:	N/A	PEUGEOT 308 1.2 5DR ALLURE PURETECH A/T 2WD S/R (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLP1327A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Cut	1,699.70 F	*1,031.00 FL
2	1		*FRONT BUMPER SENSOR	Not Necessary	233.94 F	*- FL
3	1		*FRONT BUMPER RETAINER	Not Necessary	188.76 F	*- FL
4	1		*LH FRONT FENDER	Buckled	688.75 F	*555.00 FL
5	1		*LH FRONT FENDER INNER SHIELD	Not Necessary	200.97 F	*- FL
6	1		*LH FRONT HEAD LAMP	Not Necessary	3,600.97 F	*- FL
7	1		*LH FRONT HEAD LAMP LOWER BRACKET (NPA)	Not Necessary	0.00 F	*- FL
8	1		*LH FRONT DOOR	Repair	1,997.30 F	*- FL
9	2		*LH FRONT DOOR HINGE	Not Necessary	377.86 F	*- FL
10	1		*LH FRONT DOOR WEATHER STRIP (NPA)	Not Necessary	0.00 F	*- FL
11	1		*LH FRONT SIDE MIRROR }	Distorted	1,976.60 F	*750.00 FL
12	1		*LH FRONT SIDE MIRROR COVER }		-	-
13	1		*LH FRONT SIDE MIRROR GLASS }		-	-
14	1		*LH FRONT LOWER ARM	Not Necessary	489.70 F	*- FL
15	1		*LH FRONT SHOCK ABSORBER (NPA)	Not Necessary	0.00 F	*- FL
16	1		*LH FRONT SHOCK ABSORBER MOUNTING (NPA)	Not Necessary	0.00 F	*- FL
17	1		*LH FRONT WHEEL KNUCKLE	Not Necessary	999.87 F	*- FL
18	1		*LH FRONT WHEEL BEARING	Jammed	499.70 F	*499.70 FL
19	1		*LH FRONT LINKAGE ROD (NPA)	Not Necessary	0.00 F	*- FL
20	1		*LH FRONT SPORT RIM	Cut	1,753.20 F	*700.00 FL
21	1		*LH FRONT TYRE (NPA)	Not Necessary	0.00 F	*- FL
22	1		*FRONT BUMPER CLIP	Necessary	78.40 FS	*30.00 FS
23	1		*LH FRONT FENDER INNER SHIELD CLIP	Necessary	47.30 FS	*20.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	14,833.02	3,585.70
- List Item Discount on L Items 0.00/10.00% (S\$)	0.00	353.57
Total Parts (S\$)	14,833.02	3,232.13

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEAT	New	1,200.00	500.00
2	SPRAY PAINT	New	1,200.00	700.00
3	WHEEL ALIGNMENT	New	100.00	60.00
4	TO REMOVE AND REFIX UNDERCARRIAGE	New	200.00	120.00
5	TO CHECK WIRING	New	80.00	30.00
6	RUST PROOF	New	100.00	60.00
Gross Labour Cost (S\$)			2,880.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >