

JL Perfect Autowork Pte Ltd

Company Reg No: 202136905K

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit
Singapore 415875

Tel : 6341 6789 Fax: 6341 6778
E-mail:jlperfectautowork@gmail.com



DATE : 27.01.2022

TO : **CHINA TAIPING** MOTOR CLAIMS DEPTS
VEHICLE NO : **SMN4841K**
MODEL : **TOYOTA CAMRY**
DATE OF ACCIDENT : 27.01.2022
TIME OF ACCIDENT : 15:00HRS

AXVH 701038450

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>Distorted</i>	1	\$ 625.70	\$ 625.70
2	REAR BUMPER DIFFUSER <i>Distorted</i>	1	\$ 393.50	\$ 393.50
3	REAR BUMPER REFLECTOR <i>New</i>	2	\$ 125.60	\$ 251.20
4	REAR BUMPER CORNER GARNISH RH <i>Red</i>	1	\$ 48.30	\$ 48.30
5	REAR BUMPER SIDE RETAINER (SIDE) <i>HH and</i>	2	\$ 128.30	\$ 256.60
6	REAR BUMPER REINFORCEMENT <i>2M</i>	1	\$ 319.70	\$ 319.70
7	REAR BUMPER REINFORCEMENT BRACKET <i>for</i>	2	\$ 171.20	\$ 342.40
8	REVERSE SENSOR <i>New</i>	2	\$ 417.60	\$ 835.20
9	REVERSE SENSOR HOLDER <i>New</i>	2	\$ 35.20	\$ 70.40
10	REVERSE SENSOR WIRE HARNESS <i>MP</i>	1	\$ 288.10	\$ 288.10
11	TAILLAMP SIDE GARNISH <i>New</i>	2	\$ 30.10	\$ 60.20
12	TAILLAMP LOWER BRACKET <i>New</i>	2	\$ 59.60	\$ 119.20
13	TAILLAMP PANEL LH <i>Repair</i>	1	\$ 241.20	\$ 241.20
14	REAR FENDER LH <i>Distorted LH</i>	2	\$ 1,067.80	\$ 2,135.60
15	REAR FENDER AIR VENT LH <i>New</i>	1	\$ 125.70	\$ 125.70
16	REAR FENDER INNER COWLING <i>torn HH</i>	2	\$ 218.60	\$ 437.20
17	REAR FENDER INNER TRIM <i>New</i>	2	\$ 790.90	\$ 1,581.80
18	REAR DRAIN PANEL LH <i>New</i>	1	\$ 182.30	\$ 182.30
19	REAR DRAIN PANEL COVER GARNISH <i>New</i>	2	\$ 79.60	\$ 159.20
20	BOOTLID <i>New</i>	1	\$ 1,143.70	\$ 1,143.70
21	BOOTLID MOULDING (CENTRE) <i>New</i>	1	\$ 362.40	\$ 362.40
22	BOOTLID NUMBER PLATE LAMP COVER GARNISH <i>New</i>	1	\$ 372.40	\$ 372.40
23	BOOTLID LOGO <i>2</i>	1	\$ 49.80	\$ 49.80
24	BOOTLID EMBLEM 'CAMRY' <i>New</i>	1	\$ 76.20	\$ 76.20
25	BOOTLID EMBLEM 'HYBRID'	1	\$ 59.80	\$ 59.80
26	BOOTLID HINGE <i>New</i>	2	\$ 228.20	\$ 456.40

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMN4841K
 MODEL : TOYOTA CAMRY
 DATE OF ACCIDENT : 27.01.2022
 TIME OF ACCIDENT : 15:00HRS

27	BOOTLID STOPPER	2	\$ 24.80	\$ 49.60	+
28	BOOTLID INSULATOR	1	\$ 549.50	\$ 549.50	+
29	BOOTLID LOCK	1	\$ 339.80	\$ 339.80	+
30	BOOTLID CATCHER	1	\$ 39.41	\$ 39.41	+
31	BOOTLID WEATHERSTRIP	1	\$ 256.40	\$ 256.40	+
32	REAR END PANEL	1	\$ 651.70	\$ 651.70	+
33	REAR END PANEL TOP GARNISH	1	\$ 296.20	\$ 296.20	+
34	REAR FLOOR SIDE PANEL RH	1	\$ 185.75	\$ 185.75	+
35	REAR FLOOR PANEL TOP BOARD	1	\$ 517.20	\$ 517.20	+
36	REAR FLOOR PANEL BOTTOM GARNISH	1	\$ 496.80	\$ 496.80	+
37	REAR FLOOR TOP SPONGE (CENTER)	1	\$ 498.70	\$ 498.70	+
38	REAR SPARE TYRE BOLT	1	\$ 42.10	\$ 42.10	+
39	REAR ABS SENSOR	1	\$ 450.00	\$ 450.00	+
40	REAR SHOCK ABSORBER RH	1	\$ 420.00	\$ 420.00	+
41	REAR STABILIZER BAR RH	1	\$ 450.80	\$ 450.80	+
42	REAR LOWER ARM RH	1	\$ 235.00	\$ 235.00	+
43	REAR ADJUSTABLE ARM RH	1	\$ 680.40	\$ 680.40	+
44	REAR CONTROL ARM RH	1	\$ 370.80	\$ 370.80	+
45	REAR KNUCKLE ARM RH	1	\$ 640.30	\$ 640.30	+
46	REAR STAY ARM RH	1	\$ 679.30	\$ 679.30	+
47	REAR WHEEL HUP RH	1	\$ 845.70	\$ 845.70	+

48 Handbrake Motor. 685 ✓
 49 ABS Pump 3415 +

TOTAL PRICE \$ 19,689.66
 LESS 25% \$ 4,922.42
 SUB TOTAL PRICE \$ 14,767.25

643820
 482865

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE (SPECIAL TYPE)	1	\$ 180.00	\$ 180.00
2	REAR BUMPER CLIPS (SET)	1	\$ 80.00	\$ 80.00
3	REAR BUMPER LOWER SIDE LID(SPECIAL TYPE)	1	\$ 1,800.00	\$ 1,800.00
4	BOOTLID INSULATOR CLIP (SET)	1	\$ 80.00	\$ 80.00
5	TAILLAMP (SPECIAL TYPE)	1	\$ 1,800.00	\$ 1,800.00
6	TAILLAMP CLIPS (SET)	1	\$ 30.00	\$ 30.00
7	TAILLAMP PANEL SEALANT RH	2	\$ 60.00	\$ 120.00
8	PETRO COVER CHROME(SPECIAL TYPE)	1	\$ 180.00	\$ 180.00
9	REAR FENDER SEALANT	2	\$ 150.00	\$ 300.00
10	REAR FENDER COWLING CLIPS (SET)	1	\$ 80.00	\$ 80.00
11	REAR FENDER INNER TRIM CLIPS (SET)	1	\$ 80.00	\$ 80.00
12	REAR DRAIN PANEL COVER GARNISH CLIP (SET)	1	\$ 60.00	\$ 60.00

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
 VEHICLE NO : SMN4841K
 MODEL : TOYOTA CAMRY
 DATE OF ACCIDENT : 27.01.2022
 TIME OF ACCIDENT : 15:00HRS

13	REAR WINDSCREEN SEALANT <i>Nec</i>	1	\$ 80.00	\$ 80.00 <i>40</i>	<i>40</i>
14	REAR WINDSCREEN INNER SEAL <i>Nec</i>	1	\$ 60.00	\$ 60.00 <i>40</i>	<i>40</i>
15	BOOTLID LAMP (SPECAIL TYPE) <i>lit</i>	1	\$ 1,000.00	\$ 1,000.00 <i>400</i>	<i>400</i>
16	BOOTLID SEALANT <i>men</i>	1	\$ 150.00	\$ 150.00	<i>+</i>
17	BOOTLID INSULATOR CLIP (SET) <i>men</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
18	REAR END PANEL INSULATION SEAL <i>Heur</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
19	REAR END PANEL TOP CHROME (SPECIAL TYPE) <i>Heur</i>	1	\$ 480.00	\$ 480.00	<i>+</i>
20	REAR FLOOR SIDE PANEL SEALANT <i>AP</i>	1	\$ 180.00	\$ 180.00	<i>+</i>
21	REAR FLOOR PANEL BOTTOM GARNISH CLIP (SET) <i>AP</i>	1	\$ 80.00	\$ 80.00	<i>+</i>
22	REAR EXHAUST CHROME PIPE (SPECIAL TYPE) <i>Heur</i>	1	\$ 350.00	\$ 350.00	<i>+</i>
23	TRIANGLE BREAKDOWN SIGN <i>Heur</i>	1	\$ 180.00	\$ 180.00	<i>+</i>
24	REAR WHEEL RIM (SET) <i>lit</i>	1	\$ 2,800.00	\$ 2,800.00 <i>800.</i>	<i>800.</i>
25	REAR WHEEL TYRE <i>Heur</i>	1	\$ 480.00	\$ 480.00	<i>+</i>
<i>2780</i>			TOTAL	\$ 10,790.00	

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,400.00	<i>700</i>
2	TO SPRAY PAINT AFFECTED AREA	\$ 2,200.00	<i>700</i>
3	TUFF COAT	\$ 250.00	<i>60</i>
4	WIRING CHECK	\$ 180.00	<i>30</i>
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	\$ 250.00	<i>60</i>
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 80.00	<i>50</i>
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 80.00	<i>x</i>
8	REMOVE AND REFIX REAR WINDSCREEN GLASS	\$ 120.00	<i>✓</i>
9	TRANSFER BOOTLID MECHANISM	\$ 80.00	<i>x</i>
10	CONDUCT WATER LEAKAGE TEST	\$ 80.00	<i>x</i>
11	REMOVE AND REFIX REAR UNDERCARRIAGE	\$ 650.00	<i>780.</i>
12	REMOVE AND REFIX REAR EXHAUST PIPE	\$ 180.00	<i>x</i>

TO : CHINA TAIPING MOTOR CLAIMS DEPTS
VEHICLE NO : SMN4841K
MODEL : TOYOTA CAMRY
DATE OF ACCIDENT : 27.01.2022
TIME OF ACCIDENT : 15:00HRS

13	REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT	\$ 120.00	X
14	REAR CHASSIS ALIGNMENT	\$ 250.00	X
15	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 250.00 180.	X

2080

TOTAL

\$7,170.00

TOTAL PARTS COST : \$ 25,557.25
TOTAL LABOUR COST : \$ 7,170.00
TOTAL REPAIR COST : \$ 32,727.25

Adrian C
2/5 28/01/22.
06 Days.

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

total: 9688.65
4/5: 7.7K.

YOURS FAITHFULLY,

IRENE

SERVICE ADVISOR
IRENE
HP : 8297 9787

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: