

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0069/2022/JT
DATE : 26-Jan-22
WIP : 65022

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian

10 days exclude 2 Sundays

Johnny Boo 16 Mar 22

OWNER'S NAME : MR TAY LIAN CHEOK
ADDRESS : 48 CARPMAEL ROAD
#01-10
SINGAPORE 429974
TELEPHONE : HP +65 96900713
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210155734
VEHICLE NO : **SKN 3300 K**
MODEL CODE : AUDI A5 SB 2.0 TFSI
MODEL YEAR : 28/12/2021
ENGINE NO : DEM 034635
CHASSIS NO : WAUZZZF56NA002936
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Jan-22
PLACE OF ACCIDENT : ALONG NICOLL HIGHWAY

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 3300 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00 \$	480.00
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	400.00 \$	250.00
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$	280.00 \$	280.00
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$	2,200.00 \$	2,200.00
5	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE TO CUT OFF POINT.	S/N \$	280.00 \$	280.00
SUB TOTAL LABOUR CHARGES		:	\$ 3,640.00	\$ 3,490.00



TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 3300 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS	
		c/f		\$	3,490.00
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.(Lock carrier x 3 days - 45)	\$	5,600.00	\$	2,500.00
7	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS FRONT DOOR.	\$	4,000.00	\$	2,200.00
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$	280.00		
9	TO CARRY OUT PRE WHEEL ALIGNMENT.	S/N \$	280.00	\$	280.00
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$	384.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 14,184.00	\$	8,662.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG
MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
1	FRONT BUMPER	1	\$ 2,493.00	\$	1,994.40
2	FRONT BUMPER SECURING STRIP	2	\$ 79.00	\$	63.20
3	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00		
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER	1	\$ 293.00	\$	234.00
5	FRONT BUMPER AIR GUIDE - LH / RH	1	\$ 72.00	\$	57.20
6	FRONT BUMPER CLOSING ELEMENT	1	\$ 293.00		
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00	\$	120.40
8	FRONT BUMPER TRIM - LH	1	\$ 54.00		
9	RADIATOR TRIM - CENTER	1	\$ 127.00		
10	RADIATOR GRILLE	1	\$ 1,881.00		
11	RADIATOR BRACKET	1	\$ 19.00		
12	RADIATOR GRILLE COVER CAP	1	\$ 141.00		
13	FRONT BUMPER FOAM FILLER PIECE	1	\$ 163.00	\$	130.40
14	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	\$	719.20
15	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	\$	32.24
16	FRONT BUMPER BRACKET - LH	1	\$ 254.00		
17	FRONT BUMPER TOP COVER	1	\$ 143.00		
18	CAUTION STICKER	1	\$ 16.00		
19	AIR COND STICKER	1	\$ 9.00		
20	FRONT BUMPER LOCK CARRIER BRACKET	1	\$ 154.00		
SUB TOTAL SPARE PARTS		:	\$ 7,501.00	\$	3,351.04

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>3,351.04</i>
21	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	<i>\$</i>	<i>25.60</i>
22	POP RIVET	4	\$ 4.00	<i>\$</i>	<i>2.88</i>
23	HORN - LH	1	\$ 134.00		
24	HORN SUPPORT - LH	1	\$ 33.00		
25	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 488.00	<i>\$</i>	<i>212.00</i>
26	FRONT PARKING AID SENSOR SEAL RING	4	\$ 10.00	<i>\$</i>	<i>8.00</i>
27	FRONT BUMPER WIRING SET	1	\$ 449.00		
28	FRONT FENDER - LH	1	\$ 1,189.00	<i>\$</i>	<i>951.20</i>
29	FRONT FENDER ATTACHMENT PARTS	1	\$ 55.00		
30	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 83.00	<i>\$</i>	<i>65.84</i>
31	FRONT FENDER BRACKET - LH	1	\$ 41.00	<i>\$</i>	<i>32.72</i>
32	POP RIVET	5	\$ 19.00	<i>\$</i>	<i>15.20</i>
33	FRONT FENDER BRACKET CENTER - LH	1	\$ 55.00		
34	FRONT FENDER BRACKET END - LH	1	\$ 40.00		
35	FRONT FENDER BRACE - LH	1	\$ 132.00	<i>\$</i>	<i>105.20</i>
36	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00		
37	FRONT WHEEL HOUSING LINER - LH	1	\$ 299.00	<i>\$</i>	<i>238.80</i>
38	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS	1	\$ 176.00		
39	FRONT WHEEL SPOILER - LH	1	\$ 82.00	<i>\$</i>	<i>65.12</i>
40	FRONT WHEEL SPOILER LOWER - LH	1	\$ 39.00		
SUB TOTAL SPARE PARTS		:	\$ 3,429.00	<i>\$</i>	<i>5,073.60</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>5,073.60</i>
41	FRONT TRIM BRACKET - LH	1	\$ 27.00		
42	STONE CHIP GUARD - LH	1	\$ 57.00		
43	FRONT FENDER CHROME TRIM - LH	1	\$ 171.00	<i>\$</i>	<i>136.40</i>
44	BONNET	1	\$ 3,491.00		
45	BONNET ATTACHMENT PARTS	1	\$ 128.00		
46	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00	<i>\$</i>	<i>24.24</i>
47	BONNET STRIKER - LH	1	\$ 56.00		
48	BONNET LOCK	1	\$ 228.00		
49	BONNET BOWDEN CABLE CENTER - INNER / OUTER	2	\$ 128.00		
50	BONNET RELEASE CABLE COVER	1	\$ 11.00		
51	FRONT FENDER LEDGE COVER - LONG	1	\$ 40.00	<i>\$</i>	<i>31.44</i>
52	FRONT FENDER LEDGE COVER - SHORT - LH	1	\$ 18.00		
53	HEADLAMPS COVER - LH	1	\$ 49.00	<i>\$</i>	<i>38.64</i>
54	HEADLIGHT MATRIX BEAM - LH	1	\$ 8,172.00	<i>\$</i>	<i>6,537.60</i>
55	HEADLIGHT HOSE	1	\$ 42.00		
56	SPACER	3	\$ 136.00		
57	LIFT CYLINDER - LH	1	\$ 217.00		
58	LIFT CYLINDER BRACKET - LH	1	\$ 17.00	<i>\$</i>	<i>12.88</i>
59	LIFT CYLINDER CORRUGATED PIPE - LH	1	\$ 107.00	<i>\$</i>	<i>85.60</i>
60	LOCK CARRIER	1	\$ 1,127.00	<i>\$</i>	<i>901.60</i>
SUB TOTAL SPARE PARTS		:	\$ 14,315.00	<i>\$</i>	<i>12,842.00</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

				DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		<i>c/f</i>		<i>\$</i>	<i>12,842.00</i>
61	LOCK CARRIER SUPPORT - LH	1	\$ 43.00		
62	CHARGE AIR COOLER	1	\$ 654.00		
63	PRESSURE PIPE	1	\$ 496.00		
64	A/C CONDENSER	1	\$ 683.00		
65	REFRIGERANT LINE	1	\$ 186.00	<i>\$</i>	<i>148.81</i>
66	REFRIGERANT LINE	1	\$ 381.00	<i>\$</i>	<i>304.80</i>
67	REFRIGERANT LINE	1	\$ 277.00	<i>\$</i>	<i>221.60</i>
68	REFRIGERANT PIPE	1	\$ 585.00	<i>\$</i>	<i>468.00</i>
69	REFRIGERANT PIPE BRACKET	1	\$ 9.00		
70	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00	<i>\$</i>	<i>16.32</i>
71	RADIATOR	1	\$ 699.00		
72	RADIATOR FAN RING	1	\$ 277.00		
73	RADIATOR FAN CONTROL UNIT	1	\$ 2,012.00		
74	RADIATOR COOLANT	6	\$ 282.00	<i>\$</i>	<i>225.60</i>
75	RADIATOR AIR GUIDE OUTER - LH	1	\$ 36.00		
76	RADIATOR AIR GUIDE INNER - LH	1	\$ 19.00		
77	RADIATOR AIR GUIDE - UPPER	1	\$ 19.00		
78	RADIATOR AIR GUIDE - LOWER	1	\$ 25.00		
79	NOISE INSULATION	1	\$ 640.00		
80	FRONT DOOR - LH	1	\$ 171.00	<i>\$</i>	<i>136.40</i>
SUB TOTAL SPARE PARTS		:	\$ 7,515.00	<i>\$</i>	<i>14,363.53</i>

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		<i>c/f</i>		<i>\$ 14,363.53</i>
81	FRONT WINDOW SLOT SEAL TRIM STRIP - LH	1	\$ 446.00	
82	FRONT NO PLATE	S/N	\$ 100.00	
83	Add parts		\$ 1,889.00	\$ 1,511.20
84	Add parts		\$ 64.00	\$ 51.20
85	SUNDRIES		\$ 500.00	\$ 43.28
TOTAL SPARE PARTS			\$ 35,759.00	\$ 15,969.21
TOTAL LABOUR CHARGES			\$ 14,184.00	\$ 8,662.00
GRAND TOTAL			\$ 49,943.00	\$ 24,631.21

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-28/02/22



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0069/2022/JT 10-Feb-22 CHANG 1 of 1 SKN 3300 K AUDI A5 SB 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	RETAINER FOR CONTROL UNIT	\$ 64.00	\$ 51.20	
	GRAND TOTAL	\$ 64.00	\$ 51.20	

For Premium Automobiles Pte Ltd

Authorized Signature



Supplementary Estimate-2

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0069/2022/JT 17-Feb-22 CHANG 1 of 1 SKN 3300 K AUDI A5 SB 2.0 TFSI	
Quantity	Description	Unit Price	Amount	
<u>Parts</u>				
1	ALUMINIUM RIM - LH FRONT	\$ 1,889.00	\$ 1,511.20	
	GRAND TOTAL	\$ 1,889.00	\$ 1,511.20	

For Premium Automobiles Pte Ltd

Authorized Signature



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT