

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699

Tel: 6366 2323 Fax: 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

Veron.

GST Reg No. 19-9902271-W


AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0069/2022/JT
10-Feb-22
CHANG
1 of 1
SKN 3300 K
AUDI A5 SB 2.0 TFSI

Quantity	Description	Unit Price	Amount
<u>Parts</u>			
1	RETAINER FOR CONTROL UNIT <i>cracked</i>	\$ 64.00	✓ <i>sls</i>
GRAND TOTAL		\$ 64.00	

For Premium Automobiles Pte Ltd




Authorised Signature

Adrian Ling
sls. 10/02/22.

Total days given : 10 Days.
for repairs

PREMIUM AUTOMOBILES




55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 3300 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 480.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR.	S/N \$ 280.00 ✓	
4	TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM, VACUUM AND REGAS.	S/N \$ 2,200.00	Price Pricing ???
5	TO RENEW LHS FRONT FENDER INNER AIRCON PIPE TO CUT OFF POINT.	S/N \$ 280.00 ✓	
SUB TOTAL LABOUR CHARGES		: \$ 3,640.00	

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 3300 K

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, LHS FRONT FENDER AND BOTH HEADLIGHTS. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. ✓ ✓ ✓	\$ 5,600.00	1000 (Without Lock Carrier) 2250 (With Lock Carrier) <i>sls</i>
7	TO RESPRAY FRONT BUMPER, BONNET, LHS FRONT FENDER AND LHS FRONT DOOR. ✓	\$ 4,000.00	2200
8	TO TOW BACK THE VEHICLE FROM ACCIDENT SCENE.	S/N \$ 280.00	+
9	TO CARRY OUT PRE WHEEL ALIGNMENT.	S/N \$ 280.00	✓
10	TO CARRY OUT PRE/POST DIAGNOSTIC CHECK.	S/N \$ 384.00	152
TOTAL LABOUR CHARGES		: \$ 14,184.00	

Car-in

8/2/22

WIP 65022

Kiam/Hong

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AIG - Adrian

- 7 days

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER Distorted	1	\$ 2,493.00	✓
2	FRONT BUMPER SECURING STRIP Distorted	2	\$ 79.00	✓
3	FRONT BUMPER GRILLE - CENTER new	1	\$ 219.00	✓
4	FRONT BUMPER CLOSING ELEMENT - LOWER CENTER ?	1	\$ 293.00	?
5	FRONT BUMPER AIR GUIDE LH / RH crushed LH	1	\$ 72.00	✓ { S/S
6	FRONT BUMPER CLOSING ELEMENT crushed	1	\$ 293.00	✓ { S/S
7	FRONT BUMPER AIR GUIDE GRILLE - LH	1	\$ 151.00	✓
8	FRONT BUMPER TRIM - LH new	1	\$ 54.00	✓
9	RADIATOR TRIM - CENTER ?	1	\$ 127.00	?
10	RADIATOR GRILLE ?	1	\$ 1,881.00	?
11	RADIATOR BRACKET ?	1	\$ 19.00	?
12	RADIATOR GRILLE COVER CAP new	1	\$ 141.00	✓
13	FRONT BUMPER FOAM FILLER PIECE crushed	1	\$ 163.00	✓ { S/S
14	FRONT BUMPER REINFORCEMENT BEAM Bented	1	\$ 899.00	✓ { S/S
15	FRONT BUMPER GUIDE SECTION - LH Distorted	1	\$ 41.00	✓
16	FRONT BUMPER BRACKET - LH ?	1	\$ 254.00	?
17	FRONT BUMPER TOP COVER new	1	\$ 143.00	✓
18	CAUTION STICKER ?	1	\$ 16.00	✓
19	AIR COND STICKER ?	1	\$ 9.00	✓
20	FRONT BUMPER LOCK CARRIER BRACKET ?	1	\$ 154.00	?
SUB TOTAL SPARE PARTS		:	\$ 7,501.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	FRONT BUMPER SUPPORT - LH / RH <i>LH Dmgd</i>	2	\$ 64.00	32 <i>sls</i>
22	POP RIVET <i>nee</i>	4	\$ 4.00	<i>sls</i>
23	HORN - LH	1	\$ 134.00	?
24	HORN SUPPORT - LH	1	\$ 33.00	?
25	FRONT PARKING AID SENSOR - INNER / OUTER <i>outer missing</i>	2	\$ 488.00	<i>294</i>
26	FRONT PARKING AID SENSOR SEAL RING <i>nee</i>	4	\$ 10.00	✓
27	FRONT BUMPER WIRING SET	1	\$ 449.00	?
28	FRONT FENDER - LH <i>Bent</i>	1	\$ 1,189.00	✓
29	FRONT FENDER ATTACHMENT PARTS <i>nee</i>	1	\$ 55.00	+
30	FRONT FENDER CLOSING ELEMENT - LH <i>nee</i>	1	\$ 83.00	✓
31	FRONT FENDER BRACKET - LH <i>nee</i>	1	\$ 41.00	✓
32	POP RIVET <i>nee</i>	5	\$ 19.00	✓
33	FRONT FENDER BRACKET CENTER - LH	1	\$ 55.00	?
34	FRONT FENDER BRACKET END - LH <i>nee</i>	1	\$ 40.00	+
35	FRONT FENDER BRACE - LH <i>Best</i>	1	\$ 132.00	✓ <i>sls</i>
36	FRONT FENDER CLOSING ELEMENT - LH	1	\$ 37.00	?
37	FRONT WHEEL HOUSING LINER - LH <i>Bent</i>	1	\$ 299.00	✓
38	FRONT WHEEL HOUSING LINER ATTACHMENT PARTS <i>nee</i>	1	\$ 176.00	+
39	FRONT WHEEL SPOILER - LH <i>torn</i>	1	\$ 82.00	✓ <i>sls</i>
40	FRONT WHEEL SPOILER LOWER - LH	1	\$ 39.00	?


SUB TOTAL SPARE PARTS

: \$ 3,429.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG


MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
41	FRONT TRIM BRACKET - LH ?	1	\$ 27.00 ?	
42	STONE CHIP GUARD - LH <i>new</i>	1	\$ 57.00 <i>T</i>	
43	FRONT FENDER CHROME TRIM - LH <i>new</i>	1	\$ 171.00 ✓	
44	BONNET <i>Rep's</i>	1	\$ 3,491.00 <i>x</i>	
45	BONNET ATTACHMENT PARTS <i>new</i>	1	\$ 128.00 <i>+</i>	
46	BONNET IMPACT PROTECTION - CENTER / LH / RH	3	\$ 93.00 <i>+</i>	
47	BONNET STRIKER - LH	1	\$ 56.00 <i>+</i>	
48	BONNET LOCK	1	\$ 228.00 <i>+</i>	
49	BONNET BOWDEN CABLE CENTER - INNER / OUTER	2	\$ 128.00 <i>+</i>	
50	BONNET RELEASE CABLE COVER	1	\$ 11.00 <i>x</i>	
51	FRONT FENDER LEDGE COVER - LONG <i>cracked</i>	1	\$ 40.00 ✓ <i>sls</i>	
52	FRONT FENDER LEDGE COVER - SHORT - LH ?	1	\$ 18.00	
53	HEADLAMPS COVER - LH <i>cracked</i>	1	\$ 49.00 ✓	
54	HEADLIGHT MATRIX BEAM - LH <i>cracked</i>	1	\$ 8,172.00 ✓	
55	HEADLIGHT HOSE <i>new</i>	1	\$ 42.00 <i>+</i>	
56	SPACER	3	\$ 136.00	
57	LIFT CYLINDER - LH ?	1	\$ 217.00 ?	
58	LIFT CYLINDER BRACKET - LH <i>cracked</i>	1	\$ 17.00 ✓ <i>sls</i>	
59	LIFT CYLINDER CORRUGATED PIPE - LH <i>new</i>	1	\$ 107.00 <i>x</i>	
60	LOCK CARRIER <i>cracked</i>	1	\$ 1,127.00 ✓ <i>sls</i>	
SUB TOTAL SPARE PARTS			\$ 14,315.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 3300 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
61	LOCK CARRIER SUPPORT - LH ?	1 S	43.00 ?	
62	CHARGE AIR COOLER <i>Mer</i>	1 S	654.00 X	
63	PRESSURE PIPE ?	1 S	495.00 ?	
64	A/C CONDENSER <i>Mer</i>	1 S	683.00 +	
65	REFRIGERANT LINE <i>Best</i>	1 S	186.00 ✓	
66	REFRIGERANT LINE <i>Best</i>	1 S	381.00 ✓	
67	REFRIGERANT LINE <i>Best</i>	1 S	277.00 ✓	
68	REFRIGERANT PIPE <i>Best</i>	1 S	585.00 ✓ <i>S.S.</i>	
69	REFRIGERANT PIPE BRACKET ?	1 S	9.00 ?	
70	OUTSIDE TEMPERATURE SENSOR BRACKET <i>Mer</i>	1 S	21.00 ✓ <i>S.S.</i>	
71	RADIATOR <i>Mer</i>	1 S	699.00 +	
72	RADIATOR FAN RING <i>Mer</i>	1 S	277.00 +	
73	RADIATOR FAN CONTROL UNIT	1 S	2,012.00 +	
74	RADIATOR COOLANT <i>Mer</i>	6 S	282.00 ✓ <i>S.S.</i>	
75	RADIATOR AIR GUIDE OUTER - LH ?	1 S	36.00 ?	
76	RADIATOR AIR GUIDE INNER - LH ?	1 S	19.00 ?	
77	RADIATOR AIR GUIDE - UPPER ?	1 S	19.00 ?	
78	RADIATOR AIR GUIDE - LOWER ?	1 S	25.00 ?	
79	NOISE INSULATION ?	1 S	640.00 ?	
80	FRONT DOOR - LH <i>Repairs</i> <i>Mer</i> <i>Chrome Trim</i>	1 S	171.00 ✓	
SUB TOTAL SPARE PARTS		:	\$ 7,515.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.