



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Our Ref :	WH0909
Vehicle No. :	YN2040B
Make & Model :	HINO FD8JPKA

Page No. 1

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
PARTS (LIST ITEMS)				
1	Front windscreen / BR		2282.00	
1	Front windscreen rubber seal / CUT		304.00	
1	Front door window glass LH / BR		532.00	
1	Front door LH / OD		2887.00	
1	Front door upper hinge LH X		198.00	
1	Front door lower hinge LH X		198.00	
1	Front door assist grip assembly LH X / CUT		179.00	
1	Front door window run channel LH / CUT		172.00	
1	Front door window outer lower rubber seal LH / CUT		87.00	
2	Front door side signal lamp LH / CUT		218.00	
1	Front bumper / OD		1405.00	
1	Front bumper lower extension / OD		712.00	
1	Front top corner panel garnish LH / BR		660.00	
1	Side mirror round LH / MIS		141.00	
1	Side mirror LH / MIS		169.00	
1	Side mirror upper stay LH / BT		237.00	
1	Side mirror upper stay cushion LH / MIS		8.00	
1	Side mirror lower stay LH / BR		486.00	
1	Side mirror bracket with motor LH / BR		150.00	
1	Front side lamp LH / MIS		169.00	
1	Step up garnish LH / CUT		348.00	
1	Front door outer pillar LH / OD		647.00	
1	Front door quarter outer panel LH X R		1121.00	
1	Front door side mudguard LH X		195.00	
1	Side mirror lower stay LH cover RH / MIS		15.00	
1	Side mirror lower stay LH cover LH / MIS		15.00	
Part Items Total:			10%	
			13535.00	
			1353.50	
			14888.50	
SPECIAL NETT ITEMS				
1	Side mirror stay nuts LH / MC		15 50.00	
1	Front door pillar panel LH sealant / MC		20 60.00	

1	Front side lamp light bulb LH / N	10	20.00	200
1	IU sticker / N		10.00	
1	Rear construct box with sliding door & rear doors	14000	15000.00	
1	Metal step up assy LH / 00		300.00	
SN Items Total:			15440.00	
Total Parts:			30328.50	

Steve (LKK)
4/2/22, 11:00a

00- M ML
Excess - ?
L/S
by AL by
15 by



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

Contact: 6773 7377 / 8778 3338

ROC NO. & GST REG NO.: (199806235M)

Page No. 2

Our Ref : WH0909
Vehicle No. : YN2040B
Make & Model : HINO FD8JPKA

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	2000.00	1000
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	3400.00	1800 1800
3	To remove and refix wiring system at accident damaged area and check for all electrical proper function	60.00	30
4	To remove and refit/replace Front door LH fitting, trimmings, garnish, window glass and lock mechanism	120.00	50
5	To remove and replace front windscreen	150.00	120
6	To remove and refix passenger seats	200.00	X
7	To remove and replace/refit roots lining & upholster garnish	200.00	80
8	To carried out repair on roof top panel	200.00	X
9	To carried out repair on rear floor panel side railing track LH	200.00	100
Labour Total :		6530.00	
TOTAL (PARTS & LABOUR):		36858.50	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: