



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22001046/Bty3n2	
			Date: 16/02/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6009X	Veh. Inspected	SLZ 8422J
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/01/22/2059	Excess (\$)	0.00
	Assign From	HUA YEN	Assign Date	03/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2015
	Chassis No.	WDD1760422J380356	Colour	RED
	Odometer	129677 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/35 R19	GOODYEAR	4 mm
	L/H Front Tyre	235/35 R19	GOODYEAR	4 mm
	R/H Rear Tyre	235/35 R19	GOODYEAR	4 mm
	L/H Rear Tyre	235/35 R19	GOODYEAR	4 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	26/01/2022	Inspection Date	04/02/2022
	Survey held at	TEAM AUTOPRO PTE LTD 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	