,r	_		
ASS. REC. BY:	3	eve	

REF: CS/CT122001053/ETY3

I KOOT	GIMIENI		
From: Date:	Veh No: SML 6634 Yr Regn: 5/4/19		
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /		
OD (TP) WS/TP RES/OD RES/EVA/INV/MV	Truck / Trailer or		
To Inspect Vehicle No:	Make: Bentley Phing Spur c.o 3993		
at Workshop m/s	Colour Blue A/C: Insured / Std / NI / NA		
of	Sp.Reading 56397 T/Radio: Insured / Std / NI / NA		
Insured:	Eng/No:		
Policy No.	C/No: SCBEE53W6JC070.240		
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt		
Sum Insured: Excess:	Steering: Inforder / Jammed / Leaked / Burnt or		
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or		
Make of Veh:	Modl: NII / SRIM / STD A/RIM or		
	Tyre Size: F: 275/35 2R21		
(Policy Condition)	R: 1/		
Remark: The veh had commenced its · N/S O/S	BS (OUN) EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /		
repair at the time of inspection.	TOYO / YOKO or		
Bal. or Market Value:	Front Rear C		
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 5 mm . R/Bal. 5 mm		
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 5 mm L/Bal. 5 mm		
Est. Repairs: days Res.: Yes or No	D.O.A. 28/122 D.O.I. 4272		
Lum Sum: % 3 Val.: Yes or No	Survey held at Wearnes		
5/15	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or		
CA / REV / REP. / 24 HRS Vehicle: IN/OUT			
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.		
Date / Time Action / Instruction			
MV-580 89788.99			
advising our Principal a cost of repair of			
\$69,292.07 (P/P before GST) - with 5			
days of repair			
1			
RED: 20496.92;22			
ale/Time, File Pass to? : Prell. Report Days Of Repair: 5			
	Resurvey No. of Trip: Survey Fee:		
Transportation:			
Add Fee: :Site Insp (\$)_s+Rs_si			
: Interview (\$) Photos			
Report Format: : Tech. Invs (\$) Others			
Lump Sum / I.B.I: (\$)	:Weekend (\$)		