

## Vehicle Damage Assessment Report for [SKZ2670K]

Estimate Created: 30/11/2022 00:09 by LKK\_admin-a  
(LKK\_Auto\_Consultants\_Pte\_Ltd)

Owned: 19/04/2023 10:25 by LKK\_admin-a (LKK\_Auto\_Consultants\_Pte\_Ltd)

### General Information

Insurance Company	III	Claim Number	MFL2022D0000528
Claim Type	TP		
Workshop	LKK_Auto_Consultants_Pte_Ltd	Reference Number	

### Vehicle Information

Brand	Nissan	Model	Teana
Engine Type			
License Plate Number	SKZ2670K	VIN (or Chassis #)	

### Vehicle Condition

Damaged Diagram	Odometer	98,387.00 Km
	Tyres Condition	
	Front Left	DUNLOP 215/55 R17 6.0 mm
	Front Right	DUNLOP 215/55 R17 6.0 mm
	Rear Left	DUNLOP 215/55 R17 6.0 mm
	Rear Right	DUNLOP 215/55 R17 6.0 mm

### Comments

- FINAL REVIEW BASED ON INFORMATION PROVIDED BY LKK:  
CONCLUDED THE COST OF REPAIR AT \$3,850.00 WITH 6 WORKING  
DAYS

Insurlogic 4 (19/03/2023 15:02)

**Parts**

Description	Number/Type	Qty	Cost	Markup/Disc.%	Sum
Rear boot		1	1080.40	-10.00 %	972.36
Rear boot logo		1	53.20	-10.00 %	47.88
Rear boot emblem Teana		1	65.20	-10.00 %	58.68
Rear boot emblem 20XL		1	65.20	-10.00 %	58.68
Rear boot emblem CVT		1	65.20	-10.00 %	58.68
Rear boot rubber		1	155.00	-10.00 %	139.50
Rear lamp grommet		1	7.50	-10.00 %	6.75
Rear end panel		1	564.90	-10.00 %	508.41
Rear end panel trim		1	155.70	-10.00 %	140.13
Rear end panel trim clips		6	7.50	-10.00 %	40.50
Rear bumper		1	682.70	-10.00 %	614.43
LH Rear bumper sensor outer		1	255.00	-10.00 %	229.50
Rear bumper inforcement		1	534.00	-10.00 %	480.60
Rear bumper reinforcement bracket		2	48.45	-10.00 %	87.21
Rear bumper clips		10	4.00	-10.00 %	36.00

Parts Subtotal 3,479.31

**Labor****Replace/RnR**

Description	Type	Cost	Markup/Disc %	Price
Panel beating	RnR	600.00	0.00 %	600.00
To remove and refix luggage compartment, side garnish, side cover, side trim board and other attachment parts.	RnR	60.00	0.00 %	60.00
To install reverse sensor and check water seepage.	RnR	60.00	0.00 %	60.00
To rush prof affected area.	RnR	40.00	0.00 %	40.00

**Paint**

Description	Paint Type	Cost	Markup/Disc %	Price
Spray painting on the affected areas.	Full spray	600.00	0.00 %	600.00

Labor Rate S\$ 50 / Hour

General Labor Subtotal 760.00

Paint Labor Subtotal 600.00

Labor Subtotal 1,360.00

**Summary**

Repair Cost	4,839.31
Discount(20 %)	(967.86)
	3,871.45
Excess	(0.00)
GST(0.00 %)	0.00
<hr/>	
Grand Subtotal	3,871.45