

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: **(65) 6476 3333**
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

 Tel: **(65) 6272 3892**
 Fax: (65) 6270 8314

 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

28/01/2022

CLAIMS DEPT CASH BILL

Page # :- 1

Veh # :- SKZ2670K

Veh Model :- NISSAN TEANA 2.0XL CVT

Estimate# :- CK422821

Claim # :-

ACC. Date :- 27/01/22

Terms :- C.O.D Days

Remarks :-

Attention :- CB016

No.	Description	Qty	U.Price	Amounts S\$
NET ITEMS :				
1.	REAR BOOT	1	PC 1,229.00	1,229.00
2.	REAR BOOT LOGO	1	PC 94.40	94.40
3.	REAR BOOT EMBLEM "TEANA"	1	PC 94.40	94.40
4.	REAR BOOT EMBLEM "20XL"	1	PC 87.90	87.90
5.	REAR BOOT EMBLEM "CVT"	1	PC 79.00	79.00
6.	REAR BOOT LOCK	1	PC 167.00	167.00
7.	REAR BOOT CATCH	1	PC 88.00	88.00
8.	REAR BOOT RUBBER	1	PC 155.00	155.00
9.	REAR BOOT HINGE LH	1	PC 115.00	115.00
10.	REAR LAMP LH	1	PC 430.00	430.00
11.	REAR LAMP GROMMET	1	PC 7.50	7.50
12.	REAR LAMP PANEL LH	1	PC 310.00	310.00
13.	REAR END PANEL	1	PC 564.90	564.90
14.	REAR END PANEL TRIM	1	PC 155.70	155.70
15.	REAR END PANEL TRIM CLIPS	6	PC 7.50	45.00
16.	REAR BUMPER	1	PC 934.70	934.70
17.	REAR BUMPER SENSOR LH OUTER	1	PC 255.00	255.00
18.	REAR BUMPER SENSOR LH INNER	1	PC 255.00	255.00
19.	REAR BUMPER SPONGE	1	PC 287.40	287.40
20.	REAR BUMPER REINFORCEMENT	1	PC 596.20	596.20
21.	REAR BUMPER REINFORCEMENT BRACKET	2	PC 96.90	193.80
22.	REAR BUMPER SIDE SHIELD LH	1	PC 156.20	156.20
23.	REAR BUMPER RETAINER L+R	2	PC 78.30	156.60
24.	REAR BUMPER CLIPS	10	PC 7.50	75.00
25.	REAR EXHAUST TAIL PIPE	1	PC 929.30	929.30
26.	REAR SPARE TYRE FROME	1	PC 185.00	185.00
27.	REAR SPARE TYRE PANEL (REPAIR)	1	PC	
28.	REAR FENDER LH (REPAIR)	1	PC	
29.	REAR CHASSISMEMBER (REPAIR)	1	PC	
	NET TOTAL S\$			7,647.00
	10% DISCOUNT S\$			-764.70
				6,882.30

LABOUR :

 TO CUT & WELD REAR END PANEL, TO REPAIR REAR
 FENDER LH, REAR FLOOR PANEL, REAR CHASISMEBER
 TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN
 & REALIGN AFFECTED AREAS

840.00

TO SPRAY AFFECTED AREAS

850.00

 TO REMOVE & REFIX LAGGAGE COMPARTMENT
 SIDE GARNISH, SIDE COVER SIDE, SIDE TRIM BOARD
 AND OTHER ATTACHMENT

120.00

 TO INSTALL REVERSE SENSOR & CHECK WATER
 SEEPAGE

80.00

TO RUST PROOF AFFECTED AREAS

60.00

Main Office:

 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: **(65) 6476 3333**
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:

 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722

 Tel: **(65) 6272 3892**
 Fax: (65) 6270 8314

 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

Estimate

28/01/2022

CLAIMS DEPT CASH BILL

 Page # :- 1 143733
 Veh # :- SKZ2670K
 Veh Model :- NISSAN TEANA 2.0XL CVT
 Estimate# :- CK422821
 Claim # :-
 ACC. Date :- 27/01/22
 Terms :- C.O.D Days
 Remarks :-

Attention :- CB016

No.	Description	Qty	U.Price	Amounts S\$
	LABOUR TOTAL S\$			1,950.00


E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 8,832.30

GST @ 7 % 618.26

AMOUNT DUE S\$ 9,450.56

 Customer's Signature/Co. Stamp  MOVA AUTOMOTIVE PTE LTD