



Main Office : No. 22, Jalan Kilang, Singapore 159419
Tel: 6476 3333 Fax: 6271 5891

Service Centre : Block 100B, Bukit Merah Lane 3,
#01-04/06/08/116, Singapore 159722
Tel: (65) 6476 3333 (8 Lines) Fax: (65) 6270 8314
www.mova.com.sg
GST Reg. No: M2-0088864-2

Mova Spray Centre
2K Oven Spray Painting System

Power-M Automotive Pte Ltd
Specialise In Car Air-con Services,
Car Audio & Hi-Fi System.

Hilton Car Rental Centre

Hilton Auto Trading
Dealing In New/Used Cars, Hire Purchase & Insurance.



TP INSURER: India International Insurance Pte Ltd (HQ)
UNKNOWN

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	27/01/2022
Vehicle Reg. No.:	SKX2670K	Driveable?	
Party At Fault:	UNKNOWN		
Make/Model:	NISSAN TEANA, 2.0 XL CVT (A)	Vehicle Reg. Date:	15/01/2016
Vehicle Colour:	WHITE	Chassis No:	MNTBBAL33Z0005524
Engine No:	MR20042195R		
Odometer:	0 KM		
Paint Type:			
Nett Item Discount:	10.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	7		
Present Location:	MOVA AUTOMOTIVE PTE LTD (BUKIT MERAH)		

COST OF CLAIMS

	Amount
Parts	6,882.30
Miscellaneous Items	11.00
Labour	1,950.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	8,843.30
+ GST 7.00% (S\$)	619.03
Nett Amount (S\$)	9,462.33

This claim is handled by: **KEONG**

Generated using Merimen e-Claims Internet Estimation & Adjusting System

DETAILS

Reference
 Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Feb 2022)
 Parts: 143 NISSAN TEANA 2.0 XL CVT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: (Unsubmitted, no print-code for SKX2670K)
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*REAR BOOT <i>HI</i>	10.00	0.00	*1,229.00 FN
2	1		*REAR BOOT LOGO <i>ne</i>	10.00	0.00	*94.40 FN
3	1		*REAR BOOT EMBLEM TEANA <i>ne</i>	10.00	0.00	*94.40 FN
4	1		*REAR BOOT EMBLEM 20XL <i>ne</i>	10.00	0.00	*87.90 FN
5	1		*REAR BOOT EMBLEM CVT <i>ne</i>	10.00	0.00	*79.00 FN
6	1		*REAR BOOT LOCK <i>X</i>	10.00	0.00	*167.00 FN
7	1		*REAR BOOT CATCH <i>X</i>	10.00	0.00	*88.00 FN
8	1		*REAR BOOT RUBBER <i>ne</i>	10.00	0.00	*155.00 FN
9	1		*REAR BOOT HINGES LH <i>X</i>	10.00	0.00	*115.00 FN
10	1		*REAR LAMP LH <i>?</i>	10.00	0.00	*430.00 FN
11	1		*REAR LAMP GROMMET <i>ne</i>	10.00	0.00	*7.50 FN
12	1		*REAR LAMP PANEL LH <i>X</i>	10.00	0.00	*310.00 FN
13	1		*REAR END PANEL <i>bt</i>	10.00	0.00	*564.90 FN
14	1		*REAR END PANEL TRIM <i>de</i>	10.00	0.00	*155.70 FN
15	6		*REAR END PANEL TRIM CLIPS <i>ne</i>	10.00	0.00	*45.00 FN
16	1		*REAR BUMPER <i>de</i>	10.00	0.00	*934.70 FN
17	1		*REAR BUMPER SENSOR LH OUTER <i>ca</i>	10.00	0.00	*255.00 FN
18	1		*REAR BUMPER SENSOR LH INNER <i>ca</i>	10.00	0.00	*255.00 FN
19	1		*REAR BUMPER SPONGE <i>?</i>	10.00	0.00	*287.40 FN
20	1		*REAR BUMPER REINFORCEMENT <i>?</i>	10.00	0.00	*596.20 FN
21	2		*REAR BUMPER REINFORCEMENT BRACKET <i>X</i>	10.00	0.00	*193.80 FN
22	1		*REAR BUMPER SIDE SHIELD LH <i>X</i>	10.00	0.00	*156.20 FN
23	2		*REAR BUMPER RETAINER L+R <i>X</i>	10.00	0.00	*156.60 FN
24	10		*REAR BUMPER CLIPS <i>ne</i>	10.00	0.00	*75.00 FN
25	1		*REAR EXHAUST TAIL PIPE <i>X</i>	10.00	0.00	*929.30 FN
26	1		*REAR SPARE TYRE FROME <i>X</i>	10.00	0.00	*185.00 FN

F=Franchise part. N=NetItemDisc.

Sub Total (\$\$)	7,647.00
- Nett Item Discount on N Items (\$\$)	764.70
Total Parts (\$\$)	6,882.30

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Particulars	Amount
Miscellaneous Items		
1	REAR CHASSISMEMBER (REPAIR)	-
1	REAR FENDER LH (REPAIR)	-
1	REAR SPARE TYRE PANEL (REPAIR)	-
1	OD/TP Case (Insurer)	11.00
Sub Total (\$\$)		11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	TO CUT & WELD REAR END PANEL, TO REPAIR REAR FENDER LH, REAR FLOOR PANEL, REAR CHASSIS MEMBER, TO REMOVE & REFIX DAMAGED PARTS, STRAIGHTEN & REALIGN AFFECTED AREAS	New	600 840.00
2	TO SPRAY AFFECTED AREAS	New	600 850.00
3	TO REMOVE & REFIX LAGGAGE COMPARTMENT, SIDE GARNISH, SIDE COVER, SIDE TRIM BOARD AND OTHER ATTACHMENT PARTS	New	60 120.00
4	TO INSTALL REVERSE SENSOR & CHECK WATER SEEPAGE	New	60 80.00
5	TO RUST PROOF AFFECTED AREAS	New	40 60.00
Gross Labour Cost (\$\$)			1,950.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Rasul
HP 2001 0068
6 days
4/8
21/02/22 @ 1145
Resny after repair