

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS4/AIG22001055/NQY3E2

Date: 03/03/2022

REFERENCE

Insured/Claimant: AH HUAT TRADING PTE LTD Policy No: 2070032176
Date of Loss: 27/01/2022 Nature of Claim: OD Claim No: 4192902740SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **GBF9147X**
Make & Model: TOYOTA PROACE, 1.6 (A) Engine No: BH020006431
Reg. Date: 13/04/2017 (Man. Year: 2016) Chassis No: YARVBBHVBGZ056872
Colour: Silver Odometer: 0 km
Engine Capacity: 1560 cc
Market Value/New Car Price: S\$45,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16 Rear Tyre Size: 215/65 R16
Front Left Side: Habilead 5 mm Rear Left Side: Habilead 6 mm
Front Right Side: Habilead 5 mm Rear Right Side: Habilead 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 04/02/2022

Date Inspected: 04/02/2022 Inspected At:

Kan Fook Sing Motor Workshop (Defu)
No. 61 Defu Lane 12
Singapore 539147

Estimated Period of Repair: 0.0 days

Adjuster: Muhammad Nazril Bin Abdullah

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value :	\$45,000.00
OMV :	\$31,537.00
PARF Rebate (1) :	\$ 0.00
Quota Premium Paid :	\$46,302.00
COE Rebate (2) :	\$24,025.00
Total Rebate (1) + (2) = :	\$24,025.00

The total amount incurred will be Market Value \$45,000.00 minus Total Rebate \$24,025.00 = \$20,975.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >