



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD
C/O JUST LAW LLC
101 CECIL STREET #12-12
TONG ENG BUILDING SINGAPORE 069533

Ref: CS3/CTI21005629/Bvy3n2-1

Date: 08/02/2022

Code: CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBH 4022U	Veh. Inspected	SJJ 291E
Policy No.	BRR/SIC/AL/9423/22	Coverage (\$)	0.00
Claim No.	SNM21D202655/C02/TANKL	Excess (\$)	0.00
Assign From	AMBROSE (JUST LAW LLC)	Assign Date	03/02/2022

2. Vehicle Particulars & Condition

Make & Model	TOYOTA ALLION 1.5	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	NZT2603030080	Colour	BLACK
Odometer	453647 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/70 R14	DUNLOP	5 mm
L/H Front Tyre	185/70 R14	DUNLOP	5 mm
R/H Rear Tyre	185/70 R14	DUNLOP	4 mm
L/H Rear Tyre	185/70 R14	DUNLOP	4 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/05/2021	Inspection Date	18/05/2021
Survey held at	BLK 14 #01-19 SECTOR B, SIN MING IND EST		
Repairer	HIAP LEK AUTOMOBILE TRADING		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**