

Parts and Labour Assessment

Report No: 0058-21-HLm Vehicle No: SJJ291E

2008

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Front door RH	1	dented	1154.00	1,306.36 ✓
Front door frame black sticker long RH	1	necessary	95.00	118.10 NECV
Front door frame black sticker vertical RH	1	necessary	48.00	78.20 NECV
Front door side mirror assy RH	1	broken	645.00	658.10 BRU
Front door side mirror cover RH	1	fractured		66.90 BRU ✓
Front door quarter garnish RH	1	deformed		83.70 CUT ✓
Front door glass outer moulding RH	1	cut		126.00 NNX
Front door weatherstrip RH	1	necessary		129.00 NDX
			<u>2092.60</u>	
			<u>523.15</u>	
			<u>1569.45</u>	
			Subtotal before discount	2,566.36
Percentage discount	0%	and	25%	0.00
				641.59
			Sub-total 1	2,566.36
				1,924.77
Tweeter	1	shorted		150.00 NDX
			Subtotal before discount	150.00
Percentage discount	0%	and	0%	0.00
				0.00
			Sub-total 2	150.00
				150.00
			Parts-total	2,716.36
				2,074.77

LABOUR

1. To straighten and panel beating front RH door pillar and front RH frame members. To remove, transfer and refit front RH door components.	600.00	300.00	500.00
2. To putty, re-spray painting and polish affected areas.	700.00	300.00	600.00
3. To check and rectify wiring system.	80.00		50.00 NNX
4. To rust proof affected areas.	90.00	30.00	60.00 ✓
	Labour total	1,470.00	1,210.00
	Parts & Labour total	4,186.36	3,284.77

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :
and the recommended number of working days for the repairs is :

\$2,600.00

3

B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Lump sum repair
Repair days 3

Parts 1569.45
SN -
Labour 630.00
2199.45
439.89
1759.56

LS 1750.2

T. Lim
4/2/2022