



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:YVONNE		Ref: CC4/ASM22001057/Dpa3q2 Date: 20/12/2022 Code: ASM	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHA 9154E	Veh. Inspected	SHA 8114C
Policy No.	P2465703	Coverage (\$)	0.00
Claim No.	S2M03SHM	Excess (\$)	0.00
Assign From		Assign Date	04/02/2022
2. Vehicle Particulars & Condition			
Make & Model	HYUNDAI I40	c.c	1685
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	KMHLB41UMHU097120	Colour	YELLOW
Odometer	569984 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	205/60 R16	WEST LAKE	5 mm
L/H Front Tyre	205/60 R16	WEST LAKE	5 mm
R/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
L/H Rear Tyre	205/60 R16	WEST LAKE	5 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	31/01/2022	Inspection Date	04/02/2022
Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	