

FRONT SUSPENSION LOWER ARM (LH/RH) <i>HN</i>	1	\$ 595.90	\$595.90
FRONT SHOCK ABSORBER ASSY (LH/RH) <i>HN</i>	1	\$ 684.40	\$684.40
STG TIE ROD (LH/RH) <i>HN</i>	1	\$ 186.40	\$186.40
STG TIE END (LH/RH) <i>HN</i>	1	\$ 125.20	\$125.20
SUB TOTAL			\$26,381.80
LESS 20%			\$5,276.36
DISCOUNTED TOTAL			\$21,105.44
REAR FENDER ADVERTISEMENT LOGO (RH) <i>HCC SN</i>	1	\$ 120.00	\$120.00
REAR WINDSCREEN SEALANT <i>HCC</i> SN	1	\$ 46.00	\$46.00
REAR DOOR TEL NO. STICKER (RH) <i>HCC HF</i> SN	1	\$ 10.00	\$10.00
Rear Door Comfortdelgro & Apps Sticker(RH) <i>HCC</i> SN	1	\$ 80.00	\$ 80.00
REAR DOOR ADVERTISEMENT LOGO (RH) <i>HCC</i> SN	1	\$ 100.00	\$100.00
ROCKER PANEL ADVERTISEMENT(RH) <i>HCC</i> SN	1	\$ 120.00	\$ -
REAR TYRE (RH) <i>Cut 50% depreciation</i> SN	1	\$ 216.00	\$216.00
FRONT FENDER ADVERTISEMENT LOGO <i>HCC</i> SN	1	\$ 100.00	\$100.00
FRONT TYRE (RH) <i>HN</i> SN	1	\$ 216.00	\$216.00
SUB TOTAL			\$888.00
Labour Charge			
Panel Beating	1	\$ 1,800.00	\$1,800.00
Spray Painting Charge	1	\$ 1,600.00	\$1,600.00
Wiring Charge	1	\$ 100.00	\$100.00
Tuff Kote	1	\$ 100.00	\$100.00
Towing Charge	1	\$ 80.00	\$80.00
Remove/Refix Cushion & Upholstery Rear	1	\$ 150.00	\$150.00
Remove/Refix Rear Windscreen Glass	1	\$ 120.00	\$120.00
Remove/Refix Reverse Sensor	1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (RR)	1	\$ 400.00	\$400.00
Re-set Rear ABS System	1	\$ 400.00	\$400.00
Remove/Refix Exhaust Pipe	1	\$ 150.00	\$150.00
Transfer of Door Mechanism REAR	1	\$ 80.00	\$80.00
Re-set Rear Power Window System	1	\$ 200.00	\$200.00
Four Wheel Alignment	1	\$ 120.00	\$120.00
Remove/Refix Undercarriage (Frt)	1	\$ 400.00	\$400.00
Re-set Frt ABS System	1	\$ 200.00	\$200.00
Remove/Refix Radiator	1	\$ 90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$ 130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$ 550.00	\$550.00
TOTAL LABOUR			\$6,790.00
ESTIMATE TOTAL			\$ 28,783.44

X
X
X
X
11,976.15
9,580.92
✓
✓
X
✓
✓
✓
108.00
X
674.00

800
800
30
40
HN
80
80
HN
150
HN
HN
60
HN
60
HN
HN
HN
HN
150

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance

04/02/2022 @ 1600hr
 Not Actual
 2/3mm @ 9 days
 ? ryan
 2KK stud
 Check part prices.
 Provide BV
 12,504.92
 1/5 10,000/-