




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: OH VALE			Ref: CS3/ASM22001064/Vvy3e2 Date: 18/02/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SKK 9545Y	Veh. Inspected	SLK 2478S
	Policy No.	GA046308	Coverage (\$)	0.00
	Claim No.	S2M03SAT	Excess (\$)	0.00
	Assign From	OH VALE	Assign Date	04/02/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA COROLLA ALTIS	c.c	1598
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	MR053REH104554333	Colour	GREY
	Odometer	52435 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/45 R17	YOKOHAMA	7 mm
	L/H Front Tyre	215/45 R17	YOKOHAMA	7 mm
	R/H Rear Tyre	215/45 R17	YOKOHAMA	7 mm
	L/H Rear Tyre	215/45 R17	YOKOHAMA	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
5. General Information				
	Accident Date	28/01/2022	Inspect Date / Time	04/02/2022 (05:30 PM)
	Survey held at	SIN HOCK LEE MOTOR REPAIR 51 UBI AVENUE 1 #01-09 PAYA UBI INDUSTRIAL PARK SINGAPORE 408933		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	

Report Ref No. CS3/ASM22001064/Vvy3e2

Inspected By

THEVAN THOMAS KARTHIKESAVAN

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.