

McMassive Trading & Auto

Unit 803B #01-405 Ang Mo Kio Industrial Pk 2 Singapore 669541
 HP 91082728

Ngoo Lay Leng
 Bk 822 Woodlands St 82
 #08-435 Singapore 730822

Vehicle No : SMX 950 C
 Make/Model : Honda Vezel 1.5 X A
 Year : 2019

Fax : 64816131

Not Withheld
11km @ 2000k
Return After Paint
3 days

Qty	Description	Unit Price	Amount
-----	-------------	------------	--------

Estimate Cost Of Repair

1 pc	Rear n/s fender		
1 pc	Rear n/s fender air duct		
1 pc	Rear n/s side bumper	195	
1 pc	Rear n/s fender arch garnish		
1 pc	Rear n/s fender innershield		
1 pc	Rear bumper	889	
1 pc	Rear n/s bumper reflector		
1 pc	Rear bumper under cover		

Return	R	\$987.10	X
	nd	\$105.10	✓
	Bu	\$335.60	✓
	Bu	\$205.10	✓
		\$197.60	✓
	nd	\$855.60	✓
	Bu	\$137.10	X
	CM	\$195.70	✓
		\$3,018.90	
	Less 20 %	\$603.78	
		\$2,415.12	

S Net

1 pc	Rear reverse sensor		
20 pcs	Rear bumper clip		

\$2.00	Sn	\$200.00	X
	M	\$40.00	✓
		\$240.00	

Labour Charges

Remove/renew the above parts including knocking, welding & cutting.

\$1,200.00 *580k*

To putty and spray paint

\$1,000.00 *300k*

Check & reconnect wiring.

\$30.00 *15k*

To respray anti-rust proofing treatment

nn \$100.00 *X*

Remove/refit roof lining to facilitate repair

\$180.00 *780k*

Remove/refit rear boot upholstery to facilitate repair

\$100.00

\$5,265.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: