LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: India International Insurance Pte Ltd

> 64 Cecil Street #04-00 IOB Building Singapore 049711

From: LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park Singapore 408933

Sherini Pillai Date: 04 Feb 2022 Attn:

Preliminary Advice

Vehicle No : YN8749B : 25/01/2022 Accident Date

Make : ISUZU NJR85AUE6W Policy No. : D18MFL0001360 03

Assignment Date : 04/02/2022 **Excess** : S\$0.00 Date of Inspection : 04/02/2022 Est. Duration of Repair : 4

Inspection At : COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)

> 205 BRADDELL ROAD SINGAPORE 579701

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,911.50
Revised Amount	:S\$	1,631.50
Check Items (Estimated)	:S\$	350.00
Total	:S\$	1,981.50

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value	:S\$
-------------------	------

Pre-Accident Value :S\$ 31,000.00 COE / PARF Rebate :S\$ 17,715.00 Salvage Value :S\$

Margin for Repair :S\$ 13,285.00

Remarks

(X)	The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly
	let us have your authorisation.

The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

(X) Other comments: Vehicle repair on lump sum

Kindly advised rear advertisement sticker insured in the policy?

Please note that the preliminary advise amount (Revised & Check items) stated are subject to consistency check, part prices and labour cost.