



Automotive Repair Centre Pte Ltd
CO. Reg. No. : 201312913C
GST Reg. No. : 201312913C

Estimate

48 Toh Guan Road East (Enterprise Hub)
#02-146, Singapore 608586
Tel: 64688834 Fax: 64622278
E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2202-059-TG
DATE : 3-Feb-2022
POLICY NO. : P10317503R02
VEHICLE REG. NO. : SLE3529D
VEHICLE MAKE : MERCEDES / B180 STYLE

TO Motor Claim Department
China Taiping Insurance (Singapore) Pte. Ltd
3 Anson Road, #15-00 Springleaf Tower
Singapore 079909
Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
SPARE PARTS				
Total Spare Parts				\$ -
SPECIAL NETT				
1	Rear Bumper Clips	10	\$ 3.00	\$ 30.00
2	Reverse Sensor	1	\$ 280.00	\$ 280.00
Total Special Nett				\$ 310.00
LABOUR				
3	Spray Painting Rear Bumper	1	\$ 300.00	\$ 300.00
4	Remove and Refit Rear Bumper	1	\$ 300.00	\$ 300.00
5	Remove and Refit Rear Reverse Sensor	1	\$ 80.00	\$ 80.00
6	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 710.00
Amount Before Excess				\$ 1,020.00
Add GST @ 7%				71.40
Total Amount Payable				\$ 1,091.40

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Amount Before Excess

Add GST @ 7%

Total Amount Payable

Steve (LKK)
7/2/22, 3:00pm

W L
P/P
hy AL hy
2 3 djs

P/P-720

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: