



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22001079/Ety3e2	
			Date: 10/03/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 785M	Veh. Inspected	SNB 8504J	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/02/22/2002	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	04/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	LEXUS ES300	c.c	2487	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	JTHB21B1902151159	Colour	WHITE	
Odometer	2301 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45 R18	MICHELIN	5 mm	
L/H Front Tyre	235/45 R18	MICHELIN	5 mm	
R/H Rear Tyre	235/45 R18	MICHELIN	5 mm	
L/H Rear Tyre	235/45 R18	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/02/2022	Inspection Date	04/02/2022	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			12 Working Days	