

Borneo Motors

No. : 196700086Z
 No. : MR-8500000-9
 36 Robinson Road
 #16-01 City House
 Singapore 068877
 Attn: Motor Claims Dept
 Tel no. 6631 1388

LEXUS

SMRT - Hua Yen
 68662650

↓
 Steve LKK @ 83228813

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mdm Toh May Fah Helen 6 Mei Hwan Drive Singapore 568347 Mobile: 96705182		
			Document No.				
			0				
			Document Date				
			03/02/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXZH10R	AEXGB L4	17/09/2021	SNB8504J	0	20626	61TP/SNB8504J/010222
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHB21B1902151159		A25AN342823	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES T/P INS: FIRST CAPITAL ACC DATE: 01.02.2022 T/P VEH: SHB785M DATE IN: DATE SURVEY: DATE AUTHORIZE:				50 / 100.00	
2	B	BP-LAB3 TO REMOVE ALL NECESSARY PARTS TO ENABLE REPAIRING AND STRAIGHTEN ON REAR BUMPER, REAR PANEL, FLOOR PAN, BOOT COVER AND FIX NEW PARTS 866 x 5				4330 / 6062.00	
3	B	BP-RES3 TO SPRAY PAINT ON WHOLE REAR PORTION INCL REAR PANEL, FLOOR PAN AND BOOT SPOILER 6 x 742				4452 / 5936.00	
4	B	BP-LAB3 TO REMOVE AND TRANSFER REAR BOOT SPOILER TO NEW BOOT				216.50	
5	B	BP-LAB3 TO REMOVE AND TRANSFER REAR REVERSE CAMERA TO NEW BOOT				216.50	
6	B	BP-LAB3 TO REMOVE AND TRANSFER BOOT COMPONENT AND MECHANISM TO NEW BOOT (NETT)				433.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

No. : 196700086Z
 No. : MR-8500000-9
 ndan Crescent
 ore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mdm Toh May Fah Helen 6 Mei Hwan Drive Singapore 568347 Mobile: 96705182		
			Document No. 0				
			Document Date 03/02/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXZH10R	AEXGB L4	17/09/2021	SNB8504J	0	20626	61TP/SNB8504J/010222
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHB21B1902151159		A25AN342823	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
7	Z	BP-SLANT SUPPLY BOOT SEALANT (NETT)				100.00	
8	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR LUGGAGE TRIM, GARNISH ETC TO ENABLE REPAIR (NETT)				433.00	
9	B	BP-LAB3 TO CHECK WIRING AND LIGHTS FUNCTIONING AND CARRY OUT WATER LEAK TEST (NETT)				216.50	
10	B	BP-LAB3 TO REMOVE AND REPLACE REAR SENSOR (NETT)				216.50	
11	Z	BP-SLANT SUPPLY REAR PANEL SEALANT (NETT)				100.00	
12	Z	BP-SLANT SUPPLY FLOOR PAN SEALANT (NETT)				100.00	
13	B	BP-LAB3 TO REMOVE AND RE-INSTALL REAR EXHAUST TO ENABLE REPAIR (NETT)				216.50	
14	T	BP-MISC1 SHOULD THE ABOVE VEHICLE BE SUBJECT TO TOTAL LOSS OR TOW OUT BY INSURANCE COMPANY OR BY THE OWNER PRIOR TO THE REPAIR A 6% OF THE QUOTATION PRICE WILL BE IMPOSED AS ADMIN CHARGES TO A MAX OF \$1000 + TOWING CHARGES IF APPLICABLE.					
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

No. : 196700086Z
g No. : MR-8500000-9
andan Crescent
pore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details		Account No.	Customer Details	
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept		S1000005 / ICFIC1	Mdm Toh May Fah Helen	
		Document No. 0	6 Mei Hwan Drive Singapore 568347	
		Document Date 03/02/2022	Mobile: 96705182	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXZH10R	AEXGB L4	17/09/2021	SNB8504J	0	20626	61TP/SNB8504J/010222

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB21B1902151159	A25AN342823	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	Z	BP-MISC2 A DAILY STORAGE CHARGE AT THE RATE OF S\$25/- PER DAY WILL COMMENCE 7 DAYS AFTER ESTIMATE DATE. THESE CHGS WILL NOT APPLY IF REPAIRS ARE UNDERTAKEN BY BORNEO MOTORS.				
16	1	L52105-33020 BUMPER SUB-ASSY, RR <i>GR (chmne)</i>	1.00	717.90		717.90
17	2	L52155-33020 SUPPORT, RR BUMPER <i>GR</i>	1.00	83.00		83.00
18	3	L52156-33020 SUPPORT, RR BUMPER <i>? x nn</i>	1.00	90.90		90.90
19	4	L52157-33040 SUPPORT, RR BUMPER <i>GR</i>	1.00	144.10		144.10
20	5	L52158-33040 SUPPORT, RR BUMPER <i>? x nn</i>	1.00	144.10		144.10
21	6	L89348-50130 RETAINER, ULTRASONIC <i>GR</i>	4.00	19.20		76.80
22	7	L52159-33986 COVER, RR BUMPER <i>GR</i>	1.00	1410.00		1410.00
23	8	S52161-0K040 BUMPER CLIPS <i>GR</i>	17.00	4.30		73.10
24	9	L52197-53040 BRACKET, RR BUMPER <i>GR</i>	1.00	5.90		5.90
25	0	L52171-33170 REINFORCEMENT, RR <i>GR</i>	1.00	782.80		782.80
26	1	L52198-53020 BRACKET, RR BUMPER LH <i>GR</i>	1.00	5.90		5.90
27	2	L52568-33040 RETAINER, RR BUMPER <i>? x nn</i>	1.00	175.40		175.40
28	3	L52581-33010 PROTECTOR, RR <i>? x nn</i>	1.00	196.60		196.60
29	4	L52582-33010 PROTECTOR, RR <i>? x nn</i>	1.00	198.10		198.10
30	5	L52585-33010 INSERT, RR BUMPER <i>? x nn</i>	1.00	26.70		26.70

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less
			Amount Due

Customer Copy

No. : 196700086Z
g No. : MR-8500000-9
andan Crescent
pore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details	Account No.	Customer Details
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept	S1000005 / ICFIC1 Document No. 0 Document Date 03/02/2022	Mdm Toh May Fah Helen 6 Mei Hwan Drive Singapore 568347 Mobile: 96705182

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXZH10R	AEXGB L4	17/09/2021	SNB8504J	0	20626	61TP/SNB8504J/010222

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTHB21B1902151159	A25AN342823	60	Carine Yeo C L	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
31	6	L52586-33010 INSERT, RR BUMPER ? x nn BR	1.00	26.70		26.70
32	7	L52615-33210 ABSORBER, RR BUMPER / nec	1.00	118.90		118.90
33	8	L75895-78030 TAPE, MOULDING, NO.1 / nec	2.00	42.10		84.20
34	9	L52462-33070 PAD, RR BUMPER, RH / nec	1.00	12.20		12.20
35	0	L52463-33070 PAD, RR BUMPER, LH / nec	1.00	14.60		14.60
36	1	L89348-58130 CLIP, ULTRASONIC / nec	4.00	12.60		50.40
37	2	L891B1-33020 BRACKET, KICK DOOR ? x nn BR	1.00	152.30		152.30
38	3	L891B2-06021 SENSOR, KICK DOOR ? x nn	1.00	734.70		734.70
39	4	L84945-33060 SWITCH, LUGGAGE ? x nn	1.00	171.30		171.30
40	5	T58301-33907 PAN SUB-ASSY, RR ? x nn (end M)	1.00	1103.50		1103.50
41	6	L58307-33191 PANEL SUB-ASSY, BODY / CRU	1.00	887.00		887.00
42	7	L64719-33300 C0 COVER, LUGGAGE / BR	1.00	533.10		533.10
43	8	L64779-33290 TRAY, SPARE WHEEL / BR	1.00	274.90		274.90
44	9	L64711-33300 C0 MAT, LUGGAGE / BR	1.00	762.50		762.50
45	0	L58387-33160 C0 PLATE, RR FLOOR / BR	1.00	382.10		382.10
46	1	L62597-33030 BOX, SIDE TRIM ? x nn	1.00	178.60		178.60
47	2	L62599-33010 BOX, SIDE TRIM, LH ? x nn / CRU	1.00	314.80		314.80
48	3	L57628-33140 COVER, RR FLOOR SIDE / CRU	1.00	412.60		412.60
49	4	L64401-33870 PANEL SUB-ASSY, / CRU	1.00	1022.50		1022.50
50	5	L64461-33130 WEATHERSTRIP, / TAI	1.00	267.00		267.00

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy

No. : 196700086Z
g No. : MR-8500000-9
andan Crescent
pore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		Mdm Toh May Fah Helen		
			Document No. 0		6 Mei Hwan Drive		
			Document Date 03/02/2022		Singapore 568347		
						Mobile: 96705182	
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2021	AXZH10R	AEXGB L4	17/09/2021	SNB8504J	0	20626	61TP/SNB8504J/010222
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTHB21B1902151159		A25AN342823	60	Carine Yeo C L	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
51	6	L64510-33271 HINGE ASSY, LUGGAGE	1.00	237.20		237.20	
52	7	L64520-33131 HINGE ASSY, LUGGAGE	1.00	224.70		224.70	
53	8	L64620-30130 STRIKER ASSY, LUGGAGE	1.00	47.10		47.10	
54	9	L64650-33040 CLOSER ASSY, LUGGAGE	1.00	1369.90		1369.90	
55	0	L64713-33070 COVER, LUGGAGE	1.00	101.00		101.00	
56	1	L64714-33060 COVER, LUGGAGE	1.00	101.00		101.00	
57	2	L85790-33020 MOTOR ASSY, LUGGAGE	1.00	3251.90		3251.90	
58	3	L90975-02134 EMBLEM, SYMBOL	1.00	174.60		174.60	
59	4	L75442-33540 PLATE, LUGGAGE COMPT	1.00	84.60		84.60	
60	5	L75447-33200 PLATE, LUGGAGE COMPT	1.00	72.30		72.30	
61	6	L76801-33720 GARNISH SUB-ASSY	1.00	591.90		591.90	
62	7	L81498-33030 COVER, RR	1.00	39.90		39.90	
63	8	L81497-33030 COVER, RR	1.00	39.90		39.90	
64	9	L52563-33050 RETAINER, RR BUMPER	1.00	63.60		63.60	
65	0	L52562-33070 RETAINER, RR BUMPER	1.00	63.60		63.60	
66	1	L81560-33592 LAMP ASSY, RR	1.00	1446.40		1446.40	
67	2	L81550-33592 LAMP ASSY, RR	1.00	1446.40		1446.40	
68	3	L81590-33472 LAMP ASSY, RR, LH	1.00	1123.60		1123.60	
69	4	L81580-33472 LAMP ASSY, RR, RH	1.00	1123.60		1123.60	
70	5	L81910-33040 REFLECTOR ASSY,	1.00	51.70		51.70	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy

No. : 196700086Z
 Reg No. : MR-8500000-9
 Pandan Crescent
 Singapore 128462, Tel no.: 6631 1388

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S1000005 / ICFIC1		Mdm Toh May Fah Helen 6 Mei Hwan Drive Singapore 568347 Mobile: 96705182			
				Document No.					
				0					
				Document Date					
				03/02/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2021	AXZH10R	AEXGB L4	17/09/2021	SNB8504J	0	20626	61TP/SNB8504J/010222		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTHB21B1902151159		A25AN342823	60	Carine Yeo C L	--/--/----		0.00		0.00
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
71	6	L81920-33030 REFLECTOR ASSY, ? x m				1.00	51.70		51.70
<i>Steve (LKK)</i> <i>4/2/22, 1.00%</i> <i>W/L</i> <i>P/P</i> <i>My Runy</i> <i>12 Lys</i> <u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer									
For & on behalf of		Signature:		Customer's Signature		Charge Summary		Total	
Borneo Motors (Singapore) Pte Ltd		Date:						37,688.30	
		Please acknowledge receipt of vehicle 		Parts		23,341.80	GST 7.00%		2,638.18
				Labour		14,346.50	Less		0.00
				Sublet		0.00			
				Lubrication/Fluid		0.00			
				Others		0.00	Amount Due		40,326.48

Customer Copy