

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22001083/BVY3Q2**Date:** 14/03/2022**REFERENCE**

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNW00138812102

Claimant Vehicle No : SLD1639M **Insured Vehicle No :** SMM9398X

Date of Loss: 02/02/2022 Nature of Claim: TP Claim No: SNM22D200795/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLD1639M**

Make & Model: MERCEDES-BENZ A200, 1.3 (A) Engine No: 27091030933155

Reg. Date: 06/06/2016 (Man. Year: 2016) Chassis No: WDD1760432J452260

Colour: White Odometer: 91899 km

Engine Capacity: 1595 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18

Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 5 mm

Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,624.25	6,452.48	11,171.77	63.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,280.00	1,740.00	2,540.00	59.35
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,904.25	8,192.48	13,711.77	62.60
Approved Total (Overridden) (S\$)		6,550.00		
(S\$)	21,904.25	6,550.00	15,354.25	70.10
+ GST 7.00/7.00% (S\$)	1,533.30	458.50	1,074.80	70.10
Nett Amount (S\$)	23,437.55	7,008.50	16,429.05	70.10

INSPECTION

Date of Assignment: 04/02/2022

Date Inspected: 09/02/2022 Inspected At: 160 SIN MING DR #01-14 SIN MING AUTO CITY SINGAPORE 575722

Estimated Period of Repair: 6.0 days Repairer: Team Autopro Pte Ltd (Sin Ming)

Adjuster: Lim Teow Guan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 08 Mar 2022)
Parts:	144	MERCEDES-BENZ A200 1.3 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1639M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Broken	2,350.00 FL	*1,421.00 FL
2	1		*FRONT BUMPER INNER SPONGE	Broken	234.80 FL	*234.80 FL
3	1		*FRONT BUMPER REINFORCEMENT	Not Damaged	650.00 FL	*- FL
4	1		*FRONT BUMPER PARKING SENSOR (RH) (6 PCS)	Scratched (1 PCS ONLY)	1,862.70 FL	*100.00 FL
5	1		*FRONT BUMPER FOG LAMP GARNISH RH	Broken	180.00 FL	*78.00 FL
6	1		*FRONT BUMPER OUTER GARNISH RH	Cut	385.60 FL	*385.60 FL
7	1		*FRONT BUMPER OUTER LOWER GARNISH RH	Cut	310.60 FL	*210.00 FL
8	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	280.00 FL	*- FL
9	1		*FRONT BUMPER SIDE LOWER LIP RH	Cut	410.70 FL	*210.00 FL
10	1		*FRONT BUMPER TOW CAP	Not Necessary	65.00 FL	*- FL
11	1		*FRONT GRILLE	Broken	680.00 FL	*460.00 FL
12	2		*FRONT GRILLE SIDE BRACKET	Not Damaged	91.60 FL	*- FL
13	1		*FRONT SUPPORT PANEL	Broken	952.89 FL	*785.00 FL
14	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	345.20 FL	*- FL
15	1		*FRONT FENDER RH	Bent	1,211.00 FL	*680.00 FL
16	1		*FRONT FENDER INNER COWLING RH	Torn	415.30 FL	*169.95 FL
17	1		*HEADLAMP RH	Cut	2,610.20 FL	*1,569.85 FL
18	1		*HEADLAMP LOWER BRACKET RH	Not Necessary	375.60 FL	*- FL
19	1		*HEADLAMP PANEL RH	Not Necessary	510.50 FL	*- FL
20	2		*HEADLAMP NOZZLE RH	Not Damaged	815.60 FL	*- FL
21	2		*HEADLAMP NOZZLE BRACKET RH	Not Damaged	377.80 FL	*- FL
22	2		*HEADLAMP NOZZLE COVER RH	Cut (1 PCS ONLY)	357.40 FL	*115.00 FL
23	1		*FRONT KNUCKLE ARM RH	Not Damaged	785.30 FL	*- FL
24	1		*FRONT KNUCKLE ARM BEARING RH	Not Damaged	285.60 FL	*- FL
25	1		*SUNDRIES	Not Necessary	80.00 FS	*- FS
26	1		*FRONT BUMPER CLIPS	Necessary	60.00 FS	*30.00 FS
27	2		*FRONT BUMPER SIDE RETAINER	Necessary	197.20 FS	*197.20 FS
28	1		*FRONT BUMPER LOWER LIP CLIPS	Not Necessary	60.00 FS	*- FS
29	1		*FRONT BUMPER FOG LAMP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
30	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
31	1		*FRONT BUMPER PARKING SENSOR SEAL (6 PCS)	Necessary (1 PCS ONLY)	348.00 FS	*58.00 FS
32	1		*FRONT GRILLE CLIPS	Not Necessary	60.00 FS	*- FS
33	1		*FRONT SUPPORT PANEL SEALANT	Not Necessary	100.00 FS	*- FS
34	1		*FRONT SUPPORT PANEL TOP GARNISH CLIPS	Not Necessary	60.00 FS	*- FS
35	1		*FRONT FENDER SEALANT	Necessary	100.00 FS	*30.00 FS
36	1		*FRONT FENDER INNER COWLING CLIPS	Necessary	60.00 FS	*30.00 FS
37	1		*FRONT TYRE	Cut	480.00 FS	*250.00 FS
38	1		*FRONT ALLOY RIM	Not Damaged	890.00 FS	*- FS
39	1		*FRONT NUMBER PLATE	Broken	120.00 FS	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	19,278.59	7,094.40
- List Item Discount on L Items 10.00/10.00% (\$\$)	1,654.34	641.92
Total Parts (\$\$)	17,624.25	6,452.48

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R&R FRONT BUMPER PARKING SENSOR	New	100.00	60.00
2	R&R FRONT UNDER CARRIAGE	New	150.00	0.00
3	R&R FRONT TYRE AND BALANCING	New	100.00	30.00
4	WHEEL ALIGNMENT	New	180.00	0.00
5	DIAGNOTIC RESET FAULT CODE	New	300.00	120.00
6	CHECK WIRING	New	150.00	30.00
7	UPHOLSTERY	New	300.00	0.00
8	PANEL BEATING	New	1,400.00	1,000.00
9	RUST PROOFING	New	200.00	0.00
10	SPRAY PAINTING	New	1,400.00	500.00
Gross Labour Cost (\$\$)			4,280.00	1,740.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >