

AUTOLUTION INDUSTRIAL PTE. LTD.

AUTOLUTION INDUSTRIAL PTE LTD
19 UBI ROAD 4
SINGAPORE 408623
TEL: 6490 9666 FAX: 68467483

ESTIMATE : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0046/2
DATE : 04-FEB-2022

MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
S(068877)
TEL : 65073848
FAX :
ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR RASHEED ABDUL AZEEZ
ADDRESS : BLK 524 BEDOK NORTH ST 3
#12-366
S(460524)
TELEPHONE NO : 96734627

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM
POLICY NO : 21-MS011970-R02
VEHICLE NO : SLV4661H
MODEL CODE : FRLARDWJ11USA--A--
MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017
ENGINE NO : HRA2548051A-J11S
CHASSIS NO : SJNFEAJ11U2151793
MILEAGE : 58072 KM
DATE IN : 04/02/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : ELMER
ACCIDENT DATE : 30/01/2022

- 9645 0084 elmer@tanchong.com

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV4661H

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	ZZ/001	LABOR CHARGES TO RENEW RR END PANEL, HATCHBACK DOOR & RR BUMPER, REPAIR BOTH RR FENDER	1950.00	1800 1170
2	ZZ/002	CHARGES TO SPRAY PAINTING, RR END PANEL, RR BUMPER HATCHBACK DOOR AND BOTH RR FENDER	1250.00	750
3	ZZ/003	RENEW REAR WINDSCREEN GLASS	180.00	180 126
4	ZZ/004	RENEW REAR WINDSCREEN GLASS SOLAR FILM	150.00	150 196
5	ZZ/005	REMOVE AND INSTALL REVERSE CAMERA	120.00	120 40
6	ZZ/006	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	80.00	80 46
7	ZZ/007	APPLY SEALANT TO RR END PANEL AND HATCHBACK DOOR	200.00	100
8	ZZ/008	RENEW BOTH RR COMB LAMP AND CHECK RR WIRING SYSTEM	48.00	/
9	ZZ/009	SUPPLY REAR LICENSE PLATE		
10	ZZ/011	COMPUTER CHECK DIAGNOSIS	120.00	120 60
11	ZZ/10	RENEW REVERSE SENSOR	110.00	110 40
TOTAL LABOUR CHARGES			4208.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV4661H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 LH REFLECTOR RR BUMPER	26565-JJ90A	61.90	7. X SUC	
2 RH REFLECTOR RR BUMPER	26560-JJ90A	61.90	7. X SUC	
3 LH RR HATCHBACK DOOR LAMP	26555-HV55A	231.30	24. X SUC	
4 RH RR HATCHBACK DOOR LAMP	26550-HV55A	231.30	24. - CCA	
5 LH RR COMB LAMP	26555-HV00A	346.90	X SUC	
6 RH RR COMB LAMP	26550-HV00A	346.90	X SUC	
7 ORNAMENT-BACK DOOR OASHQAI	90892-4EA0A	94.40	/NCC	
8 EMBLEM-REAR NISSAN	90890-4EA0A	64.90	/NCC	
9 PLATE-LUGGAGE REAR GARNISH	84992-4EA0A	68.80	X SUC	
10 STRIKER HATCHBACK DOOR	90570-4EA0A	34.80	/BT	
11 HATCHBACK DOOR LOCK	90502-4EA1B	173.20	X SUC, DLS	
12 RUBBER-DUM	62616-89900	63.80	24. - NCC	
13 GLASS-TAIL GATE	90300-HV00A	990.00	/NCC	
14 WEATHER STRIP HATCHBACK DOOR	90830-4EA0B	167.00	7. X SUC	
15 HATCHBACK DOOR CENTER MOULDING	90810-4ES0H	352.00	/SUC	
16 HATCHBACK DOOR	K0100-HV0MB	3062.60	/DT	
17 LH SIDE BRACKET RR BUMPER	85221-4EA0A	38.90	/NCC	
18 RH SIDE BRACKET RR BUMPER	85220-4EA0A	38.90	/NCC	
19 LH STAY RR BUMPER	H5211-4EAMA	141.00	7. X SUC	
20 RH STAY RR BUMPER	H5210-4EAMA	141.00	7. X SUC	
21 REINFORCEMENT RR BUMPER	H5030-4EAMA	691.50	7. - DT	
22 ENERGY ABSORBER RR BUMPER	85090-HV00A	141.40	7. X SUC	
23 TOW HOOK COVER RR BUMPER	85071-HV00A	18.80	X SUC / SUC	
24 CLIP RR BUMPER @ SGD\$1.30 EACH	01553-05933	13.00	/NCC	
25 REAR BUMPER	85022-HV00H	796.70	/CUT	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV4661H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
26 SENSOR-REVERSE	SENSOR			250.00 /lt
27 REAR W/SCREEN SEALANT	SEALANT - 4			80.00 /me
28 SUNDRIES	NPN			50.00 XNW
29 RR END PANEL	G9110-HVOMA	482.60		? Xr
SUB TOTAL		8855.50	0.00	380.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1771.10	0.00	0.00
GRAND TOTAL		7084.40	0.00	380.00
OVERALL TOTAL		7464.40		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLION INDUSTRIAL PTE. LTD.

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO S1V466111

TOTAL LABOUR CHARGES	4208.00
TOTAL SPARE PARTS CHARGES	2464.40
GRAND TOTAL	11672.40 *

* All charges do not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Thuan@LKHauto-lon

82235469

8/2/22 1030

PIP 4 days wp

F: 8489.84

RP: S

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

AUTOLUTION INDUSTRIAL PTE. LTD.

SURVEYOR THE VAN
4 DAYS

FINALIZED : ACCIDENT/BODY REPAIRS

REFERENCE : INS/IC/EA/0046/22

DATE : 04-FEB-2022

MS FIRST CAPITAL INSURANCE LIMITED

36 ROBINSON ROAD

#16-01 CITY HOUSE

S(068877)

TEL : 65073848

FAX :

ATTN:MOTOR CLAIM DEPT

OWNER'S NAME : MR RASHEED ABDUL AZEEZ

ADDRESS : BLK 524 BEDOK NORTH ST 3

#12-366

S(460524)

TELEPHONE NO : 96734627

TYPE OF CLAIM : DIRECT SETTLEMENT / THIRD PARTY CLAIM

POLICY NO : 21-MS011970-R02

VEHICLE NO : SLV4661H

MODEL CODE : FRLARDWJ11USA--A--

MODEL/YEAR : NISSAN QASHQAI 1.2 MY2017

ENGINE NO : HRA2548051A-J115

CHASSIS NO : SJNFEAJ11U2151793

MILEAGE : 59214 KM

DATE IN : 04/02/2022

LIABILITY : 0.00

EXCESS CLAUSE : 0.00

ESTIMATE BY : ELMER

ACCIDENT DATE : 30/01/2022

AUTOLUTION INDUSTRIAL PTE. LTD.

LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLV46614

S/NO JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1 ZZ/001	LABOR CHARGES TO REPAIR RR END PANEL,RENEW HATCH BACK DOOR AND REAR BUMPER	1950.00	1170.00
2 ZZ/002	CHARGES TO SPRAY PAINTING,RR END PANEL,RR BUMPER HATCHBACK DOOR	1250.00	750.00
3 ZZ/003	RENEW REAR WINDSCREEN GLASS	180.00	180.00
4 ZZ/004	RENEW REAR WINDSCREEN GLASS SOLAR FILM	150.00	150.00
5 ZZ/005	REMOVE AND INSTALL REVERSE CAMERA	120.00	120.00
6 ZZ/006	REMOVE AND TRANSFER HATCHBACK DOOR MECHANISM	80.00	80.00
7 ZZ/007	APPLY SEALANT TO HATCHBACK DOOR	200.00	100.00
8 ZZ/008	RENEW BOTH RR COMB LAMP AND CHECK RR WIRING SYSTEM	48.00	48.00
9 ZZ/009	SUPPLY REAR LICENSE PLATE		
10 ZZ/011	COMPUTER CHECK DIAGNOSIS	120.00	120.00
11 ZZ/10	RENEW REVERSE SENSOR	110.00	110.00
TOTAL LABOUR CHARGES		4208.00	2828.00

AUTOLUTION INDUSTRIAL PTE. LTD

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SLV4661H

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES		
		NETT	LIST	S/NETT REMARKS
1 HATCHBACK DOOR	K0100-KV0MB	3062.60		OK
2 HATCHBACK DOOR CENTER MOLDING	90810-4C50H	352.00		OK
3 LH SIDE BRACKET RR BUMPER	85221-4EA0A	38.90		OK
4 RH SIDE BRACKET RR BUMPER	85220-4EA0A	38.90		OK
5 REINFORCEMENT RR BUMPER	H5030-4EAMA	691.50		OK
6 TOW HOOK COVER RR BUMPER	85071-HV00A	18.80		OK
7 CLIP RR BUMPER @ SGD\$1.30 EACH	01553-05933	13.00		OK
8 RH RR HATCHBACK DOOR LAMP	26550-HV55A	231.30		OK
9 ORNAMENT-BACK DOOR QASHQAI	90892-4EA0A	94.40		OK
10 EMBLEM-REAR NISSAN	90890-4EA0A	64.90		OK
11 STRIKER HATCHBACK DOOR	90570-4EA0A	34.80		OK
12 HATCHBACK DOOR LOCK	90502-4EA1B	173.20		OK
13 RUBBER-DUM	G2G16-89900	63.80		OK
14 GLASS-TAIL GATE	90300-HV00A	990.00		OK
15 REAR BUMPER	85022-HV00H	796.70		OK
16 SENSOR-REVERSE	SENSOR		250.00	OK
17 REAR W/SCREEN SEALANT	SEALANT - 4		80.00	OK
SUB TOTAL		6664.80	0.00	330.00
LESS DISCOUNT (NETT-20.00%, LIST-30.00%, S/NETT-.00%)		1332.96	0.00	0.00
GRAND TOTAL		5331.84	0.00	330.00
OVERALL TOTAL		5661.84		

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLV4561H

NETT ITEM	6664.80
LESS 20.00%)	-1332.96
NETT AMOUNT	5331.84
LIST ITEM	0.00
LESS 30.00%)	0.00
LIST AMOUNT	0.00
SPECIAL NETT ITEM	330.00
LESS .00%)	0.00
SPECIAL NETT AMOUNT	330.00
TOTAL LABOUR CHARGES	2628.00
TOTAL SPARE PARTS CHARGES	5661.84
TOTAL CHARGES	8489.84
ADD 7 % GST	594.29
GRAND TOTAL	9084.13

AUTOLUTION INDUSTRIAL PTE. LTD.

SUMMARY OF OVERALL CHARGES FOR VEHICLE REGN NO SLV4561M

NETT ITEM	6664.80
LESS 20.00%	-1332.96
NETT AMOUNT	5331.84

LIST ITEM	0.00
LESS 30.00%	0.00
LIST AMOUNT	0.00

SPECIAL NETT ITEM	330.00
LESS .00%	0.00
SPECIAL NETT AMOUNT	330.00

TOTAL LABOUR CHARGES	2628.00
TOTAL SPARE PARTS CHARGES	5661.84

TOTAL CHARGES	8489.84
ADD 7 % GST	594.29

GRAND TOTAL	9084.13
-------------	---------