



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2207358

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 29/11/2022
Reference CC3/CTI22001093/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHF 778M
Insured Veh. SMK 348K
Claim No. SNM22D200846/C02
Policy No. DMHCSNW00002672101
Accident Date 01/02/2022
Inspection Date 04/02/2022

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERSINGAPORE 079909			Ref: CC3/CTI22001093/Kpa3q2 Date: 29/11/2022 Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SMK 348K	Veh. Inspected	SHF 778M	
Policy No.	DMHCSNW00002672101	Coverage (\$)	0.00	
Claim No.	SNM22D200846/C02	Excess (\$)	0.00	
Assign From		Assign Date	04/02/2022	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1995	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	VF1ABL15AUC283285	Colour	METALLIC WHITE / RED	
Odometer	492949 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	FALKEN	4 mm	
L/H Front Tyre	215/60 R16	FALKEN	4 mm	
R/H Rear Tyre	215/60 R16	SAILUN	8 mm	
L/H Rear Tyre	215/60 R16	SAILUN	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/02/2022	Inspection Date	04/02/2022	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHF 778M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR PANEL REAR RH	BENT	2,844.66	2,844.66
1	DOOR WEATHERSTRIP REAR RH	SERVICEABLE	311.60	-
1	DOOR HANDLE MODULE REAR RH	SERVICEABLE	133.40	-
1	DOOR HANDLE OUTER REAR RH	SERVICEABLE	42.10	-
1	DOOR REGULATOR REAR RH	BENT	450.60	450.60
1	DOOR REGULATOR MOTOR REAR RH	JAMMED	758.10	758.10
1	DOOR HINGE UPPER REAR RH	TO REPAIR SEE LABOUR	241.60	-
1	DOOR HINGE LOWER REAR RH	TO REPAIR SEE LABOUR	169.90	-
1	ROCKER PANEL OUTER RH	BENT	1,184.99	1,184.99
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	1,933.20	-
1	WHEELARCH REAR RH	TO REPAIR SEE LABOUR	275.40	-
	LESS 10% DISCOUNT		-834.56	-523.84
			7,510.99	4,714.51
<u>SPECIAL NETT ITEMS</u>				
1	FENDER CLIP (SN)	NOT NECESSARY	60.00	-
1	DOOR TRIM CLIP (SN)	NOT NECESSARY	70.00	-
1	DOOR SEAL CLIP (SN)	NOT NECESSARY	65.00	-
1	DOOR MOULDING CLIP (SN)	NOT NECESSARY	70.00	-
1	RR DOOR ADVERTISEMENT (SN)	NECESSARY	200.00	160.00
1	DOOR STICKER TRANSCAB (SN)	NECESSARY	100.00	60.00
1	DOOR STICKER 65553333 (SN)	NECESSARY	100.00	60.00
1	DOOR STICKER CLASSIC (SN)	NECESSARY	100.00	15.00
			765.00	295.00
<u>LABOUR</u>				
	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS.		230.00	60.00
	TO TRANSFER OF DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		1,400.00	660.00
	PANEL BEATING, KNOCKING AND STRAIGHTENING THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME. INCLUSIVE OF THE REPAIR OF DOOR HINGE UPPER REAR RH, DOOR HINGE LOWER REAR RH, FENDER PANEL REAR RH AND WHEELARCH REAR RH.		2,000.00	600.00
	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING.	NOT NECESSARY	170.00	-
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
			4,360.00	1,400.00
GRAND TOTAL			12,635.99	6,409.51
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				5,150.00

Report Ref No. CC3/CTI22001093/Kpa3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHF 778M

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

