

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF778M*Not Authorized*
*61 Pp & 5150h***AAD2202-**

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

04 FEB 2022

SHF778M

VF1ABL15AUC283272

200303878K

RENAULT

LATITUDE

01/02/2022

CHINA/SMK348K

30/06/2016

PART

- 1 DOOR PANEL REAR RH
- 1 DOOR WEATHERSTRIP REAR RH
- 1 DOOR HANDLE MODULE REAR RH
- 1 DOOR HANDLE OUTER REAR RH
- 1 DOOR REGULATOR REAR RH
- 1 DOOR REGULATOR MOTOR REAR RH
- 1 DOOR HINGE UPPER REAR RH
- 1 DOOR HINGE LOWER REAR RH
- 1 ROCKER PANEL OUTER RH
- 1 FENDER PANEL REAR RH
- 1 WHEELARCH REAR RH

LIST

\$	<i>B</i>	2,844.66	✓
\$	<i>R</i>	311.60	X
\$	<i>S</i>	133.40	X
\$	<i>L</i>	42.10	X
\$	<i>B</i>	450.60	—
\$	<i>J</i>	758.10	—
\$	<i>R</i>	241.60	X
\$	<i>R</i>	169.90	X
\$	<i>B</i>	1,184.99	✓
\$	<i>R</i>	1,933.20	X
\$	<i>R</i>	275.40	X
TOTAL \$		8,345.55	
10% \$		834.56	
\$		7,511.00	

Special Nett

- 1 FENDER CLIP
- 1 DOOR TRIM CLIP
- 1 DOOR SEAL CLIP
- 1 DOOR MOULDING CLIP
- 1 RR DOOR ADVERTISEMENT
- 1 DOOR STICKER TRANSCAB
- 1 DOOR STICKER 65553333
- 1 DOOR STICKER CLASSIC

\$	<i>nn</i>	60.00	X
\$	<i>nn</i>	70.00	X
\$	<i>nn</i>	65.00	X
\$	<i>nn</i>	70.00	X
\$	<i>nn</i>	200.00	160.00
\$	<i>nn</i>	100.00	80.00
\$	<i>nn</i>	100.00	80.00
\$	<i>nn</i>	100.00	15.00
TOTAL \$		765.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHF778M

AAD2202-

TOTAL PARTS	\$	8,276.00
--------------------	-----------	-----------------

LABOUR

To rust-proofing and apply undercoat of the affected areas.	\$	230.00	601
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	601
Putty and spray painting of the affected portion.	\$	1,400.00	6601
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	2,000.00	6001
To transfer of tire, rim and on wheel balancing.	\$	na 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	201
To check steering geometry and computer wheel alignment	\$	na 220.00	X
TOTAL	\$	4,360.00	
Over All Total	\$	12,636.00	

(LUMPSUM) Repair Days~~20~~ Days

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

is subject to the terms of the Insurance Company's policy and is not guaranteed and

- Such amounts shall not be assigned and
- No withdrawal shall be made from the
- Third party interest in the Insurance Policy
- Part of the proceeds of the Insurance Policy
- To the extent of the proceeds during recovery

the Register of the following:

KK Auto Consultants hence notify