

**Spark Car Care**  
 ComfortDelGro Engineering Pte Ltd  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax:62815767

87492.80

**Spare Parts**

Vehicle No : XE4693M Case Owner : PATRICK

Make & Model : SCANIA P410 XT Year Manufacture : 2019

Chassis No : YS2P4X20005528572 Engine No : DC13141L017124883

Sales Order : \_\_\_\_\_ Supplier : \_\_\_\_\_

Order By : \_\_\_\_\_ Type of Claim : TP

| S/No | Part Description   | QTY | Cost Price | List Price | Nett Price | S/N |
|------|--|-----|------------|------------|------------|-----|
| 1    | RH TAILLAMP ASSY <i>CM ✓</i>                                 | 1   |            | 945.00     | ✓          |     |
| 2    | REAR RH MUD GUARD (REAR) <i>Bu ✓</i>                         | 1   |            | 592.00     | ✓          |     |
| 3    | REAR RH MUD FLAP <i>CM ✓</i>                                 | 1   |            | 139.00     | ✓          |     |
| 4    | REAR RH MUD GUARD SCANIA BADGE <i>PC ✓</i>                   | 1   |            | 139.00     | ✓          |     |
| 5    | REAR RH MUD GUARD (CENTER) <i>Top Bu ✓</i>                   | 1   |            | 398.00     | ✓          |     |
| 6    | REAR RH MUD GUARD RH RUBBER HOOK <i>DIS ✓</i>                | 1   |            | 28.00      | ✓          |     |
| 7    | REAR RH MUD GUARD SUPPORT BAR <i>RR ✓</i>                    | 1   |            | 300.00     | X NN       |     |
| 8    | REAR RH MUD GUARD SUPPORT BAR BRACKET <i>RR ✓</i>            | 1   | BUC        | 1411.00    | ✓          |     |
| 9    | REAR RH MUD GUARD SUPPORT BAR BRACKET BUSH <i>Bu</i>         | 4   |            | 30.00      | X          |     |
| 10   | REAR RH TOP LEAF SPRING <i>RL ✓</i>                          | 1   |            | W 17       | X          |     |
| 11   | REAR RH TOP LEAF SPRING BUSH <i>RL ✓</i>                     | 1   |            | 60.00      | X          |     |
| 12   | REAR RH TOP LEAF SPRING BUSH GREASE NIPPER <i>RL ✓</i>       | 1   |            | 9.00       | ✓          |     |
| 13   | RR RH TOP LEAF SPRING BRACKET <i>RL ✓</i>                    | 1   |            | 300.00     | X          |     |
| 14   | RR RH TOP LEAF SPRING BRACKET HOUSING <i>RL ✓</i>            | 1   |            | 450.00     | X          |     |
| 15   | RR RH TOP LEAF SPRING BRACKET BUSH <i>RL ✓</i>               | 1   |            | 60.00      | X          |     |
| 16   | RR RH TOP LEAF SPRING BRACKET BUST GREASE NIPPER <i>RL ✓</i> | 1   |            | 9.00       | ✓          |     |
| 17   | RR RH LEAF SPRING (1-10) <i>RL ✓</i>                         | 10  |            | 5186.00    | X          |     |
| 18   | RR LH TOP LEAF SPRING <i>RL ✓</i>                            | 1   |            | -          |            |     |
| 19   | RR LH LEAF SPRING (1-10) <i>RL ✓</i>                         | 10  |            | 5186.00    | X          |     |
| 20   | REAR END CHASSIS CENTER PANEL <i>Bu</i>                      | 1   | RL         | 3342.00    | repair     | X   |
| 21   | REAR AIR TANK <i>DD ✓</i>                                    | 1   |            | 735.00     | ✓          |     |
| 22   | REAR AIR TANK SUPPORT BRACKET <i>Bu ✓</i>                    | 1   |            | 1318.00    | ✓          |     |
| 23   | REAR AIR TANK HOSE CONNETOR (SINGLE) <i>Bu</i>               | 1   |            | 59.00      | X          |     |
| 24   | REAR AIR TANK HOSE CONNSTOR (DOUBLE) <i>Bu</i>               | 1   |            | 50.00      | X          |     |
| 25   | AIR RETAINER STRIP <i>mi ✓</i>                               | 1   |            | 170.00     | ✓          |     |
| 26   | AIR RETAINER STRIP RUBBER <i>mi ✓</i>                        | 1   |            | 8.00       | ✓          |     |
| 27   | AIR TANK CONNECTOR RING <i>Bu</i>                            | 2   |            | 22.00      | X          |     |
| 28   | AIR TANK HOSE INSERT UNION <i>Bu</i>                         | 1   |            | 37.00      | X          |     |
| 29   | 0  | 1   |            |            |            |     |
| 30   | 0  | 1   |            |            |            |     |

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

5892

04/02/2022

12:03 PM



**Spark Car Care**  
 ComfortDelGro Engineering Pte Ltd  
 205 Braddell Road S (579701)  
 Tel: 63837168 / 63837466 Fax: 62815767

**Labour**

Vehicle No. : **XE4693M** Case Owner : **PATRICK**  
 Make & Model : **SCANIA P410 XT** Year of Manufacture : **2019**

| S/No | Labour Description  | Estimated Price | Adjusted Price |
|------|---|-----------------|----------------|
| 1    | TO JACK, STRAIGHTEN REAR CHASSIS MEMBER, CROSS MEMBER, REPLACE DAMAGE PARTS AND REALIGNMENT | \$2,800.00      | 2000           |
| 2    | TO REMOVE REAR AXLE, BOTH MULTI LEAF SPRING TO ASSIST REPAIR AND REPLACE DAMAGE PARTS       | \$2,200.00      | X              |
| 3    | TO REMOVE AND REPLACE AIR TANK AND CHECK SYSTEM   | \$100.00        | 80             |
| 4    | TO CHECK LIGHTING AND WIRING  | \$60.00         | 20             |
| 5    | CHECK AND ADJUST WHEEL ALIGNMENT  | \$120.00        | 60             |
| 6    | TO TUFF KOTE ON REAR AFFECTED AREAS   | \$150.00        | 30             |
| 7    | TO REPAIR ON REAR AFFECTED AREAS.   | 600.00          | TBA X          |
|      | TO: Kenneth   |                 |                |
|      | Parts = 5892.00   | 27013           |                |
|      | -10% 589.20   |                 |                |
|      | = 5302.80   |                 |                |
|      | + Labour 2190.00 ✓  |                 |                |
|      | = 7492.80   |                 |                |
|      | 9/5/22  |                 |                |

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.

2190