

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/EG122001099/VVF3N2**Date:** 25/02/2022**REFERENCE**

Handling Insurer: ERGO Insurance Pte. Ltd. Policy No:

Claimant Vehicle No : SHC948E **Insured Vehicle No :** GBB4507U

Date of Loss: 04/02/2022 Nature of Claim: TP Claim No: CDMCG22000220

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHC948E**

Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZRS045018

Reg. Date: 31/05/2017 (Man. Year: 2017) Chassis No: JTDKB3FU603557590

Colour: Yellow Odometer: 576747 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15

Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm

Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,913.15	1,498.70	414.45	21.66
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	620.00	500.00	44.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,033.15	2,118.70	914.45	30.15
Approved Total (Overridden) (S\$)		1,700.00		
(S\$)	3,033.15	1,700.00	1,333.15	43.95
+ GST 7.00/7.00% (S\$)	212.32	119.00	93.32	43.95
Nett Amount (S\$)	3,245.47	1,819.00	1,426.47	43.95

INSPECTION

Date of Assignment: 07/02/2022

Date Inspected: 07/02/2022 Inspected At: ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Estimated Period of Repair: 2.0 days

Adjuster: Thevan Thomas Karthikesavan**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 25 Feb 2022)

Parts: 144 TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SHC948E)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILLAMP UPPER RH	Cracked	557.90 FL	*557.90 FL
2	1		*TAILLAMP LOWER RH	Cracked	548.40 FL	*548.40 FL
3	1		*REAR BUMPER	Distorted	458.60 FL	*458.60 FL
4	1		*REAR BUMPER LOWER COVER	Serviceable	552.60 FL	*- FL
5	1		*REAR BUMPER EXTENSION RH	Distorted	232.00 FL	*232.00 FL
6	1		*REAR BUMPER SIDE RETAINER RH	Necessary	112.70 FL	*112.70 FL
7	10		*REAR BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
8	1		*REAR BUMPER MAT	Necessary	50.00 FS	*50.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,534.20	1,981.60
- List Item Discount on L Items 25.00/25.00% (\$\$)	621.05	482.90
Total Parts (\$\$)	1,913.15	1,498.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING	New	400.00	350.00
2	SPRAY PAINTING CHARGE-REAR FENDER RH	New	600.00	250.00
3	R/I REVERSE SENSORS	New	120.00	20.00
Gross Labour Cost (S\$)			1,120.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >