

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22001101/VTY3Q2**Date:** 09/03/2022**REFERENCE**

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSNW00135612101		
<b>Claimant Vehicle No :</b>	FW9792X	<b>Insured Vehicle No :</b>	GBK7550B		
Date of Loss:	26/01/2022	Nature of Claim:	TP	Claim No:	SNM22D200707/C02/TANCHC

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	FW9792X	Engine No:	E101E076021
Make & Model:	YAMAHA Y125Z, 125cc (M)	Chassis No:	KE1076021
Reg. Date:	28/07/2003 (Man. Year: 2003)	Odometer:	0 km
Colour:	Blue		
Engine Capacity:	125 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

**CONDITION OF TYRES**

Front Tyre Size:	80/90 R17	Rear Tyre Size:	80/90 R17
Front Left Side:	Michelin 5 mm	Rear Left Side:	Michelin 5 mm
Front Right Side:	0 mm	Rear Right Side:	0 mm

*The above values represent the remaining tyre tread depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	6,555.80	1,893.72	4,662.08	71.11
Miscellaneous Items	0.00	0.00	0.00	
Labour	500.00	400.00	100.00	20.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>7,055.80</b>	<b>2,293.72</b>	<b>4,762.08</b>	<b>67.49</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,800.00</b>		
<b>Nett Amount (\$\$)</b>	<b>7,055.80</b>	<b>1,800.00</b>	<b>5,255.80</b>	<b>74.49</b>

**INSPECTION**

Date of Assignment:	26/02/2022	
Date Inspected:	07/02/2022 Inspected At:	SYNERGY@KAKI BUKIT 23, #01-18 KAKI BUKIT RD 4
Estimated Period of Repair:	4.0 days	Repairer:Erzat Lee Motor Trading Pte Ltd (HQ)

**Adjuster:** Thevan Thomas Karthikesavan**Manager:** DENISE TAY KWEE CHENG*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	(Last Synchronised: 07 Mar 2022)	
<b>Parts:</b>	N/A	YAMAHA Y125Z 125cc (M) (Model not available in database)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for FW9792X)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FORK (LOCAL REPAIR)	Necessary	750.00 FS	*120.00 FS
2	1		*FORK UNDER BRACKET	Serviceable	300.00 F	*- FL
3	1		*STEERING CONE	Necessary	250.00 F	*30.00 FL
4	1		*TYRES SHAFT	Serviceable	80.00 F	*- FL
5	1		*SPORT RIM	Repair	450.00 F	*- FL
6	1		*HANDLE BAR	Bent	380.00 F	*200.00 FL
7	1		*HANDLE GRIP	Scratched	50.00 F	*30.00 FL
8	1		*SET MIRROR	Scratched	80.00 F	*80.00 FL
9	1		*IU UNIT	Scratched	155.80 F	*155.80 FL
10	1		*CLUTCH LEVER	Scratched	90.00 F	*90.00 FL
11	1		*FRONT MUDGUARD	Cut	300.00 F	*125.00 FL
12	1		*HEAD COVER	Cut	280.00 F	*250.00 FL
13	1		*HEAD LIGHT	Scratched	250.00 F	*120.00 FL
14	1		*SET SIGNAL LIGHT	Cracked	180.00 F	*80.00 FL
15	1		*FRONT DISC	Serviceable	250.00 F	*- FL
16	1		*LEFT FAIRING COVER	Scratched	400.00 F	*150.00 FL
17	1		*FOOTREST BAR	Bent	350.00 F	*70.00 FL
18	1		*FOOTREST	Bent	200.00 F	*70.00 FL
19	1		*REAR LEFT FOOTREST BAR	Bent	320.00 F	*70.00 FL
20	1		*REAR FOOTREST	Scratched	150.00 F	*70.00 FL
21	1		*REAR LEFT FAIRING	Scratched	380.00 F	*150.00 FL
22	1		*HANDLE COVER	Scratched	280.00 F	*100.00 FL
23	1		*SIDE STAND	Scratched	150.00 F	*50.00 FL
24	1		*MAINSTAND	Scratched	480.00 F	*80.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,555.80</b>	<b>2,090.80</b>
<b>- List Item Discount on L Items 0.00/10.00% (\$\$)</b>	0.00	197.08
<b>Total Parts (\$\$)</b>	<b>6,555.80</b>	<b>1,893.72</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	LABOUR	New	500.00	400.00
<b>Gross Labour Cost (\$\$)</b>			<b>500.00</b>	<b>400.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >