

李 汽 车 贸 易

ERZAT LEE MOTOR TRADING PTE LTD

Synergy@KB 25 Kaki Bukit Road 4

#03-37 Singapore 417800

Reg 201918537M

Office: 69961751

VEHICLE NO: FW 9792 X

VEHICLE MODEL: YAMAHA 125Z

QUOTATION SUMMARY: 1096

CLAIM DETAIL: PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE	Surveyor Recommendation	
1	FORK SET	1	\$750.00	\$750.00	L R 120	SW NEC
2	FORK T-UNDER BRACKET	1	\$300.00	\$300.00	Xsvc	
3	STEERING CONE	1	\$250.00	\$250.00	/ nec	30
4	TYRES SHAFT	1	\$80.00	\$80.00	Xsvc	
5	SPORT RIM	1	\$450.00	\$450.00	Xr	
6	HANDLE BAR	1	\$380.00	\$380.00	✓ BT	200
7	HANDLE GRIP	1	\$50.00	\$50.00	/ scr	30
8	MIRROR SET	1	\$80.00	\$80.00	/ scr	
9	IU UNIT	1	\$155.80	\$155.80	/ scr	
10	CLUTCH LEVER	1	\$90.00	\$90.00	/ scr	
11	FRONT MUDGUARD	1	\$300.00	\$300.00	/ cut	125
12	HEAD COVER	1	\$280.00	\$280.00	/ cut	150
13	HEAD LIGHT	1	\$250.00	\$250.00	/ sw	120
14	SIGNAL LIGHT SET	1	\$180.00	\$180.00	/ crq	80
15	FRONT DISC	1	\$250.00	\$250.00	Xsvc	
16	LEFT FAIRING COVER	1	\$400.00	\$400.00	/ scr	150

17	FOOTREST BAR	1	\$350.00	\$350.00	✓BT	70
18	FOOTREST	1	\$200.00	\$200.00	✓BT	70
19	REAR LEFT FOOTREST BAR	1	\$320.00	\$320.00	✓BT	70
20	REAR FOOTREST	1	\$150.00	\$150.00	✓Scr	70
21	REAR LEFT FAIRING	1	\$380.00	\$380.00	✓Scr	150
22	HANDLE COVER	1	\$280.00	\$280.00	✓Scr	100
23	SIDE STAND	1	\$150.00	\$150.00	✓Scr	50
24	MAINSTAND	1	\$480.00	\$480.00	✓Scr	80
25	LABOUR	1	\$500.00	\$500.00	Uuo	
TOTAL			\$ 7,055.80			

ESTIMATE REPORT
TOTAL PARTS COST : \$ 6,555.80
TOTAL LABOUR COST : \$ 500.00
TOTAL REPAIR COST : \$ 7,055.80

1970.8
1773.72
2293.72
-20% = 1834.97
1800

Thuan

82235769

11/2/22

1300

4/5 4dayswp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

1780.8
1602.72
222.72