



Case Details

Case Reference Number : TAX/01/22/2058
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1217E

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-17348-ID
 Assigned By : Wei Siong #

Insurance Company Name : NTUC Income Insurance Co-operative Ltd
 Accident Date and Time : 26/01/2022 07:07 AM
 Vehicle Age(In Months) : -

Documents / Photographs

View Documents / Photographs

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval			Remarks
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
Standard	Main			FASCIA-RR BPR	1	758.47	758.47	10.00	682.62	Replace	1	0	Repair	
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	1	207.61	Replace	sla
Standard	Main			FINISHER-RR BPR - RH	1	47.42	47.42	10.00	42.68	Replace	0	0	Not Give	Xan
Standard	Main			FINISHER-RR BPR - LH	1	47.42	47.42	10.00	42.68	Replace	1	42.68	Replace	cm
Standard	Main			BRACKET ASM-RR BPR FASCIA SI - RH	1	29.84	29.84	10.00	26.86	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET ASM-RR BPR FASCIA SI - LH	1	29.84	29.84	10.00	26.86	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET-RR BPR FASCIA SI MTG	1	46.07	46.07	10.00	41.46	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH	1	46.08	46.08	10.00	41.47	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - LH	1	13.20	13.20	10.00	11.88	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - RH	1	12.90	12.90	10.00	11.61	Replace	0	0	Not Give	Xan
Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - RH	1	12.80	12.80	10.00	11.52	Replace	0	0	Not Give	Xan

Total Spare Part Cost 1,871.81

Surveyor Total 250.29

Lump Sum Discount (%) 0.00

Lump Sum Dis (%) 0

Final Spare Part Cost 1,871.81

Final Sur Total 250.29

SMRT Recommendation													
Surveyor Approval													
Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
Standard	Main		BRACKET-RR BPR FASCIA LWR MTG - LH	1	12.80	12.80	10.00	11.52	Replace	0	0	Not Give	Xnn
Standard	Main		SCRIVET-RR BPR FASCIA	10	0.84	8.40	10.00	7.56	Replace	0	0	Not Give	Xnn
Standard	Main		BOLT/SCREW-RR BPR FASCIA BRKT	12	0.52	6.24	10.00	5.62	Replace	0	0	Not Give	Xnn
Standard	Main		NUT-RR BPR FASCIA BRKT	10	0.94	9.40	10.00	8.46	Replace	0	0	Not Give	Xnn
Standard	Main		BOLT/SCREW-RR BPR FASCIA	2	0.52	1.04	10.00	0.94	Replace	0	0	Not Give	Xnn
Standard	Main		NUT-RR BPR FASCIA	2	0.52	1.04	10.00	0.94	Replace	0	0	Not Give	Xnn
Standard	Main		CLIP-RR BPR FASCIA	4	1.24	4.96	10.00	4.46	Replace	0	0	Not Give	Xnn
Standard	Main		NUT-RR BPR FASCIA	2	0.52	1.04	10.00	0.94	Replace	0	0	Not Give	Xnn
Standard	Main		BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0	Check	? Xnn
Standard	Main		LAMP ASM-RR FOG - RH	1	189.08	189.08	10.00	170.17	Replace	0	0	Not Give	Xnn
Standard	Main		LAMP ASM-RR FOG - LH	1	36.30	36.30	10.00	32.67	Replace	0	0	Check	? Xnn
Standard	Main		SENSOR-RR PARK DIST CONT	3	65.00	195.00	10.00	175.50	Replace	0	0	Not Give	Xnn
Total Spare Part Cost								1,871.81	Surveyor Total		250.29		
Lump Sum Discount (%)								0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost								1,871.81	Final Sur Total		250.29		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	2,400.00	250	
Total:			2,400.00	250.00	/

Spray Cost Detail


S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	220	
Total:			428.00	220.00	/

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0 <i>Xm</i>	
2 Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0 <i>Xm</i>	
3 Main	ISOLATED OF (EV) (NET)	150.00	150	
4 Main	TO REPLACE SUNDRY PARTS	100.00	0 <i>Xm</i>	
5 Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
Total:		800.00	300.00	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,871.81	250.29
Total Labour Cost	2,400.00	250.00
Total Spray Painting	428.00	220.00
Other	800.00	300.00
Overall Total	5,499.81	1,020.29
Lump Sum Repair Option	☐	☐
Lump Sum Total	0.00	1,020.29
Surveyor Approved Amount		1,020.29
No of Repair Days*	5	2
Remarks		PART BY PART REPAIR / RESURVEY DAMAGE OLD AND NEW PART PHOTO / AFTER PAINT PHOTO
Surveyor Name		Rasul
Signature		
Survey Date		

Save Clear

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance company

Acknowledged by Repairer

Signature:

Date: