

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ECICS Limited  
10 Eunos Road 8  
#09-04A Singapore Post Centre  
Singapore 408600

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Liu Chun Cheong

Date: 11 Aug 2022

**Preliminary Advice**

Insured Vehicle No	: SKQ8259Z	Accident Date	: 04/02/2022
TP Vehicle No	: SHC3795J	Assignment Date	: 08/02/2022
Make	: HYUNDAI IONIQ EV FL SR	Est. Duration of Repair	: 9
Date of Inspection	: 07/02/2022		
Inspection At	: BIFROST AUTO PTE LTD (HQ) 176 SIN MING DRIVE, #03-09 SINGAPORE 575721		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	24,680.15
Revised Amount	:S\$	12,918.44
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,918.44

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.