



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS FIRST CAPITAL INSURANCE LTD 36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Ref: CS/FCI22001111/Evf3e2	
			Date: 23/02/2022	
			Code: FCI2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
	Insured Veh.	GBF 9452P	Veh. Inspected	SLT 8309K
	Policy No.		Coverage (\$)	0.00
	Claim No.	D22000340MFCV	Excess (\$)	0.00
	Assign From	HARMINDER KAUR	Assign Date	07/02/2022
<b>2. Vehicle Particulars &amp; Condition</b>				
	Make & Model	MAZDA 3	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JM6BN22A8J0187053	Colour	WHITE
	Odometer	76319 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	FAIR		
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre	205/55 R16	MICHELIN	5 mm
	L/H Front Tyre	205/55 R16	MICHELIN	5 mm
	R/H Rear Tyre	205/55 R16	MICHELIN	5 mm
	L/H Rear Tyre	205/55 R16	MICHELIN	5 mm
<b>4. Description of Damages</b>				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
<b>5. General Information</b>				
	Accident Date	31/01/2022	Inspection Date	10/02/2022
	Survey held at	WAH HONG MOTORS & CREDIT PTE LTD 38 TOH GUAN ROAD EAST #01-57 ENTERPRISE HUB SINGAPORE 608581		
<b>5a. Remarks</b>				
	A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
<b>5b. Estimate Days of Repair</b>				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	