

LEE BROTHERS AUTOMOTIVE PTE. LTD.

NO.1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

Not Audited
7/2/22
1/5 \$7000 /
5 days

The Motor Claims Dept.

CHINA TAIPING INSURANCE (S) PTE LTD

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

YP3519X

ESTIMATE

DATE : 08.02.2022
VEHICLE NO : SLK5326C
MAKE/MODEL : TOYOTA VELLFIRE
ACC DATE : 06.02.2022

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
	LIST PRICE		
1	1 TAILGATE <i>body 22</i>	2,120.20	2,120.30 ✓
2	1 TAILGATE GLASS <i>one</i>		1,886.90 X
3	1 TAILGATE LOGO <i>one</i>		68.60 ✓
4	1 TAILGATE EMBLEM 'VELLFIRE' <i>one</i>		110.20 ✓
5	1 TAILGATE LICENCE PLATE GARNISH ASSY <i>one</i>	855.10	1,955.10 ✓
6	2 TAILGATE LAMPS - RH/LH <i>one</i>	485.60	971.20 ✓
7	1 TAILGATE INNER LOCK <i>m/shorted</i>	495.10	954.65 ✓
8	1 TAILGATE INNER TRIM BOARD <i>de/torn</i>	710.60	780.65 ✓
9	1 TAILGATE WITH STRIP <i>weatherstrip</i>		387.66 ✓
10	2 TAILGATE DAMPER - RH/LH <i>11</i>	286.60	573.20 X
11	2 TAILGATE SIDE STOPPER - RH/LH <i>11</i>	48.60	97.20 X
12	2 TAILLAMPS - RH/LH <i>11</i>	581.93	1,163.86 X
13	2 TAILLAMP MOULDINGS - RH/LH <i>11</i>	141.25	282.50 X
14	2 TAILLAMP LOWER GARNISHES - RH/LH <i>ms</i>	241.60	483.20 1pc
15	2 TAILLAMP LOWER GARNISHES RETAINERS - RH/LH <i>11</i>	58.60	117.20 X
16	1 REAR BUMPER <i>dis</i>	937.30	1,656.91 ✓
17	2 REAR BUMPER REFLECTOR - RH/LH <i>ms one</i>	89.95	179.90 1pc
18	1 REAR BUMPER TOW COVER <i>de</i>	42.60	42.60 ✓
19	2 REAR BUMPER SIDE RETAINERS - RH/LH <i>11</i>	89.95	179.90 X
20	2 REAR BUMPER BRACKETS - RH/LH <i>11</i>	103.50	207.00 X
21	1 REAR END PANEL <i>22/buf</i>	960.60	960.60 ✓
22	1 REAR END PANEL GARNISH <i>one</i>	273.60	273.60 ✓
23	1 REAR FLOOR BOARD <i>one</i>	420.60	420.60 X
24	1 REAR FENDER INNER TRIM BOARD - LH <i>one</i>	1,359.20	1,359.20 X
25	1 REAR SMART KEYLESS ANTENNA <i>one</i>	181.90	181.90 X
			17,414.63
LESS 25%			4,353.66
			<u>13,060.97</u>

8264.31
252
6198.23

LEE BROTHERS AUTOMOTIVE PTE. LTD.

PARTICULAR		UNIT PRICE	AMOUNT
QTY		S\$	S\$
1	1 (SET) TAILGATE GLASS SEALANT <i>nee</i>	80.00	80.00 <i>40</i>
2	1 (SET) TAILGATE GLASS FOAM TAPE <i>nee</i>	65.00	65.00 <i>40</i>
3	1 (SET) TAILGATE LICENCE PLATE GARNISH CLIP <i>11</i>	80.00	80.00 <i>X</i>
4	1 (SET) TAILGATE TOP SPOILER CLIP <i>11</i>	80.00	80.00 <i>X</i>
5	1 (SET) REAR BUMPER CLIP <i>nee</i>	45.00	45.00 <i>✓</i>
6	1 REAR BUMPER TOP CHROME PLATE <i>beat</i>	480.00	480.00 <i>250</i>
7	1 (SET) REAR REVERSE SENSOR (4 PCS) <i>shocked</i>	380.00	380.00 <i>250</i>
8	1 REAR REVERSE CAMERA <i>see</i>	450.00	450.00 <i>X</i>
			<u>1,660.00</u>

LABOUR CHARGES :

1	TO REMOVE & REPLACE TAILGATE GLASS	180.00 <i>120</i>
2	TO TRANSFER TAILGATE COMPONENTS PARTS	150.00 <i>80</i>
3	TO CHECK REAR ELECTRICAL WIRING	50.00 <i>30</i>
4	TO VACUUM, WAX & CLEAN INTERIOR TRIMS	<i>11</i> 150.00 <i>X</i>
5	TO REMOVE AND REPLACE REVERSE CAMERA & SENSORS	100.00 <i>50</i>
6	TO TUFF KOTE	120.00 <i>60</i>
7	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,300.00 <i>1000</i>
8	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	1,200.00 <i>600</i>
TOTAL:		<u>3,250.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : **\$ 17,970.97**

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

p- 6198-23
S.N- 625
L- 1940
876323
204
701048