

2 Kaki Bukit Ave 2, #02 19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

ESTIMATE OF REPAIR

2YX102036903

Veh# : SLT1996Y

Accident Date : 24/1/2022

Location : PASIR RIS INDUSTRIAL DRIVE 1

T.P. Chin.
Xiao Tong

Model: Toyota C-HR

10/10/2017 - 9/10/2027

3P: XD6502Z (CHINA
TAIPING)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front windscreen <i>Chipped.</i>	1,888.32	<i>1712</i>	
2	1 pc	Front windscreen moulding <i>NW</i>		146.30	
3	1 pc	Front windscreen sealant <i>NW</i>		80.00	<i>60</i>
4	1 pc	Front windscreen solar film <i>NW</i>		250.00	<i>200</i>
		<i>1712 SN: 40630</i> Sub Total:	1,888.32	476.30	0.00
			25%	0%	0%
		<i>1284</i> After Less %:	1416.24	476.30	0.00
		Labour			
1		To remove & refit front windscreen		180.00	<i>120</i>
		Sub Total:		180.00	
		Total:		2,072.54	

Chan

Chan San Choon
Director
DipEng, AAE MIMI,MSAE(Aust)


Adrian Lj
P/P 10/02/22.

02 Days

total: 1810.30(P/P)



8778 1999
24 hr accident call



- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: