

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/GRB22001121/EGA3Q2**Date:** 08/04/2022REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D21MFL0000447_01
Claimant Vehicle No : SHD2186T **Insured Vehicle No :** SLR4635E
 Date of Loss: 02/02/2022 Nature of Claim: TP Claim No: MFL2022D0000602

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHD2186T**
 Make & Model: TOYOTA PRIUS, 1.8 HYBRID CVT (A) Engine No: 2ZR6283556
 Reg. Date: 11/05/2015 (Man. Year: 2014) Chassis No: ZVW300431282
 Colour: Brown Odometer: 500162 km
 Engine Capacity: 1797 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 185/65 R15 Rear Tyre Size: 185/65 R15
 Front Left Side: Dunlop 4 mm Rear Left Side: Dunlop 4 mm
 Front Right Side: Dunlop 4 mm Rear Right Side: Dunlop 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,439.35	2,735.09	1,704.26	38.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,640.00	1,360.00	280.00	17.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,079.35	4,095.09	1,984.26	32.64
Approved Total (Overridden) (S\$)		3,300.00		
(S\$)	6,079.35	3,300.00	2,779.35	45.72
+ GST 7.00/7.00% (S\$)	425.55	231.00	194.55	45.72
Nett Amount (S\$)	6,504.90	3,531.00	2,973.90	45.72
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$68.90/day) (S\$)		344.50		
+ Doc/Search Fee (S\$)		7.45		
+ Other Costs (S\$)		42.80		
Nett Liability (S\$)		4,175.75		
Global Sum Settlement (S\$)		4,150.00		

INSPECTION

Date of Assignment: 07/02/2022
 Date Inspected: 07/02/2022 Inspected At: Prime Auto Claims Service Pte Ltd (HQ)
 6 Benoi Place
 Singapore 629927
 Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Mar 2022)
Parts: 144	TOYOTA PRIUS 1.8 HYBRID CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SHD2186T)	
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	449.20 FL	*449.20 FL
2	1		*REAR BUMPER LEFT SIDE RETAINER	Broken	122.25 FL	*122.25 FL
3	1		*REAR BUMPER LEFT SIDE BRACKET	Not Necessary	132.10 FL	*- FL
4	1		*REAR END PANEL	Repair	608.10 FL	*- FL
5	1		*REAR END PANEL TOP GARNISH	Broken	561.40 FL	*374.00 FL
6	1		*REAR DECK TRIM COVER	Broken	782.00 FL	*494.00 FL
7	1		*TAIL GATE	Dented	1,450.00 FL	*1,450.00 FL
8	1		*TAIL GATE WEATHERSTRIP	Torn	284.00 FL	*284.00 FL
9	1		*TAIL GATE TOYOTA EMBLEM	Not Necessary	62.00 FL	*- FL
10	1		*TAIL GATE PRIUS EMBLEM	Not Necessary	72.00 FL	*- FL
11	1		*TAIL GATE HYBRID SYNERGY DRIVE EMBLEM	Not Necessary	51.00 FL	*- FL
12	1		*TAIL GATE LOCK STICKER ASSY	Not Necessary	106.40 FL	*- FL
13	1		*TAIL GATE LOCK ASSY	Not Necessary	552.02 FL	*- FL
14	1		*SET REAR BUMPER CLIP	Necessary	20.00 FS	*20.00 FS
15	1		*SET REAR END PANEL TOP GARNISH CLIP	Necessary	15.00 FS	*10.00 FS
16	2		*TUBE REAR GLASS SEALANT	Necessary	80.00 FS	*60.00 FS
17	1		*PRIME TAXI STICKER	Necessary	55.00 FS	*45.00 FS
18	1		*DIAL -A-CAB STICKER	Necessary	45.00 FS	*40.00 FS
19	2		*TAIL GATE LOWER GLASS MOULDING	Necessary	60.00 FS	*60.00 FS
20	1		*SET TAIL GATE GLASS MOULDING (3 PCS)	Necessary	240.00 FS	*120.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,747.47	3,528.45
- List Item Discount on L Items 25.00/25.00% (S\$)	1,308.12	793.36
Total Parts (S\$)	4,439.35	2,735.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TUFF-KOTE REAR PORTION	New	80.00	30.00
2	TO REMOVE & REFIT TAIL GATE GLASS	New	120.00	120.00
3	TO REMOVE & REPLACE TAIL GATE CENTER GLASS	New	60.00	60.00
4	TO TRANSFER TAIL GATE TRIM BOARD ,MECHANISM PARTS & ETC	New	80.00	50.00
5	TO CUT /WELDING REAR END PANEL ,REMOVE TAILGATE ,REAR BUMPER & ETC .TO ADJUST & ALIGN TAILGATE & REAR BUMPER	New	600.00	500.00
6	TO PUTTY ,RESPRAY PAINTING TAIL GATE INLET & OUTER ,REAR BUMPER ,END PANEL,TO POLISH	New	700.00	600.00
			Gross Labour Cost (\$\$)	1,640.00
				1,360.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >