



Prime Auto Claims Service Pte Ltd

GST Reg. No : 201606560M
 6 Benoi Place Singapore 629927
 Tel: 6861 0908 Fax: 6515 2948

Date: 02.02.2022

India International Insurance Pte Ltd
 64 Cecil Street #04/#05
 IOB Building
 Singapore 049711

Attn: Motor Claims Dept

RE: ESTIMATE COST OF REPAIR TO SHD2186T PRIUS HYBRID 1.8 (2015)

Registration Date: 11.05.2015

| | | | |
|------------------|--|----|--------------|
| <u>To supply</u> | | \$ | 449.20 / |
| 1) | 1pc rear bumper / DD | \$ | 122.25 / |
| 2) | 1pc rear bumper left side retainer / BR | \$ | 132.10 |
| 3) | 1pc rear bumper left side bracket X NA | \$ | 608.10 |
| 4) | 1pc rear end panel 2 X R | \$ | 561.40 374 / |
| 5) | 1pc rear end panel top garnish / BR | \$ | 782.00 494 / |
| 6) | 1pc rear deck trim cover / BR | \$ | 1,450.00 / |
| 7) | 1pc tail gate / DD | \$ | 284.00 / |
| 8) | 1pc tail gate weatherstrip / TN | \$ | 62.00 |
| 9) | 1pc tail gate "Toyota" emblem NA X NA | \$ | 72.00 |
| 10) | 1pc tail gate "Prius" emblem NA X NA | \$ | 51.00 |
| 11) | 1pc tail gate "Hybrid Synergy Drive" emblem NA X NA | \$ | 106.40 |
| 12) | 1pc tail gate lock stricker assy X NA | \$ | 552.02 |
| 13) | 1pc tail gate lock assy X NA | \$ | |

3173.45
 -25%
 2380.08

| | | |
|-------------------|----|------------|
| Sub total parts | \$ | 5,232.47 |
| Less:25% discount | \$ | (1,308.12) |
| | \$ | 3,924.35 |

To Supply S.Nett Parts

| | | | |
|-----|---|----------|---------------|
| 1) | 1set rear bumper clip / NA NA | \$ | 20.00 / |
| 2) | 1set rear end panel top garnish clip / NA | \$ | 10 / 15.00 |
| 3) | 2tube rear glass sealant / NA | @\$40.00 | \$ 60 / 80.00 |
| 4) | 1pc "Prime Taxi" sticker / NA | \$ | 45 / 55.00 |
| 5) | 1pc "Dial-A-Cab" sticker / NA | \$ | 40 / 45.00 |
| 6) | 2pcs tail gate lower glass moulding (2pcs) / NA | \$ | 60.00 / |

7) 1 set tail gate glass moulding (3pcs) / M \$ 120 / 240.00

Sub total S.Nett Parts \$ 515.00

355

L/charge

- 1) To tuff-kote rear portion \$ 30 80.00
- 2) To remove & refit tail gate glass \$ 120.00 /
- 3) To remove & replace tail gate center glass \$ 60.00 /
- 4) To transfer tail gate trim board, mechanism parts & etc \$ 50 80.00
- 5) To cut / welding rear end panel, remove tailgate, rear bumper & etc. To adjust & align tailgate & rear bumper \$ 500 600.00
- 6) To putty, respray painting tail gate inlet & outer, rear bumper, end panel, To polish \$ 600 700.00

Sub total L/charges \$ 1,640.00
Estimated Grand Total \$ 6,079.35

1360
= 4095.08
L/S - 3276.06
= 3300

Steve (LKK)
7/2/22, 12.9.2022

M
5 L/S
L/S
by AL by

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: