

2 Kaki Bukit Ave 2, #02-19/22 AutoHub @ Kaki Bukit, Singapore 417921

Email: ryderautoworkshop@gmail.com

Tel: 67418277 Fax: 67468277

JALSY2S2K 67000024

ESTIMATE OF REPAIR

Veh# XE2420Y

TP Chinn
Asher.

Model:

ISUZU CYH52T

Accident Date : 5/2/2022

17/11/2016

Location : SUNGEI KADUT STREET 4

3P: YP6163T (China Taiping)

S/Nos.	Qty	Description	List \$	S/Nett \$	Nett \$
1	1 pc	Front o/s door Distorted	3,527.20	✓	
2	1 pc	Front o/s door inner board <i>replaced</i>	585	✓	
3	12pcs	Front o/s door inner board clips <i>new</i>		68	30.
4	1 pc	Front o/s door inner lock <i>new</i>	440	x	
5	1 pc	Front o/s door weatherstrip <i>new</i>	382.25	x	
6	1 pc	Front n/s door window regulator <i>new</i>	296	✓	
7	1 pc	Front n/s door window motor <i>new</i>		x	x
8	1 pc	Front o/s door sticker <i>new</i>		300.00	150.
9	1 pc	Front o/s door garnish <i>Missing</i>	656.50	✓	
10	8pcs	Front o/s door garnish retainer <i>new</i>	231.20	✓	
11	1 pc	Front o/s door indicator lamp <i>new</i>	332.40	✓	104
12	1 pc	Front o/s door hinges <i>Best</i>	698.20	✓	218
13	1 pc	Front o/s door pillar corner panel garnish <i>new</i>	835.30	✓	
14	1 pc	Front o/s door pillar corner panel weather strip <i>new</i>	90.00	✓	
		Front o/s B Pillar garnish <i>new</i> ✓ 220	6,753.05	368.00	0.00
		Front o/s B Pillar step garnish <i>new</i> x 325	15%	0%	0%
		After Less %:	5,740.09	368.00	0.00
		Labour			
1		To dismantle, straighten & welding.	1,500.00	700	
2		To spray painting.	1,000.00	600	
3		To remove front dash board to facilitate repair door pillar	400.00	100 x.	
5		To remove & replace front o/s door. <i>8 Hrs</i>	200.00	120	
6		To check wiring.	100.00	30	
7		To re-set electrical system.	280.00	x	
8		To re-seal anti-rust.	200.00	80	
		Sub-Total:	3,680.00		
		Total:	9,788.09		
		After Less 20%:	7,830.47		

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Chan San Choon
Director
DipEng, AAM, MIMI, MSAE (Aust)



XE2420Y ESITMATEPg1

Bel: 7458.72
L/S: S.9K
04 Days
6/5 07/02/22