

PROVI AUTOWORKS PTE LTD.

Blk 8 , Kaki Bukit Avenue 4 , #02-24

Premier @ Kaki Bukit Singapore 415875

Email: claims@PROVIAUTO.com

Tel: 6286 6060 Fax : 6286 7060

TR111 Xiao Tong.

Office Use Only

Parts -20%	
SN	
Labour	
TOTAL	
LUMSUM	
ERV	36k

TO:

Vehicle No : SMW 9745 A

Make & Model : HONDA FIT GK3

DATE: 24/1/2022

No.	DESCRIPTION - PARTS	QTY	UNIT PRICE	PRICE	
1	BONNET Distorted	1	\$ 712.00	\$ 712.00	✓
2	BONNET CENTER RUBBER SEAL	1	\$ 68.00	\$ 68.00	+
3	BONNET CENTER GARNISH	1	\$ 169.20	\$ 169.20	+
4	BONNET SIDE GARNISH	2	\$ 124.00	\$ 248.00	+
5	BONNET REBBER SEAL	2	\$ 41.00	\$ 82.00	+
6	BONNET STOPPER Ne n	2	\$ 18.00	\$ 36.00	+
7	BONNET LOCK Ne n	1	\$ 198.20	\$ 198.20	+
8	BONNET HINGES Best	2	\$ 112.00	\$ 224.00	✓
9	BONNET INSULATOR Ne n	1	\$ 198.00	\$ 198.00	+
10	FRONT BUMPER Distorted	1	\$ 625.20	\$ 625.20	525
11	FRONT BUMPER TOW COVER Ne n	1	\$ 16.40	\$ 16.40	+
12	FRONT BUMPER REINFORCEMENT Ne n	1	\$ 395.20	\$ 395.20	+
13	FRONT BUMPER SIDE RETAINER LH Damd	2	\$ 35.20	\$ 70.40	35.2
14	FRONT BUMPER LOWER GRILLE Torn	1	\$ 257.00	\$ 257.00	✓
15	FRONT BUMPER LOWER SIDE GRILLE missing LH	2	\$ 136.00	\$ 272.00	136
16	FRONT BUMPER LOWER SIDE GRILLE CHROME missing LH	2	\$ 98.00	\$ 196.00	98
17	FRONT BUMPER UNDER COVER Ne n	1	\$ 154.00	\$ 154.00	+
18	FRONT GRILLE Build	1	\$ 425.00	\$ 425.00	✓
19	FRONT GRILLE LOGO Ne n	1	\$ 49.00	\$ 49.00	✓
20	FRONT GRILLE LOGO CENTER BRACKET Ne n	1	\$ 45.00	\$ 45.00	+
21	FRONT GRILLE BASE Ne n	1	\$ 458.00	\$ 458.00	+
22	FRONT GRILLE CHROME TOP Ne n	1	\$ 154.00	\$ 154.00	+
23	FRONT GRILLE SIDE CHROME Ne n	2	\$ 114.00	\$ 228.00	+
24	FRONT FOG LAMP 2 Missing Ne n	2	\$ 256.00	\$ 512.00	+
25	FRONT FOG LAMP CHROME RING	2	\$ 56.00	\$ 112.00	+
26	HEADLAMP LH Smashed	2	\$ 897.00	\$ 1,794.00	897
27	HEADLAMP LOWER BRACKET LH Smashed	2	\$ 114.00	\$ 228.00	114
28	HORN Ne n	2	\$ 79.60	\$ 159.20	+
29	WIPER WASHER C/W MOTOR 2 Ne n	1	\$ 498.00	\$ 498.00	+
30	FRONT WINDSCREEN SIDE MOULDING 2 Ne n	2	\$ 212.00	\$ 424.00	+

31	FRONT FENDER LH Distorted	2	\$ 515.00	\$ 1,030.00	S/S
32	FRONT FENDER INNER PANEL LH Distorted Rys	1	\$ 398.00	\$ 398.00	✓
33	FRONT FENDER INNER COWLING torn LH	2	\$ 124.00	\$ 248.00	124
34	FRONT FENDER QUARTER GLASS MOULDING LH	2	\$ 187.00	\$ 374.00	187
35	FRONT EXTENTION PANEL INNER LH Distorted	1	\$ 176.00	\$ 176.00	✓
36	FRONT EXTENTION PANEL OUTER LH Distorted	1	\$ 169.30	\$ 169.30	✓
37	FRONT EXTENTION PANEL BRACKET LH Best	1	\$ 217.00	\$ 217.00	✓
38	FRONT CHASSIS FRAME MEMBER LH Rys	1	\$ 674.30	\$ 674.30	+
39	AIR BAG IMPACT SENSOR Activated	2	\$ 233.00	\$ 466.00	✓
40	FRONT ABSORBER LH Best	1	\$ 410.20	\$ 410.20	2
41	FRONT LOWER ARM LH Best	1	\$ 269.90	\$ 269.90	2
42	FRONT KNUCKLE ARM LH Dmg	1	\$ 330.40	\$ 330.40	2
43	FRONT WHEEL BEARING LH Dmg	1	\$ 236.40	\$ 236.40	2
44	FRONT ORIGINAL WHEEL RIM LH New	1	\$ 985.00	\$ 985.00	+
45	FRONT SUPPORT PANEL Rys	1	\$ 698.60	\$ 698.60	+
46	FRONT SUPPORT PANEL TOP GARNISG New	1	\$ 110.00	\$ 110.00	+
47	AIR CON CONDENSER New	1	\$ 762.80	\$ 762.80	+
48	AIR CON CONDENSER MOUNTING RUBBER New	2	\$ 18.00	\$ 36.00	+
49	AIR CON CONDENSER BRACEKT New	2	\$ 36.00	\$ 72.00	+
50	AIR CON SUCTION PIPE 3 ne	1	\$ 321.00	\$ 321.00	+
51	AIR CON DISCHARGE PIPE 1 ne	1	\$ 325.00	\$ 325.00	+
52	RADIATOR The new	1	\$ 1,382.60	\$ 1,382.60	+
53	RADIATOR AIR ARCH TOP	2	\$ 45.00	\$ 90.00	+
54	RADIATOR AIR ARCH LOWER	2	\$ 45.00	\$ 90.00	+
55	RADIATOR RUBBER MOUNTING	2	\$ 25.00	\$ 50.00	+
56	RADIATOR SPARE TANK	1	\$ 155.60	\$ 155.60	+
57	RADIATOR FAN MOTOR	1	\$ 369.80	\$ 369.80	+
58	RADIATOR FAN COWLING	1	\$ 142.30	\$ 142.30	+
59	RADIATOR FAN BLADE	1	\$ 156.00	\$ 156.00	+
60	AIR DUCT The new	1	\$ 152.00	\$ 152.00	+
61	AIR DUCT HOSE New	1	\$ 98.40	\$ 98.40	+
62	AIR DUCT BASE LOWER New	1	\$ 65.00	\$ 65.00	+
63	BATTERY TRAY Dmg	1	\$ 166.30	\$ 166.30	2
64	BATTERY TOP BRACKET Best	1	\$ 142.10	\$ 142.10	✓
65	FUSE BOX 2t	1	\$ 453.20	\$ 453.20	2
66	ECU New	1	\$ 1,127.40	\$ 1,127.40	+
67	DASH BOARD torn	1	1076.30	\$ -	✓
68	FRONT PASSENGER AIR BAG 3 Activated	1	2192.10	\$ -	✓
69	FRONT DRIVER AIR BAG	1	1887.40	\$ -	✓
70	STEERING COLUMN SENSOR The new	1	544.00	\$ -	+
71	FRONT SEAT BELT Activated	2	788.20	\$ 1576.40	✓
72	FRONT SEAT BELT BUCKER New	2	342.00	\$ 684 -	+

73	CENTER PILLAR INNER LOWER TRIM	3x4	2	\$	311.00	\$	622.00	+
74	CENTER PILLAR INNER TOP TRIM	3x4	2	\$	247.20	\$	494.40	+
75	TAIL GATE	Repair	1	\$	998.00	\$	998.00	+
76	TAIL GATE STOPPER		1	\$	28.50	\$	28.50	+
77	TAIL GATE INNER LOCK		1	\$	289.00	\$	289.00	+
78	TAIL GATE DETECTOR		1	\$	154.00	\$	154.00	+
79	TAIL GATE WEATHER STRIP		1	\$	154.00	\$	154.00	+
80	TAIL GATE INNER TRIM		1	\$	258.00	\$	258.00	+
81	TAIL GATE WINDSCREEN MOULDING		1	\$	110.00	\$	110.00	+
82	TAIL GATE REFLECTOR LH		1	\$	311.00	\$	311.00	+
83	TAIL GATE EMBLEM (FIT)	Rec	1	\$	35.00	\$	35.00	✓
84	REVERSE CAMERA	Not new	1	\$	854.00	\$	854.00	+
85	REAR BUMPER	Distorted	1	\$	659.00	\$	659.00	545
86	REAR BUMPER SIDE RETAINER	LH Dented	2	\$	45.00	\$	90.00	45
87	REAR BUMPER TOW COVER	Missing	1	\$	42.00	\$	42.00	✓
88	REAR BUMPER SIDE GARNISH LH	Missing	1	\$	121.00	\$	121.00	✓
89	REAR BUMPER REFLECTOR LH	Not new	1	\$	144.20	\$	144.20	+
90	REAR BUMPER CENTER GARNISH	Not new	1	\$	124.00	\$	124.00	+
91	TAIL LAMP LH	Cracked	1	\$	489.00	\$	489.00	?
92	TAIL LAMP PANEL LH	Repair Buckled	1	\$	315.00	\$	315.00	✓
93	ALARM BUZZER	Not new	1	\$	121.00	\$	121.00	+
94	REAR FENDER LH	Distorted	1	\$	689.00	\$	689.00	✓
95	REAR FENDER INNER TOP TRIM	Not new	2	\$	255.00	\$	510.00	+ 315
96	REAR FENDER INNER LOWER TRIM	LH Dented	2	\$	412.00	\$	824.00	412
97	REAR FENDER INNER SHIELD LH	Torn	1	\$	89.60	\$	89.60	✓
98	REAR FENDER COWLING LH	Repaired	1	\$	165.00	\$	165.00	+
99	REAR AIE VENT LH	Cracked	1	\$	85.00	\$	85.00	✓
100	REAR QUARTER GLASS WITH MOULDING LH	Not new	1	\$	412.00	\$	412.00	- 85
101	REAR END PANEL	Distorted	1	\$	542.00	\$	542.00	✓
102	REAR END PANEL TOP GARNISH	Dented	1	\$	101.00	\$	101.00	✓
103	REAR FLOOR PANEL	Repair	1	\$	985.00	\$	985.00	+
104	REAR FLOOR TOP BOARD	Not new	1	\$	415.00	\$	415.00	+
105	REAR TOOLS TOOLS BOX COMPARTMENT	Not new	1	\$	421.00	\$	421.00	+
106	REAR EXHAUST TAIL PIPE	3x4	1	\$	898.00	\$	898.00	+
107	REAR EXHAUST MOUNTING	3x4	2	\$	38.00	\$	76.00	+
108	REAR ABSORBER LH	Not new	1	\$	339.50	\$	339.50	+
109	REAR WHEEL BEARING LH	Dented	1	\$	452.90	\$	452.90	✓
110	REAR AXLE BEAM	Not new	1	\$	1,188.70	\$	1,188.70	+
111	REAR ORIGINAL WHEEL RIM LH	Not new	1	\$	985.00	\$	985.00	+
112	REAR DOOR LH	Repair	1	\$	899.20	\$	899.20	+
113	REAR DOOR BLACK STICKER LH	3x4	2	\$	45.00	\$	90.00	+
114	REAR DOOR OUTER MOULDING LH	3x4	1	\$	180.80	\$	180.80	+

115	REAR DOOR INNER LOCK LH <i>3x</i>	1	\$	354.00	\$	354.00	+
116	REAR DOOR LOCK CATCH RH <i>1x</i>	1	\$	46.00	\$	46.00	+
117	REAR DOOR WEATHERSTRIP LH <i>3x</i>	1	\$	154.00	\$	154.00	+
118	REAR DOOR LOWER SEAL LH <i>1x</i>	1	\$	65.00	\$	65.00	+
119	REAR DOOR INNER TRIM <i>1x</i>	1	\$	568.00	\$	568.00	+

18018.70

14414.96

Subtotal : \$ 39,907.20

Less 20% \$ 7,981.44

Parts Total : \$ 31,925.76

NO.	SPECIAL NETT	QTY	UNIT PRICE	PRICE	
1	FRONT NUMBER PLATE <i>2</i>	1	\$ 50.00	\$ 50.00	+
2	BONNET SEALANT <i>1x</i>	1	\$ 60.00	\$ 60.00	+
3	BONNET INSULATOR CLIP <i>1x</i>	1	\$ 60.00	\$ 60.00	+
4	FRONT BUMPER CLIP <i>1x</i>	1	\$ 60.00	\$ 60.00	30
5	FRONT BUMPER LOWER GRILLE CLIP <i>1x</i>	1	\$ 30.00	\$ 30.00	+
6	FRONT GRILLE CLIP <i>1x</i>	1	\$ 50.00	\$ 50.00	20
7	FRONT EXTENTION PANEL INNER SEALANT <i>2x</i>	1	\$ 70.00	\$ 70.00	+
8	FRONT EXTENTION PANEL OUTER SEALANT <i>1x</i>	1	\$ 70.00	\$ 70.00	+
9	FRONT EXTENTION PANEL BRACKET SEALANT	1	\$ 70.00	\$ 70.00	+
10	SUPPORT PANEL SEALANT <i>1x</i>	1	\$ 80.00	\$ 80.00	x
11	RADIATOR COOLANT <i>1x</i>	1	\$ 80.00	\$ 80.00	40
12	BATTERY <i>1x</i>	1	\$ 200.00	\$ 200.00	+
13	CENTER PILLAR INNER LOWER TRIM CLIP <i>3x</i>	1	\$ 40.00	\$ 40.00	+
14	CENTER PILLAR INNER TOP TRIM CLIP	1	\$ 40.00	\$ 40.00	+
15	REAR NUMBER PLATE <i>1x</i>	1	\$ 50.00	\$ 50.00	+
16	REAR BUMPER CLIP <i>1x</i>	1	\$ 60.00	\$ 60.00	30
17	TAIL LAMP CLIP <i>2</i>	1	\$ 50.00	\$ 50.00	+
18	TAIL LAMP PANEL SEALANT	1	\$ 80.00	\$ 80.00	+
19	TAIL GATE SEALANT <i>1x</i>	1	\$ 80.00	\$ 80.00	+
20	TAIL GATE INNER TRIM CLIP	1	\$ 60.00	\$ 60.00	+
21	TAIL GATE WINDSCEEN SEALANT	1	\$ 80.00	\$ 80.00	+
22	TAIL GATE WINDSCEEN INNER SEAL	1	\$ 80.00	\$ 80.00	+
23	REAR FENDER SEALANT <i>1x</i>	1	\$ 80.00	\$ 80.00	40
24	REAR FENDER INNER SHIELD CLIP <i>1x</i>	1	\$ 60.00	\$ 60.00	20
25	REAR FENDER INNER TRIM CLIPS <i>1x</i>	1	\$ 60.00	\$ 60.00	+
26	REAR END PANEL INSULATION SEAL <i>1x</i>	1	\$ 150.00	\$ 150.00	60
27	FLOOR PANEL SEALANT <i>1x</i>	1	\$ 80.00	\$ 80.00	+
28	REVERSE SENSOR <i>1x</i>	1	\$ 220.00	\$ 220.00	200
29	REAR DOOR SEALANT <i>1x</i>	1	\$ 80.00	\$ 80.00	+
30	TYRE <i>Per Punch</i>	2	\$ 400.00	\$ 800.00	180

SPECIAL NETT

\$ 3,030.00

LABOUR (FRONT)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 2,000.00 ²⁸⁰⁰
TO SPRAY PAINT AFFECTED AREA	\$ 1,800.00 ⁸⁰⁰
WIRING CHECK	\$ 100.00 ³⁰
REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS	\$ 150.00 ²⁶⁰
REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	\$ 150.00 ²⁶⁰
TO REMOVE AND INSTALL FRONT UNDERCARRIAGE	\$ 500.00 ²²⁰
REFOCUS HEADLAMP BEAM	\$ 200.00 ¹⁹⁷⁰
TO JACK AND REALIGHT CHASSIS MEMBER	\$ 400.00 ⁺
LABOUR (REAR)	PRICE
PANEL BEATING, REMOVAL AND REPLACING PARTS	\$ 1,800.00 ¹⁰⁰⁰
TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00 ⁹⁰⁰
TUFF COAT	\$ 250.00 ¹²⁰
WIRING CHECK	\$ 100.00 ³⁰
REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR	\$ 600.00 ¹²⁰
REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	\$ 120.00 ⁵⁰
REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 300.00 ⁺
REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 150.00 ⁺
TRANFER TAILGATE MECHANISM	\$ 150.00 ⁺
REVOME AND INSTALL REAR FENDER GLASS	\$ 150.00 ²⁴⁶⁰
REVOME AND INSTALL REAR EXHAUST	\$ 250.00 ⁺
TO REMOVE AND INSTALL REAR UNDERCARRIAGE	\$ 500.00 ¹⁰⁰
TO CHECK FOUR WHEEL ALIGHMENT	\$ 150.00 ⁸⁰
CONDUCT WATER LEAKAGE TEST	\$ 100.00 ⁺
LABOUR TOTAL	
	\$ 11,520.00
Total Parts Cost	\$ 34,955.76
Total Labour Cost	\$ 11,520.00
Total Repair Cost	\$ 46,475.76

APPROVED DETAILS

NO. OF WORKING DAYS
PART BY PART OR LUMP SUM
DATE & TIME OF SURVEY
SURVEYED BY
CONTACT NUMBER
FAX NUMBER

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Adrian Lij
w/s 08/02/22

15 Days

total: 19464.96

L/S: 15.5K