



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. **GBD9660R NISSAN NV200**

Page No. **1**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<b><u>PARTS (LIST ITEMS)</u></b>				
1	Headlamp RH <i>cm</i> ✓		275.00	
1	Center grille assy <i>ca</i> ✓		280.00	
1	Center grille logo badge <i>m</i> ✓		65.00	
1	Front bumper <i>cut</i> ✓		380.00	
2	Headlamp lower panel garnish LH/RH @2*\$195 <i>LH-cut/RH-?ca</i> ✓		390.00	
		Part Items Total:	1390.00	
			10% 139.00	
			1529.00	<u>1529</u>
<b><u>SPECIAL NETT ITEMS</u></b>				
1	Front bumper clips <i>m</i> ✓		<del>35.00</del> 30	
1	Center grille clips <i>cut</i> ✓		<del>30.00</del> 20	
1	Front carplate with holder <i>bt</i> ✓		35.00 ✓	<u>85</u>
		SN Items Total:	100.00	
		Total Parts	1629.00	



# Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. **GBD9660R NISSAN NV200**

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	SURVEYOR'S ADJUSTMENT
<b>LABOUR</b>			
1	To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	<del>600.00</del>	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	<del>400.00</del>	200
3	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	30.00	<u>530</u>
Labour Total :		1030.00	
<b>TOTAL (PARTS &amp; LABOUR):</b>		<b>2659.00</b>	

1529  
 85  
530  
 2144  
 20%  
 1715.20  
1/2 - \$1,700

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Rasul  
 Hp 90010068  
 2 days  
 45  
 08/02/22 P1145  
 EXCESS: 500  
 Repairer  
 Resurvey after repair