



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. **GBD9660R NISSAN NV200**

Page No. **1**

QTY	DESCRIPTION	CONDITION	REPAIRER'S ESTIMATE(S\$)	SURVEYOR'S ADJUSTMENT
<u>PARTS (LIST ITEMS)</u>				
1	Headlamp RH <i>cm</i>		275.00	
1	Center grille assy <i>cm</i>		280.00	
1	Center grille logo badge <i>cm</i>		65.00	
1	Front bumper <i>cut</i>		380.00	
2	Headlamp lower panel garnish LH/RH @2*\$195 <i>LH-cut/RH-?</i>		390.00	
Part Items Total:			1390.00	
			10% 139.00	
			1529.00	
<u>SPECIAL NETT ITEMS</u>				
1	Front bumper clips <i>cm</i>		35.00	<i>30</i>
1	Center grille clips <i>cm</i>		30.00	<i>20</i>
1	Front carplate with holder <i>cm</i>		35.00	
SN Items Total:			100.00	
Total Parts			1629.00	



Wah Hong Motors & Credit Pte Ltd

Enterprise Hub 38 Toh Guan Road East #01-57 S(608581)

Email: motor@wahhong.sg

(199806235M)

Vehicle No. GBD9660R NISSAN NV200

Page No. 2

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (\$\$)	SURVEYOR'S ADJUSTMENT
1	LABOUR To remove the affected parts & fittings to commence repairs; panel beat & reshape the affected areas and replace the damaged parts and components	600.00	300
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	400.00	200
3	To remove and repair/refit wiring system at accident damaged area and check for all electrical proper function	30.00	
Labour Total :		1030.00	
TOTAL (PARTS & LABOUR):		2659.00	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

R45ul
Hp 90010068
2 days
4/3
08/02/22 P1145
EXCESS: 500
REPAIR
Resurvey after repair